

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19020594/AGS3Q2

Date: 23/09/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00007364-01

Claimant
Vehicle No : SKD4233S **Insured Vehicle No :** SKK493Y

Date of Loss: 19/11/2019 Nature of Claim: TP Claim No: 1201900036053

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD4233S		
Make & Model:	JAGUAR XJ, 3.0 3.0 DIESEL SWB PL TSS EU5 (A)	Engine No:	0631646306DT
Reg. Date:	23/10/2012 (Man. Year: 2012)	Chassis No:	SAJAC2221CNV36373
Colour:	White	Odometer:	164402 km
Engine Capacity:	2993 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	245/45 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,181.50	4,741.20	8,440.30	64.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	880.00	1,520.00	63.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,581.50	5,621.20	9,960.30	63.92
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	15,581.50	4,500.00	11,081.50	71.12
+ Loss of Use (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,107.45		
Global Sum Settlement (S\$)		5,100.00		

INSPECTION

Date of Assignment: 20/11/2019

Date Inspected: 20/11/2019 Inspected At:

Hua Meng Spray Painting Workshop (HQ)

No 1 Kaki Bukit Avenue 6, #01-61

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2020)
Parts:	143	JAGUAR XJ 3.0 3.0 DIESEL SWB PL TSS EU5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD4233S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Distorted	3,476.00 F	*2,850.00 FL
2	1		*FRONT RH DOOR GLASS OUTER MOULDING	Not Necessary	77.00 F	*- FL
3	1		*FRONT RH DOOR TOP HINGE	Not Necessary	121.00 F	*- FL
4	1		*FRONT RH DOOR LOWER HINGE	Not Necessary	145.20 F	*- FL
5	1		*FRONT RH DOOR STOPPER	Not Necessary	146.30 F	*- FL
6	1		*FRONT RH DOOR INNER BOARD	Cracked	1,120.00 F	*1,120.00 FL
7	1		*FRONT RH DOOR INNER LOCK	Not Necessary	3,960.00 F	*- FL
8	1		*FRONT RH DOOR LOWER RUBBER	Not Necessary	517.00 F	*- FL
9	1		*FRONT RH DOOR WEATHERSTRIP	Necessary	264.00 F	*264.00 FL
10	1		*FRONT RH DOOR TOP RUBBER	Not Necessary	209.00 F	*- FL
11	1		*FRONT RH DOOR INNER SIDE GARNISH	Not Necessary	202.40 F	*- FL
12	1		*FRONT RH DOOR POWER WINDOW MOTOR	Damaged	319.00 F	*319.00 FL
13	1		*FRONT RH DOOR WINDOW REGULATOR	Not Necessary	825.00 F	*- FL
14	1		*FRONT RH DOOR GLASS CHANNEL	Not Necessary	464.20 F	*- FL
15	1		*RH ROCKER PANEL GARNISH	Cracked	715.00 F	*715.00 FL
16	1		*RH DOOR INNER GARNISH	Not Necessary	206.80 F	*- FL
17	2		*RH DOOR INNER LOWER SIDE GARNISH	Not Necessary	413.60 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	13,181.50	5,268.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	526.80
Total Parts (\$\$)	13,181.50	4,741.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RESET	New	100.00	0.00
2	REMOVE & REINSTALL DOOR GLASS	New	200.00	80.00
3	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,100.00	400.00
4	RESPRAY PAINTING	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,400.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >