

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

SAJAC221CNU36373

NG SIN WEI

BLK 522 ANG MO KIO AVE 5

#07-4202

S 560522

TP FWD

Cecilia.

Date

:03.12.2019

Vehicle No

:SKD 4233 S

Make/Model

:JAGUAR XJ 3.0L

Accident date

:19.11.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front RH door Distorted	1	\$ 3476 ✓ 2850
2	Front RH door glass outer moulding New	1	\$ 77 x
3	Front RH door top hinge	1	\$ 121 ✓
4	Front RH door lower hinge	1	\$ 145.2 ✓
5	Front RH door stopper	1	\$ 146.3 ✓
6	Front RH door inner board	1	\$ 1120 ✓
7	Front RH door inner lock New	1	\$ 3960 x
8	Front RH door lower rubber New	1	\$ 517 ✓
9	Front RH door weather strip New	1	\$ 264 ✓
10	Front RH door top rubber New	1	\$ 209 x
11	Front RH door inner side garnish New	1	\$ 202.4 ✓
12	Front RH door power window motor	1	\$ 319 ✓
13	Front RH door window regulator New	1	\$ 825 x
14	Front RH door glass channel New	1	\$ 464.2 x
15	RH rocker panel garnish	1	\$ 715 ✓
16	RH door inner garnish New	1	\$ 206.8 x
17	RH door inner lower side garnish @ \$206.80 New	2	\$ 413.6 ✓
Total			\$ 12210

Labour Cost

- 1 To reset
- 2 Remove & reinstall door glass
- 3 Remove ,replace & repair consistent to the accident
- 4 Respray painting

	\$ 100 ✓
880	\$ 200 80
	\$ 1100 400
	\$ 1000 400
Total	\$ 2400

Grand Total \$ 14610

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 5621.20
c/s: 4.5K
0500p.

4.5K
0500p.