

ASS. REC. BY:

REF: es/fci/19020611/71ydbm Special Instruction:

Senior:

Taufik

ASSIGNMENT (Office)

CWS

From (Person): Mermerchia

of

FCIDate/Time: 2.53pm 20/11/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBB 8427R

Insured:

SHC 72122

at Workshop m/s

Gthoz

Tel:

96240656

of

30 Bukit Butek Crescent

Policy No:

Claim No:

D19007343 MP&H

Sum Insured:

Excess:

Make of Veh:

D.O.A

17/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4.33pm @ 20/11/19

Person Contacted:

ShahVehicle IN OUT

Date/Time

Action/Instruction

JohnnyGBB 8427R - XSHC 72122 - NS/INC/5016-797/H/19/11D.O.A: 2/10/201525/11/19Email preli revised to FCI

ASS. REC. BY:

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$4K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Shm

Veh No:

GBB8427R Yr Regn: 2010 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan NV200

c.c 1461

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

466971

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

175/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/12/19 Email to Shm limit \$6500 (Repair limit) + \$46500, 8 days email to Shm.

(Red \$4152-72, 38%)

MV = \$9000/-
LTA = \$1896/-
Nett = \$7104/-

RECEIVED 5 DEC 2019

4/12/2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

4/12/19 Typist

Report Format:

Lump Sum \$6500/-

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Week end (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

170

50

50 + 50

74

394



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19007343MFSH

Our ref: CS/FCI19020611/T1yd3

Date: 25/11/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. GBB 8427R


We thank you for your instruction on 20/11/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/11/2019 at the premises of M/s ETHOZ GROUP LTD and have the following to report:-

Workshop Estimate Amount	: S\$10,652.72
Revised Estimate Amount	: S\$6,853.83
"Check" Items Amount	: S\$2,389.86
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front and rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAL, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	19-11-2019	Our Ref No. D19007343MFSH
Accident Date	17-11-2019	Claim Type. Third Party
Insured Vehicle	SHC7212Z	Third Party Vehicle. GBB8427R
Survey Location	30 BUKIT BATOK CRESCENT	
Contact Person.	SELAMATSHAH ZAINAL	
Contact No.	66547519/ 96248656	Fax No. 66547542
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ETHOZ GROUP LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 25 November 2019 10:12 AM
To: 'CWS Motor Claims'
Cc: 'Merina Chia'; SUR
Subject: RE: SURVEY ASSESSMENT - D19007343MFSH/1-GBB 8427R
Attachments: GBB 8427R PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle GBB 8427R
Date of survey: 20/11/2019
Number of days (estimated) : 8 days

Best Regards,

Veron Chen | Case Handler **on behalf of Yvonne**

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 20 November 2019 4:37 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19007343MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 20 November 2019 2:52 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007343MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	531H
Vehicle Details	
Vehicle No.:	GBB8427R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	06 Dec 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5L MT ABS AIRBAG 2WD 6DR
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	K9KF276D078820
Chassis No.:	JN1YBAM20U0002944
Maximum Power Output:	-
Open Market Value:	\$21,922.00
Original Registration Date:	14 Jun 2010
First Registration Date:	14 Jun 2010
Transfer Count:	0
Actual ARF Paid:	\$1,097.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jun 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$36,511.00
COE Rebate Amount:	\$1,896.00
Total Rebate Amount:	\$1,896.00

The information contained herein is correct as at 06 Dec 2019

OK

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 20/11/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTHCVE000181

Accident Date : 17/11/2019

Vehicle No : GBB-8427-R

Make & Model : NISSAN NV200 1.5 DIESEL G (M) VAN

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

- 1 FRONT BUMPER
- 2 FRONT BUMPER RETAINER
- 1 FRONT BUMPER REINFORCEMENT
- 1 FRONT BUMPER DAMPER
- 10 FRONT BUMPER CLIPS
- 1 FRONT GRILLE
- 1 FRONT GRILLE LOGO
- 10 FRONT GRILLE CLIPS
- 2 HEADLAMP RH/LH

563.50 de
76.80 LH-RH di 38.40
x 589.20 Kun
148.20 av
50.00 ni
344.60 ? con
87.50 m. s
50.00 ni
1,101.80 LH-? RH con 550 90

Date : 20/11/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTHCVE000181

Accident Date : 17/11/2019

Vehicle No : GBB-8427-R

Make & Model : NISSAN NV200 1.5 DIESEL G (M) VAN

ESTIMATED REPAIR COST DETAILS

Excess

: 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
2	HEADLAMP LOWER PANEL RH/LH	/ 929.60	LH- ^{del} R4- ^{del} ✓ 464.80
1	BONNET	/ 858.60	bt ✓
1	BONNET LOCK	nnx 54.60	? ✓
10	BONNET INSULATOR CLIPS	/ 50.00	nei ✓
1	SUPPORT PANEL	X 598.40	Ry ✓
1	AIRCON CONDENSER	/ 376.20	? bt ✓
1	RADIATOR	X 424.50	? Xnn ✓
2	FRONT FENDER RH/LH		RESTORE
1	REAR BUMPER	/ 650.40	del ✓
2	REAR BUMPER RETAINER	/ 70.40	LH-nei, R4x ⁿⁿ 35.20

Date : 20/11/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTHCVE000181

Accident Date : 17/11/2019

Vehicle No : GBB-8427-R

Make & Model : NISSAN NV200 1.5 DIESEL G (M) VAN

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
2	REAR BUMPER REFLECTOR	✓95.80	Xin
10	REAR BUMPER CLIPS	✓50.00	he
1	END PANEL		
1	REAR DOOR LH	1,545.40	bt
1	REAR DOOR WEATHERSTRIP LH	✓112.60	?
1	REAR DOOR LOGO	✓77.40	he
1	REAR EMBLEM - NV200	✓91.60	he
1	REAR DOOR LOWER HINGE LH	X79.30	Ry
1	REAR EMBLEM - DCI	✓63.20	he
1	REAR DOOR RH		

RESTORE

RESTORE

Date : 20/11/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTHCVE000181

Accident Date : 17/11/2019

Vehicle No : GBB-8427-R

Make & Model : NISSAN NV200 1.5 DIESEL G (M) VAN

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	9139.60	
	Discount 30% On Parts	(2741.88)	
	<u>Special Nett Item</u>		
1	FRONT NUMBER PLATE	35.00	66
1	REVERSE SENSOR	220.00	200nm
1	COOLANT	30.00	?
1	REAR GLASS SEALANT	50.00	nei
1	70KM/HR - STICKER	15.00	nei
1	5 PAX - STICKER	15.00	nei
1	FRONT AND REAR ADVERTISEMENT PANELS STICKERS	400.00	300

Date : 20/11/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTHCVE000181

Accident Date : 17/11/2019

Vehicle No : GBB-8427-R

Make & Model : NISSAN NV200 1.5 DIESEL G (M) VAN

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	765.00	
<u>Labour & Misc</u>			
	LABOUR TO FACILITATE REPAIR	✓ 1,500.00	1200-
	TO RESPRAY AFFECTED AREAS	✓ 1,500.00	1200
	TO REMOVE AND TRANSFER REAR DOOR COMPONENTS	✓ 150.00	60
	TO REMOVE AND REFIT REAR DOOR GLASS LH	✓ 120.00	860
	TO TOP UP AIRCON GAS	× 120.00	100 X mm
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	✓ 50.00	30
	RUST PROOFING	✓ 50.00	30

Date : 20/11/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTHCVE000181

Accident Date : 17/11/2019

Vehicle No : GBB-8427-R

Make & Model : NISSAN NV200 1.5 DIESEL G (M) VAN

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	3490.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10,652.72

Remarks:

SUB TOTAL

GST 7.0 % 745.69

TOTAL 11,398.41

Surveyor's name: Taufiq 97495744

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 20/11/19 @ 5pm

Bohays
Lumpsum
Resurvey after repair
To check repair unit
survelldata.com

Lump Sum Limit
@ \$6500
8 days

ETHOZ

Date : 30/11/2019
To : MS FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTHCVE000181 Accident Date : 17/11/2019

Vehicle No : GBB-8427-R Make & Model : NISSAN NV200 1.5 DIESEL G (M) VAN

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
<u>List Item</u>			
1	FRONT BUMPER	563.50	563.50
2	FRONT BUMPER RETAINER	76.80	38.40
1	FRONT BUMPER REINFORCEMENT	589.20	0.00
1	FRONT BUMPER DAMPER	148.20	148.20
10	FRONT BUMPER CLIPS	50.00	50.00
1	FRONT GRILLE	344.60	344.60
1	FRONT GRILLE LOGO	87.50	87.50
10	FRONT GRILLE CLIPS	50.00	50.00
2	HEADLAMP RH/LH	1101.80	1101.80
2	HEADLAMP LOWER PANEL RH/LH	929.60	929.60
1	BONNET	858.60	858.60
1	BONNET LOCK	54.60	0.00
10	BONNET INSULATOR CLIPS	50.00	50.00
1	SUPPORT PANEL RESTORE	598.40	0.00

PAGE : 1



Date : 30/11/2019
To : MS FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D19MTHCVE000181 Accident Date : 17/11/2019
Vehicle No : GBB-8427-R Make & Model : NISSAN NV200 1.5 DIESEL G (M) VAN

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	AIRCON CONDENSER	376.20	376.20
1	RADIATOR	424.50	0.00
2	FRONT FENDER RH/LH RESTORE	0.00	0.00
1	REAR BUMPER	650.40	650.40
2	REAR BUMPER RETAINER	70.40	35.20
2	REAR BUMPER REFLECTOR	95.80	0.00
10	REAR BUMPER CLIPS	50.00	50.00
1	END PANEL RESTORE	0.00	0.00
1	REAR DOOR LH	1545.40	1545.40
1	REAR DOOR WEATHERSTRIP LH	112.60	0.00
1	REAR DOOR LOGO	77.40	77.40
1	REAR EMBLEM - NV200	91.60	91.60
1	REAR DOOR LOWER HINGE LH	79.30	0.00
1	REAR EMBLEM - DCI	63.20	63.20
1	REAR DOOR RH RESTORE	0.00	0.00

PAGE : 2



Date : 30/11/2019
To : MS FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D19MTHCVE000181 Accident Date : 17/11/2019
Vehicle No : GBB-8427-R Make & Model : NISSAN NV200 1.5 DIESEL G (M) VAN

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	8541.20	7111.60
	Discount 30% On Parts	(0.00)	(2133.48)
		(2562.36)	
<u>Special Nett Item</u>			
1	FRONT NUMBER PLATE	35.00	35.00
1	REVERSE SENSOR	220.00	200.00
1	COOLANT	30.00	0.00
1	REAR GLASS SEALANT	50.00	50.00
1	70KM/HR - STICKER	15.00	15.00
1	5 PAX - STICKER	15.00	15.00
1	FRONT AND REAR ADVERTISEMENT PANELS STICKERS	400.00	300.00

PAGE : 3



Date : 30/11/2019
To : MS FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTHCVE000181 Accident Date : 17/11/2019

Vehicle No : GBB-8427-R Make & Model : NISSAN NV200 1.5 DIESEL G (M) VAN

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	765.00	615.00
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	1500.00	1200.00
	TO RESPRAY AFFECTED AREAS	1500.00	1200.00
	TO REMOVE AND TRANSFER REAR DOOR COMPONENTS	150.00	60.00
	TO REMOVE AND REFIT REAR DOOR GLASS LH	120.00	60.00
	TO TOP UP AIRCON GAS	120.00	0.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	30.00
	RUST PROOFING	50.00	30.00

PAGE : 4



Date : 30/11/2019
To : MS FIRST CAPITAL INSURANCE LIMITED

Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D19MTHCVE000181 Accident Date : 17/11/2019
Vehicle No : GBB-8427-R Make & Model : NISSAN NV200 1.5 DIESEL G (M) VAN

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	3490.00	2580.00
	Sub Total	10,652.72	8,173.12
	GST 7.0 %	745.69	572.12
	Total	11,398.	8,745.24

Surveyor Name : TAUFIK - LKK

Date & Time : 20/11/2019 5:00:00 PM

Selamatshahh

PAGE : 5

CLAIM DEPARTMENT

DID : 66547519

FAX :



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19020611/T1yd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-12-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7212Z	Veh. Inspected	GBB 8427R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19007343MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	20/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JN1YBAM20U0002944	Colour	WHITE	
Odometer	466971	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	YOKOHAMA	6 mm	
L/H Front Tyre	175/70 R14	YOKOHAMA	6 mm	
R/H Rear Tyre	175/70 R14	YOKOHAMA	6 mm	
L/H Rear Tyre	175/70 R14	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/11/2019	Inspection Date	20/11/2019	
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 8427R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	563.50	563.50
2	FRONT BUMPER RETAINER	O/S DEFORMED / N/S NOT NECESSARY	76.80	38.40
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	589.20	-
1	FRONT BUMPER DAMPER	CRACKED	148.20	148.20
10	FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT GRILLE	CRACKED	344.60	344.60
1	FRONT GRILLE LOGO	MISSING	87.50	87.50
10	FRONT GRILLE CLIPS	NECESSARY	50.00	50.00
2	HEADLAMP RH/LH	CRACKED	1,101.80	1,101.80
2	HEADLAMP LOWER PANEL RH/LH	DEFORMED	929.60	929.60
1	BONNET	BENT	858.60	858.60
1	BONNET LOCK	NOT NECESSARY	54.60	-
10	BONNET INSULATOR CLIPS	NECESSARY	50.00	50.00
1	SUPPORT PANEL	TO REPAIR SEE LABOUR	598.40	-
1	AIRCON CONDENSER	BENT	376.20	376.20
1	RADIATOR	NOT NECESSARY	424.50	-
2	FRONT FENDER RH/LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER	DEFORMED	650.40	650.40
2	REAR BUMPER RETAINER	N/S NECESSARY / O/S NOT NECESSARY	70.40	35.20
2	REAR BUMPER REFLECTOR	NOT NECESSARY	95.80	-
10	REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR DOOR LH	BENT	1,545.40	1,545.40
1	REAR DOOR WEATHERSTRIP LH	NOT NECESSARY	112.60	-
1	REAR DOOR LOGO	NECESSARY	77.40	77.40
1	REAR EMBLEM-NV200	NECESSARY	91.60	91.60

Report Ref No. CS/FCI19020611/T1yd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DOOR LOWER HINGE LH	TO REPAIR SEE LABOUR	79.30	-
1	REAR EMBLEM-DCI	NECESSARY	63.20	63.20
1	REAR DOOR RH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 30% DISCOUNT		-2,741.88	-2,133.48
			6,397.72	4,978.12
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
1	REVERSE SENSOR (SN)	NOT WORKING	220.00	200.00
1	COOLANT (SN)	NOT NECESSARY	30.00	-
1	REAR GLASS SEALANT (SN)	NECESSARY	50.00	50.00
1	70KM/HR-STICKER (SN)	NECESSARY	15.00	15.00
1	5 PAX-STICKER (SN)	NECESSARY	15.00	15.00
			365.00	315.00
	LABOUR			
	FRONT AND REAR ADVERTISEMENT PANELS STICKERS.		400.00	300.00
	LABOUR TO FACILITATE REPAIR.INCLUSIVE OF THE REPAIR OF SUPPORT PANEL,FRONT FENDER RH/LH,END PANEL,REAR DOOR LOWER HINGE LH AND REAR DOOR RH.		1,500.00	1,200.00
	TO RESPRAY AFFECTED AREAS.		1,500.00	1,200.00
	TO REMOVE AND TRANSFER REAR DOOR COMPONENTS.		150.00	60.00
	TO REMOVE AND REFIT REAR DOOR GLASS LH.		120.00	60.00
	TO TOP UP AIRCON GAS.	NOT NECESSARY	120.00	-
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		50.00	30.00
	RUST PROOFING.		50.00	30.00
	-		-	-
	-		-	-
	-		-	-
			3,890.00	2,880.00
GRAND TOTAL			10,652.72	8,173.12



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,500.00
---	--	--	----------

Report Ref No. CS/FCI19020611/T1yd3n2

MARKET VALUE: \$9,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$1,896.00=NETT VALUE: \$7,104.00

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.