

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 19552**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/19552/2019/NS  
**Date** : 19-Nov-19

**Vehicle NOT IN workshop. Kindly arrange for survey.**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Lam Jer Wei  
**Address** : 216 Jalan Eunos  
#05-88  
Singapore 419552  
**Telephone** : (HP)+65 83991299  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 1700063044-02  
**Vehicle No** : **SLU 128 M**  
**Model Code** : Audi Q7 2.0 TFSI QU  
**Model / Year** : 9/10/2017  
**Engine No** : CYR 047030  
**Chassis No** : WAUZZZ4M5JD004163  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 17-Nov-19  
**Place of Accident** : Paya Lebar Before Geylang

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SLU 128 M

| S/n                         | Nature of Jobs                                                                                                                             | Estimated Charges            | Surveyor's Recommendations                           |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|------------------------------------------------------|
| 1                           | To remove and transfer rhs front door and rhs rear door multi-lock system and power window devices. Check function and renew in necessary. | S/N \$ <del>560.00</del> 280 |                                                      |
| 2                           | To dismantle rhs front door panel trim. To remove and transfer rhs wing mirror assy.                                                       | S/N \$ 300.00 X              |                                                      |
| 3                           | To dismantle and renew rhs front door and rhs rear door. Re-organise crash management components. Reinstall all parts removed.             | \$ <del>2,700.00</del> 600   |                                                      |
| 4                           | To respray rhs front door, rhs rear door, door covers and rhs door wheel arch trim.                                                        | \$ <del>3,800.00</del> 1100  | 600 : Door<br>400 Door Cover x 02<br>Wheel Arc : 100 |
| 5                           | To renew rhs rear rim and carry out wheel alignment.                                                                                       | S/N \$ 280.00 ✓              | 1700                                                 |
| 6                           | To carry out diagnostic check.                                                                                                             | S/N \$ 192.00 ✓              |                                                      |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                            | <b>: \$ 7,832.00</b>         |                                                      |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLU 128 M

| S/N                         | Parts Description          | Damaged Parts & Prices |         |
|-----------------------------|----------------------------|------------------------|---------|
|                             |                            | S/Nett                 | Remarks |
| 1                           | FRONT DOOR - RH            | \$ 3,570.00            | +       |
| 2                           | FRONT DOOR OUTER SEAL      | NEC \$ 229.00          | +       |
| 3                           | BONDING AGENT              | NEC \$ 45.00           | +       |
| 4                           | CLEANING SOLUTION          | NEC \$ 65.00           | +       |
| 5                           | FRONT DOOR CATCH           | \$ 117.00              | +       |
| 6                           | TYRE PRESSURE DATA PLATE   | \$ 38.00               | +       |
| 7                           | FRONT DOOR COVER - RH      | \$ 632.00              | ✓       |
| 8                           | REAR DOOR - RH             | \$ 3,570.00            | ✓       |
| 9                           | REAR DOOR OUTER SEAL       | NEC \$ 229.00          | ✓       |
| 10                          | BONDING AGENT              | NEC \$ 45.00           | ?       |
| 11                          | CLEANING SOLUTION          | NEC \$ 65.00           | ?       |
| 12                          | REAR DOOR ATTACHMENT PARTS | \$ 89.00               | +       |
| 13                          | REAR DOOR CATCH            | \$ 96.00               | +       |
| 14                          | SILL PANEL SEAL - RH       | \$ 234.00              | +       |
| 15                          | REAR DOOR COVER - RH       | \$ 545.00              | ✓       |
| 16                          | REAR WHEEL COVER - RH      | \$ 179.00              | ✓       |
| 17                          | REAR ALUMINIUM RIM - RH    | \$ 1,116.00            | +       |
| 18                          | ALUMINIUM RIM RUBBER VALVE | 4 \$ 13.00             | +       |
| 19                          | SUNDRIES                   | \$ 300.00              | ?       |
| <b>TOTAL SPARE PARTS</b>    |                            | <b>\$ 11,177.00</b>    |         |
| <b>TOTAL LABOUR CHARGES</b> |                            | <b>\$ 7,832.00</b>     |         |
| <b>GRAND TOTAL</b>          |                            | <b>\$ 19,009.00</b>    |         |

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : *Adrian Lj*  
Surveyed Date : *20/11/19.*  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : *Not Authorised, 03 Days.*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant