



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/11/2019

User ID : GohKK2

Section A - Accident Details	
Registration Number	SMB140P
Case Reference Number	BUS/11/19/1041
Registration Date	14/3/2011
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC530
Name of Driver	KUMARAN S/O CHEMPATAYAN
Type of Accident	Rear To Head
Accident Date and Time	17/11/2019 1:32 PM
Accident Reported Date and Time	17/11/2019 2:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SMB140P-FRONT PORTION SLR5395R (TP) INSURED WITH INDIA INT'L
Prepared Date and Time	19/11/2019 5:22 PM
Chassis Number	WEB62808323120695
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$0.00	\$0.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$6,119.59	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$6,119.59	\$0.00
Lump Sum Total	\$6,100.00	\$0.00
Number of Repair Days	5.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	19/11/2019 6:00 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/11/2019

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$2,120.00						
Total Labour			\$2,120.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$1,048.00						
Total Spray Painting & Panel Beating			\$1,048.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	
6010191	VM	9417500184	FASTENER:FRT BUMPER,FOR MB CITARO BUS	2.00	\$19.35	10.00	\$34.83	Replace	
6009701	VE		LAMP,BLINKER:FRONT, RIGHT,FOR MB OC500 LE	1.00	\$155.30	10.00	\$139.77	Replace	
6009903	BODY RH	6288800272	BUMPER:FRONT,RH,FO R MB CITARO O530	1.00	\$1,754.79	10.00	\$1,579.31	Replace	
6009901	Body	6283850401	BUMPER:FRONT,CENTR E,FOR MB CITARO O530	1.00	\$1,663.80	10.00	\$1,497.42	Replace	
6009904	Body	6288850526	FLAP:FRONT,CENTRE,F OR MB CITARO O530	1.00	\$1,513.05	10.00	\$1,361.74	Replace	
6009508	VE		HEADLAMP FOR MERCEDES OC500 LE, RIGHT	1.00	\$1,276.50	10.00	\$1,148.85	Replace	
6012457			WIPER ARM COVER	2.00	\$19.50	10.00	\$35.10	Replace	
6009509	VE		HEADLAMP FOR MERCEDES OC500 LE, LEFT	1.00	\$1,276.50	10.00	\$1,148.85	Replace	
6010066	VM	6287510014	BRACKET:(15),FOR MB CITARO BUS	2.00	\$4.56	10.00	\$8.21	Replace	
6010067	Body	3577500150	LOCK:(20),FOR MB CITARO BUS	2.00	\$43.80	10.00	\$78.84	Replace	
6010069	VM	6288802114	BRACKET:(40),FOR MB CITARO BUS	1.00	\$439.74	10.00	\$395.77	Replace	
6010070	VM	6287510314	BRACKET:(120),FOR MB CITARO BUS	2.00	\$33.00	10.00	\$59.40	Replace	
6010071	Body	6287510051	HINGE:(35),FOR MB CITARO BUS	2.00	\$48.00	10.00	\$86.40	Replace	
6009902	BODY LH	6288800172	BUMPER:FRONT,LH,FO R MB CITARO O530	1.00	\$1,767.78	100.00	\$0.00	Repair	
Total					\$10,090.67		\$7,649.49		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									