

Sherwin Beh (LKK Auto)

**From:** Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>  
**Sent:** Tuesday, 22 October, 2019 11:22 AM  
**To:** Sherwin Beh (LKK Auto); Naz (LKKAuto)  
**Cc:** Bryan Ang (LKKAuto); SPF-TP FAIT; Intan Wulandari (SPF); David DY YAP (SPF); Shahrul Nizam SAMARRI (SPF)  
**Subject:** Mechanical Inspection Report Request

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 9 vehicles below: [The ones marked in RED are deemed to be URGENT hence please EXPEDITE ON THESE REQUESTS]

- a) Case IAFP-IB-20191003 - Mechanical Inspection of Tipper Truck, XD8219D (TP/IP/57869/2019)
- b) Case IAFP-IB-20191003 - Mechanical Inspection of Motorcycle: FX7596D (TP/IP/57869/2019)

On 13 September 2019 (Friday) at about 3.31 p.m., the Involved Party's tipper truck broke down while travelling along Ayer Rajah Expressway towards the direction of Tuas. After the Involved Party placed a breakdown signage at the rear of his tipper truck, about 1.5 motor car's length away, the Deceased's motorcycle travelled towards the Involved Party, collided into the breakdown signage and subsequently into the rear centre portion of the Involved Party's tipper truck. Before the Deceased collided into the tipper truck, the Involved Party managed to move aside to avoid a near collision. After witnessing the accident, the Involved Party called for the ambulance. The Involved Party approached the Deceased however he was not responding. As a result of the accident, the Deceased sustained head injuries and was conveyed to the Singapore General Hospital by ambulance. The Deceased, who was reported to be unconscious, suffered a traumatic arrest. He succumbed to his injuries and was pronounced dead in hospital on the same day at 4.45 p.m., by Dr Tess Toe.

Vehicles to be inspected: XD8219D - Driver (Involved Party)  
FX7596D - Rider (Deceased)

IO In-Charge: SIO Kamaliah

- c) Case IAFP-IB-20191003 - Mechanical Inspection of Motor Van, GZ557R (TP/IP/44533/2019) *(Reported)*

On 17 July 2019 at about 04.50 pm, Police incident was created regarding an accident along Marymount Rd by Marymount Lane. The motor van, GZ557R, was travelling on the rightmost lane of 5-lanes along Marymount Rd towards Thomson Rd. Driver informed that upon approaching the said junction of Marymount Lane, traffic light was showing red. At the time, there was an unknown stationary motor car ahead of him. When he applied brakes, the vehicle continued moving forward and as such, in order for him to avoid colliding onto the rear of the said unknown motor car – he swerved to the right, mounted onto the centre divider and subsequently collided onto a traffic light pole. Driver did not sustain any injury however claimed that the motor van brakes are faulty.

Vehicle to be inspected: GZ557R - Driver (Potential Defendant)

IO In-Charge: IO Intan

- d) Case IAFP-IB-20191003 - Mechanical Inspection of Motorcycle, FBK7189L (TP/IP/55759/2019)