



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19020642/T1td3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 27-07-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3978Z	Veh. Inspected	FBE 5961T
Policy No.		Coverage (\$)	0.00
Claim No.	D19007273MFSH	Excess (\$)	0.00
Assign From	JASON TEA	Assign Date	20/11/2019

2. Vehicle Particulars & Condition

Make & Model	YAMAHA RXZ	c.c	135
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	PMY5PV100A0032114	Colour	RED
Odometer	48520	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	70/90 R18	DUNLOP	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/80 R18	DUNLOP	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/11/2019	Inspection Date	21/11/2019
Survey held at	PANG SCOOTER SERVICE BLK 1006 BUKIT MERAH LANE 2 #01-06 SINGAPORE 159762		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------