

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020647/FKA3Q2

Date: 26/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900007215
Claimant
Vehicle No : SH6535S **Insured Vehicle No :** SMG7486U
Date of Loss: 20/11/2019 Nature of Claim: TP Claim No: 0390360007SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH6535S**
Make & Model: TOYOTA PRIUS HYBRID, 1.8 (A) Engine No: 2ZR2B84209
Reg. Date: 07/01/2019 (Man. Year: 2018) Chassis No: JTDKB3FU303077765
Colour: Blue Odometer: 116227 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Davanti 7 mm Rear Left Side: Goodyear 7 mm
Front Right Side: Davanti 7 mm Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,056.62	1,957.90	2,098.72	51.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	860.00	570.00	39.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,486.62	2,817.90	2,668.72	48.64
+ GST 7.00/7.00% (S\$)	384.06	197.25	186.81	48.64
Nett Amount (S\$)	5,870.68	3,015.15	2,855.53	48.64
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$126.47/day) (S\$)		252.94		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,375.58		
Global Sum Settlement (S\$)		3,280.00		

INSPECTION

Date of Assignment: 20/11/2019
Date Inspected: 20/11/2019 Inspected At: ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID COVER	Not Necessary	1,126.60 FL	*- FL
2	1		*REAR TRUNK LID LOCK	Not Necessary	457.90 FL	*- FL
3	1		*REAR TRUNK LID GLASS (BLACK COLOR)	Not Necessary	733.50 FL	*- FL
4	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Broken	889.70 FL	*889.70 FL
5	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	52.90 FL	*52.90 FL
6	1		*REAR TRUNK LID LOGO (PHYBRID)	Necessary	52.90 FL	*52.90 FL
7	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	47.00 FL	*47.00 FL
8	1		*REAR BUMPER	Deformed	458.60 FL	*458.60 FL
9	1		*REAR BUMPER UNDER COVER	Scratched	552.60 FL	*552.60 FL
10	1		*REAR BUMPER SIDE RETAINER	Not Necessary	112.70 FL	*- FL
11	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
12	1		*REAR BUMPER TOW COVER	Deformed	82.70 FL	*82.70 FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	438.80 FL	*318.80 FL
14	1		*REAR TRUNK LID APPS STICKER	Necessary	40.00 FS	*40.00 FS
15	1		*REAR TRUNK LID COMFORT & TEL NO.STICKER	Necessary	60.00 FS	*60.00 FS
16	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	135.70 FS	*- FS
17	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,313.60	2,577.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,256.98	619.30
Total Parts (\$\$)	4,056.62	1,957.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	750.00	480.00
2	SPRAY PAINTING CHARGE	New	500.00	300.00
3	WIRING CHARGE	New	50.00	20.00
4	TUFF KOTE	New	50.00	30.00
5	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
			Gross Labour Cost (\$)	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >