

COMFORTDELGRO ENGINEERING

Our Job Ref No 305350423
Date : 22/11/2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax :
Attn : RAM
: SH 6535S 20.11.19


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


- The repair job shall bill to: AIG --- SMG7486U
###
- The finalized amount shall be:

(a) Spare Parts after List discount		<u>1963.38 \$1957.89</u>
(b) Labour Charges	###	<u>\$860.00</u>
Total for Part-By-Part Repair Cost		<u>2823.38</u>
	###	<u>\$2817.88</u>
- (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

- Estimated normal period for repairs: 3 working days
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
- Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : Ram
Date : 22/11/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305350423
 REGN NO : SH 6535S
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 07.01.2019
 DATE/TIME IN : 20.11.2019 10:10
 ACCIDENT DATE : 20.11.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2346-G	PRIG4 GARNISH SUB ASSY BA	1	889.70	25.00	667.27
0002	04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95
0003	04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1	552.60	25.00	414.45
0004	04-01-0302-2286-G	PRIG4 COVER REAR BUMPER-T	1	82.70	25.00	62.02
0005	04-01-0302-2288-G	PRIG4 REINFORCEMENT SUB-A	1	318.80	25.00	239.10
0006	04-01-0302-2269-G	PRIG4 ORNAMENT SUB-ASSY B	1	47.00	25.00	35.25
0007	04-01-0302-2271-G	PRIG4 PLATE-BACK DOOR NAM	1	52.90	25.00	39.67
0008	04-01-0302-2270-G	PRIG4 PLATE-BACK DOOR NAM	1	52.90	25.00	39.67
0009	28-01-9999-2025-A	APP LOGO REAR BONNET CTPL	1 N	40.00	2.50-	40.00
0010	28-01-0302-2015-A	PRIVC REAR BONNET COMFORT	1 N	30.00	0.25	30.00
0011	28-01-0302-0006-A	PRIVC REAR BOOT 65521111	1 N	30.00	0.03-	30.00
0012	04-01-0302-2267-G	PRIVC BUMPER PIECE	10	22.00	0.00	22.00 16.5

SUB-TOTAL : ~~1,963.38~~

1957.88

JOB NATURE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305350423
 REGN NO : SH 6535S
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(C
 DATE OF REGN : 07.01.2019
 DATE/TIME IN : 20.11.2019 10:10
 ACCIDENT DATE : 20.11.2019

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 PB	PANEL BEATING	480.00	/			
0001 SP	SPRAYPAINT CHARGE	300.00	/			
0002 17-01	CHECK ALL LIGHTING	20.00	/			
0003 20-00	TUFF COAT ON AFFECTED PARTS.	30.00	/			
0004 L	REMOVE/REFIX REVERSE SENSOR	30.00	/			
SUB-TOTAL :						860.00

TOTAL : ~~2,823.38~~ \$2817.88

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

REPAIR ESTIMATE

VEHICLE NO: SH 6535S

20/11/2019 13:25

MAKE :

MODEL : TOYOTA PRIUS

AKG-JM
PIP

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER new <i>Xnn</i>			\$ 1,126.60
REAR TRUNK LID LOCK <i>Xnn</i>			\$ 457.90
REAR TRUNK LID GLASS (BLACK COLOR) <i>Xnn</i>			\$ 733.50
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>Br</i>			\$ 889.70
REAR TRUNK LID LOGO (PRIUS) <i>new</i>			\$ 52.90
REAR TRUNK LID LOGO (HYBRID) <i>new</i>			\$ 52.90
REAR TRUNK LID LOGO (TOYOTA STAR) <i>new</i>			\$ 47.00
REAR BUMPER <i>DEF</i>			\$ 458.60
REAR BUMPER UNDER COVER <i>SC</i>			\$ 552.60
REAR BUMPER SIDE RETAINER <i>Xnn</i>			\$ 112.70
REAR BUMPER CLIPS <i>new</i>			\$ 22.00
<i>See supplementary</i> SUB TOTAL			\$ 4,506.40
LESS 25% DISCOUNTED TOTAL			\$ 1,126.60
DISCOUNTED TOTAL			\$ 3,379.80
REAR TRUNK LID APPS STICKER <i>new</i>			\$ 40.00
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>new</i>			\$ 60.00
REAR BUMPER REVERSE SENSOR <i>Xnn</i>			\$ 135.70
REAR BUMPER RUBBER MAT <i>Xnn</i>			\$ 50.00
LABOUR CHARGE			
Panel Beating			\$ 750.00
Spray Painting Charge			\$ 500.00
Wiring Charge			\$ 50.00
Tuff Kote			\$ 50.00
Remove/Refix Reverse Sensor			\$ 80.00
TOTAL LABOUR			\$ 1,430.00
ESTIMATE TOTAL			\$ 5,095.50

2075.7

NETT
NETT
NETT
NETT

\$480
\$300
\$20
\$30
\$30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:

Ram (LKE)
20/11/19 1520hrs
Povrasurama@lkkauto.com
88622728 hr
3 repair days
Part by Part
bes spray photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

