

CCU/A1G19020652 / AF63



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

KDY2318015924

Vehicle No. GBD2185S TOYOTA DYNA

TPA16
Khanhachan

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR BOOT COVER <i>Dented.</i>		1837.50	1265
1	REAR BOOT COVER SIDE BRACKET L LOCK	<i>3 new</i>	207.90	X
1	REAR BOOT COVER SIDE BRACKET RUBBER		101.00	X
1	REAR BOOT " DYNA " EMBLEM <i>new</i>		50.00	✓
1	REAR BOOT MEMBER <i>Dented</i>		410.00	✓
1	REAR BOOT REFLECTOR LH & RH @\$95.00	<i>crushed</i>	190.00	✓
1	REAR NUMBER PLATE PANEL <i>Best</i>		315.00	175
1	REAR NUMBER PLATE LAMP <i>new</i>		295.00	X
2	REAR LAMP LH & RH @\$275.00 <i>crushed</i>		550.00	✓
1	REAR END PANEL (LOWER MEMBER) <i>Repeated</i>		1341.90	X
2	REAR LOWER MEMBER BRACKETE @\$145.10	<i>3 new</i>	290.20	X
1	REAR CHASSIS FRAME (DECK SUPPORT)		1659.00	X
1	REAR FLOOR DECKING <i>Peris</i>		2079.00	X
2	REAR CHASSIS FRAME U BOLTS <i>new</i>		367.50	X
1	REAR EXHAUST PIPE <i>3 new</i>	3063.10	581.00	X
2	REAR EXHAUST PIPE BRACKET	2297.32	126.00	X
1	REAR TOW HOCK <i>new</i>		80.20	X
1	REAR BOOT STEP BRACKET <i>Best</i>		85.00	✓
1	REAR BOOT STEP BRACKET STAINLESS STEEL <i>new</i>		787.50	X
2	REAR BOOT HINGES LH & RH @\$80.00 <i>new</i>		160.00	X
2	REAR BOOT STOPPER PILLAR LH & RH @\$210.00 <i>Peris</i>		420.00	X
2	REAR BOOT STOPPER LH & RH @\$22.50 <i>new</i>		45.00	X
2	Taillamp Panel LH and RH (A) <i>Best</i>	169.10.	11978.70	
		338.20 less	25% 2994.68	25%
			8984.03	
SPECIAL NETT ITEMS				
1	70KM/H STICKER <i>3</i>		80.00	15
1	13 PAX STICKER <i>new</i>		70.00	15
1 SET	REVERSE SENSOR <i>new</i>		262.50	X
1	REAR BOOT COMPANY STICKER <i>new</i>		300.00	200.
1	REAR CAR PLATE WITH PLATE <i>Crushed</i>		80.00	50
TOTAL PARTS			9776.53	

280



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Vehicle No. GBD2185S TOYOTA DYNA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	ADJUSTMENT
1	<u>LABOUR</u> To remove the affected parts & fittings to commence repairs; replace parts	1600.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	500
3	To remove, refix wiring system at accident damaged areas	250.00	30
4	To carry out chassis alignment	350.00	X
5	To perform anti-rust treatment on affected areas	270.00	60
6	To remove and replace rear exhaust pipe & re-align	200.00	X 1190
Labour Total :		3870.00	
TOTAL (PARTS & LABOUR):		13646.53	

total: 3767.32

h/s: 3Kk ✓

04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: