

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
Date: 21/11/2019
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO.SLG3981U
CHASSIS NO : RU31208692
MAKE / MODEL : Honda Vezel Hybrid1.5X CVT
DATE OF ACCIDENT :19/11/2019
YOUR INSURED VEHICLE NUMBER : SKW5725D
MILEAGE : 177786 km

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

<u>PARTS DeSCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1 Front bumper / DP	1PC	\$955.00	\$955.00
2 F/R fender wheel arch moulding / SCH	1PC	\$300.00	\$300.00
3 F/R headlamp assy (LED) / CR4	1PC	\$2,100.00	\$2,100.00
4 F/R headlamp lower bracket / CRA	1PC	\$40.00	\$40.00
5 F/R headlamp top bracket / CRA	1PC	\$180.00	\$180.00
LIST TOTAL S\$:			\$3,575.00
20.00% DISCOUNT S\$:			\$715.00
			\$2,860.00

SPECIAL NETT

1 Front bumper clips / Nec	1 SET	\$80.00	30
2 F/R fender wheel arc moulding clips / Nec.	1 SET	\$80.00	30
Special Nett Total S\$:		\$80.00	

LABOUR CHARGES

1 To labour charge for removing front bumper out to facilitate repairs and replacement of damaged part, Repair fender FR.	\$900.00	500
2 To respray front bumper, F/R fender and F/R fender wheel arc moulding	\$900.00	500
3 To check and focus both headlamps	\$80.00	X
LABOUR TOTAL S\$:		\$1,880.00
TOTAL S\$:		\$4,820.00
7% GST		\$337.40
GRAND TOTAL S\$:		\$5,157.40

Repair day - 4 days
4

Sun Pm (Lkk)

21/11/2019.

TP with prejudice.

P/P Repair

Before spray paint