

ve

Year Regn : 29/09/2016

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
Date: 21/11/2019
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLG3981U
CHASSIS NO : RU31208692
MAKE / MODEL : Honda Vezel Hybrid 1.5X CVT
DATE OF ACCIDENT : 19/11/2019
YOUR INSURED VEHICLE NUMBER : SKW5725D
MILEAGE : 177786 km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1 Front bumper / DP	1PC	\$955.00	\$955.00 850
2 F/R fender wheel arch moulding / SCH	1PC	\$300.00	\$300.00 192.60
3 F/R headlamp assy (LED) / CR4	1PC	\$2,100.00	\$2,100.00 1820.20
4 F/R headlamp lower bracket / CRA	1PC	\$40.00	\$40.00 /
5 F/R headlamp top bracket / CRA	1PC	\$180.00	\$180.00 60
LIST TOTAL S\$:			\$3,575.00 2962.8 + 60
20.00% DISCOUNT S\$:			\$715.00
			\$2,860.00 3,022.8

Supp
* RH Bumper retainer - \$60 /

SPECIAL NETT	QTY	UNIT PRICE	LIST PRICE
1 Front bumper clips / NEC	1 SET	\$80.00	\$80.00 30
2 F/R fender wheel arc moulding clips / NEC	1 SET	\$80.00	\$80.00 30
Special Nett Total S\$:			\$80.00

LABOUR CHARGES	QTY	UNIT PRICE	LIST PRICE
1 To labour charge for removing front bumper out to facilitate repairs and replacement of damaged part, Repair fender FR.		\$900.00	500
2 To respray front bumper, F/R fender and F/R fender wheel arc moulding		\$900.00	500
3 To check and focus both headlamps		\$80.00	X

LABOUR TOTAL S\$:	\$1,880.00
TOTAL S\$:	\$4,820.00
7% GST	\$337.40
GRAND TOTAL S\$:	\$5,157.40

Repair day - 4 days

Sum Pm (Lkk)
21/11/2019.
TP within procedure.

Lump Sum
p/p Repair
Before spray paint

L/S = 2,800

4 days

3,022.8
- 20%
P = 2,418.24
N = 60
L = 1,000
3,478.24
- 20%
2,782.60

YR Regn = 29/09/2016

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
Date: 21/11/2019
Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLG3981U
CHASSIS NO: RU31208692
MAKE / MODEL: Honda Vezel Hybrid 1.5X CVT
DATE OF ACCIDENT: 19/11/2019
YOUR INSURED VEHICLE NUMBER: SKW5725D
MILEAGE: 177786 km

3,022.8
- 20%
P = 2,418.24
M = 60
L = 1000

3,478.24
- 20%
2,782.60

PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1 Front bumper / DP	1PC	\$955.00	\$955.00 850
2 F/R fender wheel arch moulding / SCH	1PC	\$300.00	\$300.00 192/60
3 F/R headlamp assy (LED) / CR4	1PC	\$2,100.00	\$2,100.00 1820.20
4 F/R headlamp lower bracket / CRA	1PC	\$40.00	\$40.00
5 F/R headlamp top bracket / CRA	1PC	\$180.00	\$180.00 60

LIST TOTAL S\$: \$3,575.00
20.00% DISCOUNT S\$: \$715.00
\$2,860.00

3635.00
727.00
2908.00

Supplementary
60 Abumper RH returner

SPECIAL NETT	
1 Front bumper clips / Nec	1 SET
2 F/R fender wheel arc moulding clips / Nec.	1 SET

\$80.00 30
\$80.00 30
Special Nett Total S\$: \$80.00

60.00

LABOUR CHARGES

1 To labour charge for removing front bumper out to facilitate repairs and replacement of damaged part, Repair fender FR.	\$900.00 500
2 To respray front bumper, F/R fender and F/R fender wheel arc moulding	\$900.00 500
3 To check and focus both headlamps	\$80.00 X

LABOUR TOTAL S\$: \$1,880.00
TOTAL S\$: \$4,820.00
7% GST \$337.40
GRAND TOTAL S\$: \$5,157.40

1,000.00
3,920.00
net 3,968.00

Repair day - 4 days

Sun Pm (Lklk)
21/11/2019.

TP wither pre-judice.

L/S Repair - Part by Part
After spray paint
B4 paint photo sent

Supp
RH bumper returner.

L/S = 2,800
4 days


Oi Sun Pin (LKK Auto)

From: Siak Tong Sim <siaktong@lioncityrentals.com.sg>
Sent: Thursday, 26 December, 2019 1:29 PM
To: Oi Sun Pin (LKK Auto)
Subject: Re: Final Bill: SLG3981U

Follow Up Flag: Follow up
Flag Status: Flagged

Sun Pin
Ok confirmed lump sum \$2,800.00/4 days

Regards
S.T.Sim (65-97422188)
Manager
Accident Reporting Center
60 Jalan Lam Huat
#04-35/36 Carros Centre
Singapore 737869



On Thu, Dec 26, 2019 at 10:55 AM Siak Tong Sim <siaktong@lioncityrentals.com.sg> wrote:
Sun Pin
This repairs is Part By Part

Regards
S.T.Sim (65-97422188)
Manager
Accident Reporting Center
60 Jalan Lam Huat
#04-35/36 Carros Centre
Singapore 737869



On Tue, Dec 24, 2019 at 11:31 AM Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com> wrote:

Dear Mr Sim,

Kindly refer the finalize amount \$2,800. Repair day 4 days, (L/S repair, before gst).

If agree please update.