

# COMFORTDELGRO ENGINEERING

Our Job Ref No 305350593

Date : 26/11/2019

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

TO : Chan Jin Le

## FINALIZATION FORM

To : LKK  
Attn : RAM  
: SHC3557E

Fax :  
20.11.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: AIG --- SGV 899A  
###
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \$821.12
  - (b) Labour Charges ### \$470.00
  - Total for Part-By-Part Repair Cost** \$1,291.12  
###
  - (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost**


3. Estimated normal period for repairs: 2 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : JUMANI  
Tel : 6214 8315  
Fax : 65468156

Signature :   
Name : Ram  
Date : 26/11/19

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 3557E

**MAKE :**

**MODEL : HYUNDAI IONIQ**

DATE 20/11/2019 16:43

AG-Ju

P/P CLK,

MODEL	: HYUNDAI IONIQ		Qty	Parts Description/ Labour	Type	Unit Price	Amount
				Rear Bumper <del>DEF</del>			\$ 459.40
				Rear Bumper Centre Moulding Assy <del>cut</del>			\$ 451.25
				Rear Bumper Lower Centre Moulding Assy <del>xnn</del>			\$ 155.00
				Rear Bumper Stay <del>xnn</del>			\$ 138.10
				Rear Bumper Side Bracket (LH/RH) <del>xnn</del>		\$ 33.10	\$ 66.20
				Rear Bumper Cover Clips <del>xnnec</del>			\$ 22.00
				<b>SUB TOTAL</b>			<b>\$ 1,291.95</b>
				<b>LESS 20%</b>			<b>\$ 258.39</b>
				<b>DISCOUNTED TOTAL</b>			<b>\$ 1,033.56</b>
				Rear Bumper Reverse Sensor <del>xnn</del>			\$ 135.70
				Rear Bumper Rubber Mat <del>xnnec</del>			\$ 50.00
				rear NO. plate cra — \$25			<b>\$ 185.70</b>
				<b>Labour Charge</b>			
				Panel Beating		\$200	\$ 350.00
				Spray Painting Charge		<del>\$200</del>	\$ 250.00
				Wiring Charge			\$ 50.00
				Remove/Refix Reverse Sensor		\$30	\$ 80.00
				<b>TOTAL LABOUR</b>			<b>\$ 730.00</b>
				<b>ESTIMATE TOTAL</b>			<b>\$ 1,949.26</b>
				<p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p>			
				<p>Ram (LKK) 21/10/19 1200hrs Part by Part 2 repairs days All repair photo Parasuram@LKKAuto.com 88622778</p>			
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>							

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305350593  
REGN NO : SHC3557E  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 10.07.2019  
DATE/TIME IN : 20.11.2019 13:50  
ACCIDENT DATE : 20.11.2019

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

---

PART REQUISITION

---

0001	04-01-0104-2533-G	IONIQV2 MOULDING ASSY-RR	1	451.25	20.00	361.00
0002	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52
0003	04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1 N	50.00	2.00-	50.00
0004	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0005	FNPS	NO PLATE(S)	1 N	25.00	2.00-	25.00

SUB-TOTAL : 821.12

---

JOB NATURE

---

0000	PB	PANEL BEATING	240.00
0001	SP	SPRAYPAINT CHARGE	200.00
0002	L	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 470.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305350593  
REGN NO : SHC3557E  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 10.07.2019  
DATE/TIME IN : 20.11.2019 13:54  
ACCIDENT DATE : 20.11.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,291.12

\_\_\_\_\_  
MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO