COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHC 3557E :

MAKE

: HYUNDAI IONIO MODEL

DATE 20/11/2019 16:43

Alg. Ju.

ty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 459.40	
	Rear Bumper Centre Moulding Assy			\$ 451.25	
	Rear Bumper Lower Centre Moulding Assy			\$ 155.00	
	Rear Bumper Stay ×n\			\$ 138.10	
	Rear Bumper Side Bracket (LH/RH) × 10		\$ 33.10	\$ 66.20	
	Rear Bumper Cover Clips * Name		55.10	\$ 22.00	
	Real Bulliper Cover Clips & 12411			22.00	
	SUB TOTAL			\$ 1,291.95	1
	LESS 20%			\$ 258.39	
	DISCOUNTED TOTAL			\$ 1,033.56	1
				#1	
	Rear Bumper Reverse Sensor ×n~			\$ 135.70	N
	Rear Bumper Rubber Mat			\$ 50.00	N
	Real Bumper Rubber Wat			3 50.00	1
			100	\$ 185.70	1
	Labour Charge		147 Late 1.44		
	Panel Beating			\$ 350.00	de
			11. 11.11.		4
	Spray Painting Charge		\$20	\$ 250.00	4
	Wiring Charge			\$ 50.00	
	Remove/Refix Reverse Sensor			\$ 80.00	
	TOTAL LABOUR		PAM (LXX) 21/10/1/19 1200000 21/10/1/19 1200000 21/10/1/19 1200000 21/10/1/19 1200000 21/10/1/19 1200000 21/10/1/19 1200000 21/10/1/19 12000000 21/10/1/19 12000000 21/10/1/19 1200000000000000000000000000000000000	\$ 730.00	1
	LKK Auto Consultants hence notify		RAM CHI JOON		
	the Repairer of the following: To resurvey before/after spray painting ESTIMATE TOTAL		21/18/1/19	\$ 1,949.26	
	To display damaged part(s) during resurvey		21 Pars		
	Parts prices are subject to confirmation		BUXX DI THIS		
	Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed		, pair	o eur	
	Supplementary item(s) must be resurveyed and		They but	to.Co	
	is subject to final approval from Insurance Company		" OF reboin VIX	Ka	
	Acknowledged by Repairer		mana M		
	Signature:		1000 118		
	Date:		28622	7 /	
			40		
					-