

LKK:
IDAC

Survivor:

DOI:

Date / Time : _____

Registered in Merimex:

Pre-assign / CCU / FTE



Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II :\$5

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel. No. _____

(V/L: YES / NO)

Claim No. _____

Policy No.

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability

Final ? Yes / No

SLH2283C



INRS:
WSP:
Tel :
Liability
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time	STAGE	DATE / PIC
7/12 - Pending liability approval. ✓	Non-Reporting ltr (1st)	
5/2 - CHECK w KRC on the COP amt. Not telling w his amt. ✓	Non-Reporting ltr (2nd)	
	Non-Reporting ltr (Final)	
	Notification ltr (if non-pickup)	
	Call OI:	
	After call ltr to OI:	
2/12 - COR to TP (pending amended LOD & invoice)	Documentation Check List: Handler	Typist
5/2 - LOD in, file pass by time report.	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
5/2 - Pending mandate approval.	After call ltr to OI:	<input checked="" type="checkbox"/>
1/15 - off to TP (as 91559.83 as per LOD, DV send (pending DV)	Authorisation To Act:	<input checked="" type="checkbox"/>
7/15 - DV in, file pass Admin to close.	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input checked="" type="checkbox"/>
	Post-Repair Photos:	<input checked="" type="checkbox"/>
	Others:	<input checked="" type="checkbox"/>
PRELIMINARY ADVICE Date/Time:	Sent By:	
FINALIZATION Date/Time:	Confirm with:	Confirm by: KENNETH
Repair Cost: PIP \$5 1520.07 (2 days) Reduction: 5198.23 % 59		Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT Date/Time: 1/17/2020 Confirm with: KENNETH		Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 29		If NO or B 28, Ass. Lia:
Repair Cost: (w/mmt) \$5 1412.47		
Loss of Rental (LOR): \$5 (days)		
Loss of Use (LOU): \$5 211.90 (569.95 x 2 days)		
Loss of Income (LOI): \$5 (3 x days)		
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/> (Tick only one)		
GIA/LTA Search \$5 9.45		
Medical: \$5 -		
Disbursement: \$5 - (e.g. Tow/ Independent)		
Legal Cost: \$5 -		
Total: \$5 1559.82	Global Sum \$5:	
FINAL PAYMENT Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1: \$5 1559.82	Name 1: Eastern Performance Pk Ltd	
Payee 2: (Strike if N.A.) \$5	Name 2:	
Payee 3: (Strike if N.A.) \$5	Name 3:	

ASS- REC. BY:

REF:

III

ASSIGNMENT

From:

Date:

25/11/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLH 2283C

at Workshop m/s

Esteem Performance

of

385 Sin Ming Drive

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 10 am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res: Yes or No

Lum Sum:

1.31%

3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLH 2283C

Yr Reg:

10. 16

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

C.C.

1798

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

240625

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

J70KB3F4 70353650

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

19/11/19

D.O.I.

25/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P \$1720.09

(Red = \$1798.27 / 57.1.)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / LBJ: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Other

TOTAL



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLH 2283 C

Not Authorised
Resurvey By point

Parts	(a) Cost / List Price Items	\$	1,744.40
	Plus/Less 25%	\$	436.10
	Total of Cost / List	\$	1,308.30
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	1,508.30
Labour		\$	1,570.00
Total		\$	3,078.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before repair spray painting
- To display damaged parts during resurvey
- Parts prices are to be at collection
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 25/11/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is not authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : L Date: 25/11/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLH 2283 C**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FU703536506**

Submit By : **JENNY**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	X
2	Rear bumper	1	\$497.50		✓
3	Rear bumper clip	10	\$40.00		✓
4	Rear bumper side retainer LH	1	\$112.70		X
5	Rear bumper side retainer RH	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		X
7	Rear bumper lower garnish centre	1	\$582.60		✓
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey to include spray painting
- To rectify damaged part(s) during resurvey
- Final prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurer

Acknowledged by Repairer:
Signature:
Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Company Reg No. 200005485N / GST No. 20-0005485-N

12/11/19

Kg

a la Pen Photo



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569538.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempart.com.sg

Repair Estimates

SLH 2283 C

Finalised

Parts	(a) Cost / List Price Items	\$ 1120.10	1,744.40
	Plus/Less 25%	\$ 270.03	436.10
	Total of Cost / List	\$ 840.07	1,308.30
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
	Total Parts Cost	\$	1,508.30
	Labour	\$ 470.00	1,570.00
	Total	\$ 1320.07	3,078.30

Not Authorised

Recovery B4point

21302.07

#1320.07

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 25/11/19 at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / Is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor : L Date: 25/11/19



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 250, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLH 2283 C**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU703536506**

Submit By : **JENNY**
Year Manufacture : **2016**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	X
2	Rear bumper	1	\$497.50		✓
3	Rear bumper clip	10	\$40.00		✓
4	Rear bumper side retainer LH	1	\$112.70		X
5	Rear bumper side retainer RH	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		X
7	Rear bumper lower garnish centre	1	\$582.60		✓
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

1120-10

480

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 20 November 2019 1:32 PM
To: jenny chong; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sundari Nagarajan - III
Subject: RE: REQUEST FOR PRI SURVEY SLH2283C

2:12pm 20/11/2019

p: Carmen
v: Not In
-

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLH2283C and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: jenny chong [mailto:jenny@esteemperf.com.sg]
Sent: 20 November, 2019 1:28 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: carmen lim <carmen@esteemperf.com.sg>; serence ctc <serence@esteemperf.com.sg>
Subject: Re: REQUEST FOR PRI SURVEY SLH2283C

Dear Sir / Madam

We are refer LKK to survey the car.

Thank you



Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division
Esteem Performance Pte Ltd

P: 6484 1221
F: 6484 7829
E: jenny@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259
(Head Office)
385 Sin Ming Drive Vicom Inspection Centre
(Showroom)

www.esteemperformance.com



On Wed, Nov 20, 2019 at 1:22 PM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: jenny chong [mailto:jenny@esteemperf.com.sg]

Sent: 20 November, 2019 12:29 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: carmen lim <carmen@esteemperf.com.sg>; serence ctc <serence@esteemperf.com.sg>

Subject: REQUEST FOR PRI SURVEY SLH2283C

Dear Sir / Madam,

Accident involving SLH2283C & SHA6513Y on 19.11.2019

Your insured vehicle no : SHA6513Y

VEHICLE WILL BE IN ON 25.11.2019 FOR SURVEY

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)

We act for Grab Rentals Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no SLH 2283 C

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address : 385 SIN MING DRIVE (S) 575718 (INSIDE VICOM)

Tel : 6566 2112 / 8799 0066

Fax : 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

Thank you



Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221

F: 6484 7829

E: jenny@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this

message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

...CLAIM SUBFOLDER...(Pending for Survey Report)
Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Nov 2019 Edit Reg		20 Nov 2019 00:00 Edit Adj Rpt	\$41,320.07 Edit Estimates	\$41,320.07 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLH2283C	Date of Loss:	19/11/2019 16:00 - :59 [36 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT19110477	Policy/Cover Note No.:	MCOMD015
Vehicle Reg. No. (Insured):	SHA6513Y	Policy No. (Claimant):	A29114756MKF
		Excess:	
Repairer:	Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel: 64841221		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 02/12/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- III_SG (05/03/2020): Alert - Adj Mandate Approved (\$41559.82) - SLH2283C - Claim Handler: Sundari Nag...
- III_SG (27/12/2019): Alert - Adj Mandate Approved (\$40.00) - SLH2283C - Claim Handler: Sundari Nagara...

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH2283C (MCT19110477)
[SHA6513Y]
TP
GRAB RENTALS PTE LTD
Nov 19 2019 4:00PM
[COMFORT TRANSPORTATION PTE LTD]
Esteem Performance Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/03/20 10:02	LKK SURVEY PHOTO	<div></div> <div>Load PDF</div>	

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/11/19 14:57	EMAIL FROM III DD 20112019	<div></div> <div>Load PDF</div>	
2	21/11/19 14:57	TP EST & GIA REPORT	<div></div> <div>Load PDF</div>	
3	02/12/19 16:10	TP ESTIMATE- MARKED.	<div></div> <div>Load PDF</div>	
4	24/02/20 17:40	LOD AND OTHER DOCUMENTS	<div></div> <div>Load PDF</div>	
5	28/02/20 13:46	WORKSHOP INVOICE	<div></div> <div>Load PDF</div>	
6	28/02/20 13:46	RENTAL RECEIPT	<div></div> <div>Load PDF</div>	
7	28/02/20 13:46	LTA SEARCH	<div></div> <div>Load PDF</div>	
8	28/02/20 13:46	LOD	<div></div> <div>Load PDF</div>	
9	30/03/20 10:24	AUTHORISATION TO ACT FORM	<div></div> <div>Load PDF</div>	
10	30/03/20 10:24	DISCHARGE VOUCHER	<div></div> <div>Load PDF</div>	

No

Finalized On

India International Insurance Pte Ltd (HQ)

Thumbnail

Print

1	22/11/19 08:39	Singapore Accident Statement	<div></div> <div>Load PDF</div>	
---	----------------	------------------------------	---------------------------------	--

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19020658/KGA3Q2

Date: 30/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant
 Vehicle No : SLH2283C Insured Vehicle No : SHA6513Y
 Date of Loss: 19/11/2019 Nature of Claim: TP Claim No: MCT19110477

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH2283C
 Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZRR957721
 Reg. Date: 27/10/2016 (Man. Year: 2016) Chassis No: JTDKB3FU703536506
 Colour: Metallic Silver Odometer: 240825 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,508.30	840.07	668.23	44.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,570.00	480.00	1,090.00	69.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,078.30	1,320.07	1,758.23	57.12
+ GST 7.00/7.00% (S\$)	215.48	92.40	123.08	57.12
Nett Amount (S\$)	3,293.78	1,412.47	1,881.31	57.12
+ Loss of Use (2.0 x S\$69.95/day) (S\$)		139.90		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,559.82		

INSPECTION

Date of Assignment: 20/11/2019
 Date Inspected: 25/11/2019 Inspected At: 385 SIN MING DRIVE
 Estimated Period of Repair: 2.0 days Repairer: CPte Ltd (HQ)

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2020)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH2283C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR	Serviceable	200.00 FS	*- FS
2	1		*REAR BUMPER	Buckled	497.50 FL	*497.50 FL
3	10		*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
4	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	112.70 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Repair	398.90 FL	*- FL
7	1		*REAR BUMPER LOWER GARNISH CENTRE	Dented	582.60 FL	*582.60 FL
					Sub Total (S\$)	1,944.40 1,120.10
					- List Item Discount on L Items 25.00/25.00% (S\$)	436.10 280.03
					Total Parts (S\$)	1,508.30 840.07

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER ,END PANEL ,TAILDOOR)	New	600.00	200.00
2	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER ,END PANEL ,TAILDOOR)	New	600.00	220.00
3	TO CHECK WIRING	New	50.00	10.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	50.00
5	TO TUFF COAT	New	50.00	0.00
6	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	0.00
Gross Labour Cost (S\$)			1,570.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >