

15/5/2010

INS. CASE OWNER:

CC 4 / FWD1902 0661, A *gib*LKK:
IDAC:

Surveyor:

Adrain

DOI:

ASSIGNMENT


Date / Time:

20/11/19

Registered in Merimen:

21/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJU 26289

Name of Insured:

SEE SING KUAN

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

20/11/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

120190 003605

Policy No.:

PNPND 17-00005462-01

Make / Model:

WISSAM

Place of Accident:

SLE

If NO, Driver Name / Age:

Driver Tel No.:


(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

*mg**Solution*

INSRS:

WSP:

Tel:

Liability:

RMKS:




INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
	<i>SJP 421P-X</i>	Non-Reporting ltr (1st):	
	<i>SJU 26289-X</i>	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☒ ☐
		After call ltr to OI:	☒ ☐
		Authorisation To Act:	☒ ☐
		Release Voucher:	☒ ☐
		Final Repair Bill:	☒ ☐
		Car Rental Invoice:	☒ ☐
		Towing Invoice:	☒ ☐
		LTA / GIA:	☒ ☐
		Medical Bill:	☒ ☐
		PIR:	☒ ☐
		Mandate/Reject Instruction:	☒ ☐
		LOD	☒ ☐
		Payment Breakdown Form:	☐ ☐
		Post-Repair Photos:	☒ ☐
		Others:	☒ ☐

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm by:	<i>Adrain</i>
Repair Cost:	<i>45</i>	S\$ <i>5200.00</i>	(<i>8</i> days) Reduction:	<i>5284.48</i> % <i>50</i>	Email ☐ Call ☐
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email ☐ Call ☐	
Final Liability:	% <i>100</i>	(Agreed / Assessed) BOLA S/N No.:	<i>27</i>	If NO or B 28, Ass. Lia:	
Repair Cost:	<i>(W/ASS)</i>	S\$ <i>5264.00</i>			
Loss of Rental (LOR):	S\$ <i>-</i>	(<i>-</i> days)			
Loss of Use (LOU):	S\$ <i>500.00</i>	(\$ <i>50</i> x <i>10</i> days)			
Loss of Income (LOI):	S\$ <i>-</i>	(\$ <i>-</i> x <i>-</i> days)			
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐	[Tick only one]				
GIA/LTA Search	S\$ <i>2.45</i>				
Medical:	S\$ <i>-</i>				
Disbursement:	S\$ <i>-</i>	(e.g. Tow/ Independent)			
Legal Cost	S\$ <i>-</i>				
Total:	S\$ <i>6071.45</i>	Global Sum S\$:			
FINAL PAYMENT		Date/Time:	Confirm with:	Email ☐ Call ☐	
Payee 1:	S\$ <i>6071.45</i>	Name 1:	<i>MG Solution Pte Ltd</i>		
Payee 2: (Strike if N.A.)	S\$ <i>-</i>	Name 2:			
Payee 3: (Strike if N.A.)	S\$ <i>-</i>	Name 3:			

COPY SENT
31/11/20

ASS. REC. BY:

REF: PWP

g

ASSIGNMENT

From:

Date:

21/11/19

Estimated Cost:

Veh No:

SJF431P

Yr Regn:

2008, May

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

☒ OD / ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

SJF 431P

Make:

Honda Fit

C.C

1339

at Workshop m/s

MG solution

Colour

Red

A/C:

Insured / Std / NI / NA

of

23 Kaki Bukit Avenue 4

Sp. Reading

176186

T/Radio:

Insured / Std / NI / NA

Insured:

#02-03B

Eng/No:

Policy No.

C/No:

GE 61053802

Claims No.

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Modi: ☒ Nil / ☒ S/Rim / ☐ STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Tyre Size:

F:

205/45R16

R:

205/45R16

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

21/11/19

Survey held at

MG solution

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Reas o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP FWD

COE Expiry: 14/05/23.

4/5 \$5200/- (Red = \$5284.48 / 50%.)

MV: 21K.

PV: 13.3K

Nett: 7.7K

*

8 repair days + 1 sunday + 1 PRS = 10 days

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Insp (\$)

☐

: Weekend (\$)

Report Format:

Lump Sum / L.B.I. (\$)

Survey Fee:

Transportation:

3 + RS. \$1

Photos:

Others:

TOTAL

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: FWD	DATE	20/11/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	T/ P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJF431P		
MODEL	: HONDA FIT 1.3G A		Cecilia
CHASSIS NO			
<u>ACCIDENT DETAILS</u>			
DATE	: 20-Nov-19		
TIME	: 07:25HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Dented</i>	1	\$ 788.90	\$ 788.90
2	TAIL GATE EMBLEM FIT <i>new</i>	1	\$ 60.00	\$ 60.00
3	TAIL GATE INNER LOCK <i>new</i>	1	\$ 198.20	\$ 198.20
4	TAIL GATE CATCH <i>new</i>	1	\$ 55.70	\$ 55.70
5	TAIL GATE WEATHER STRIP <i>new</i>	1	\$ 102.00	\$ 102.00
6	TAIL GATE INNER TRIM <i>new</i>	1	\$ 153.50	\$ 153.50
7	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 97.10	\$ 97.10
8	REAR BUMPER <i>Distorted</i>	1	\$ 555.30	\$ 555.30
9	REAR BUMPER SIDE RETAINER <i>new RH</i>	2	\$ 64.50	\$ 129.00
10	REAR BUMPER TOWING COVER <i>Distorted</i>	1	\$ 52.30	\$ 52.30
11	TAIL LAMP RH <i>Smashed</i>	1	\$ 280.00	\$ 280.00
12	TAIL LAMP BRACKET RH <i>new</i>	1	\$ 48.00	\$ 48.00
13	TAIL LAMP PANEL RH <i>Dented</i>	1	\$ 155.60	\$ 155.60
14	REAR FENDER <i>Distorted</i>	1	\$ 860.00	\$ 860.00
15	REAR FENDER INNER TRIM <i>new</i>	1	\$ 320.00	\$ 320.00
16	REAR FENDER AIRVENT <i>new</i>	1	\$ 90.00	\$ 90.00
17	REAR FENDER QUARTER GLASS MOULDING <i>new</i>	1	\$ 120.00	\$ 120.00
18	REAR END PANEL <i>Dented</i>	1	\$ 380.00	\$ 380.00
19	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 120.00	\$ 120.00

3801.60

3041.28

TOTAL PRICE \$ 4,565.60

LESS 20% \$ 913.12

SUB TOTAL PRICE \$ 3,652.48

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Not in</i>	1	\$ 50.00	\$ 50.00	+
2	TAIL GATE INNER TRIM CLIP (SET) <i>Not in</i>	1	\$ 20.00	\$ 20.00	+
3	TAIL GATE WINDSCREEN SEALANT <i>7 in</i>	1	\$ 80.00	\$ 80.00	30
4	TAIL GATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	30
5	REAR BUMPER CLIP <i>Not in</i>	1	\$ 22.00	\$ 22.00	✓
6	REAR BUMPER LOWER LIP <i>Not in</i>	1	\$ 1,200.00	\$ 1,200.00	+
7	TAIL LAMP CLIP (SET) <i>Not in</i>	1	\$ 20.00	\$ 20.00	✓
8	REAR FENDER INNER TRIM CLIPS (SET) <i>Not in</i>	1	\$ 20.00	\$ 20.00	✓
9	REAR END PANEL TOP GARNISH CLIPS (SET) <i>Not in</i>	1	\$ 20.00	\$ 20.00	+
10	REAR END PANEL INSULATION SEAL <i>Not in</i>	1	\$ 120.00	\$ 120.00	60
11	WHEEL RIM <i>lit</i>	1	\$ 850.00	\$ 850.00	400
12	REVERSE SENSOR <i>Drop</i>	1	\$ 220.00	\$ 220.00	200

TOTAL \$ 2,682.00

782

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	1200	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	1000	
3	TUFF COAT	\$ 250.00	100	
4	WIRING CHECK	\$ 80.00	30	
5	TRANSFER TAILGATE MECHANISM	\$ 100.00	80	
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓	
7	REMOVE AND REFIX QUARTER GLASS	\$ 100.00	60	
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 150.00	50	
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 150.00	50	

TOTAL \$4,150.00

ESTIMATE REPORT

2690

TOTAL PARTS COST : \$ 6,334.48

TOTAL LABOUR COST : \$ 4,150.00

TOTAL REPAIR COST : \$ 10,484.48

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian L
L/S 21/11/19.

08 Days

total : 6513.28.

L/S : 5.2K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: