

**CAS GARAGE PTE LTD**

(Reg No. 201829067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: LONPAC INSURANCE BHD

Address: 300, BEACH ROAD, #17-04/07
THE CONCOURSE, S(199555)

Vic

Telephone: 62507388

Fax: 62963767

Email assignments@lkkauto.com

Make/ Model : HYUNDAI ELANTRA

Date: 21.05.2019

Chassis No : KMHD841CMHU143486

Vehicle No: SMF4771X

Date/Time of Accide 20.11.2019/ 1740

Date of Reg: 13.05.2016

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	BOOTLID <i>Dented</i>	1	\$ 1,720.40		\$ ✓ 1,720.40
2	BOOTLID SMART KEY ANTENNA <i>Painted</i>	1	\$ 265.30		\$ ✓ 265.30
3	BOOTLID BOOT RELEASE ANTENNA <i>new</i>	1	\$ 276.20		\$ ✗ 276.20
4	BOOTLID INNER TRIM <i>new</i>	1	\$ 406.20		\$ ✗ 406.20
5	BOOTLID REFLECTORS <i>LH cut</i>	2	\$ 689.70		\$ 689.70 379.40
6	BOOTLID EMBLEM "ELANTRA" <i>new</i>	1	\$ 95.30		\$ ✓ 95.30
7	BOOTLID EMBLEM "ELITE" <i>new</i>	1	\$ 89.60		\$ ✓ 89.60
8	BOOTLID LOGO	1	\$ 95.40		\$ ✓ 95.40
9	BOOTLID INNER LOCK <i>Dented</i>	1	\$ 298.70		\$ ✓ 298.70
10	BOOTLID LOWER LATCH <i>new</i>	1	\$ 45.20		\$ ✗ 45.20
11	BOOTLID WEATHERSTRIP <i>new</i>	1	\$ 301.20		\$ ✗ 301.20
12	REAR BUMPER <i>Deformed</i>	1	\$ 645.30		\$ ✓ 645.30
13	REAR BUMPER REFLECTORS <i>LH cut</i>	2	\$ 102.50		\$ 102.50 205.00
14	REAR BUMPER RETAINERS <i>new</i>	2	\$ 92.30		\$ ✓ 184.60
16	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 378.10		\$ ✓ 378.10
17	REAR REINFORCEMENT BRACKETS <i>new</i>	2	\$ 89.70		\$ ✗ 179.40
18	REAR MUDGUARDS <i>new</i>	2	\$ 90.60		\$ ✗ 181.20
19	REAR BUMPER COVERS <i>new</i>	2	\$ 154.80		\$ ✗ 309.60
20	TAILAMPS <i>LH cut</i>	2	\$ 889.60		\$ 889.60 779.20
21	TAILAMPS PANELS <i>new</i>	2	\$ 498.60		\$ ✗ 498.60 997.20
22	REAR FENDER INNER TRIM <i>new</i>	2	\$ 376.80		\$ ✗ 753.60
23	REAR FENDER INNER COWLING <i>new</i>	2	\$ 189.20		\$ ✗ 378.40
24	REAR END PANEL <i>Dented</i>	1	\$ 585.90		\$ ✓ 585.90
25	REAR END PANEL TOP GARNISH <i>Deformed</i>	1	\$ 235.80		\$ ✓ 235.80
Total List Price Cost					\$ 11,786.20
				PARTS DISCONT 20%	\$ 9,428.96

6276.20

5020.96

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING <i>new</i>	1 SET	\$ 50.00	\$ 50.00 50.00
2	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00 30.00
3	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00 30.00
4	REVERSE SENSOR <i>Damaged</i>	1 SET	\$ 250.00	\$ 250.00 250.00
5	REAR BOOTLID SPOILER <i>cracked</i>	1	\$ 450.00	\$ 450.00 450.00
6	REAR LOWER LIP (ACCESSORIES) <i>del</i>	1	\$ 650.00	\$ 650.00 650.00
7	REAR LOWER LIP CENTRE LAMP <i>lit</i>	1	\$ 200.00	\$ 200.00 200.00
8	REAR LOWER LIP EXHAUST GARNISH <i>new</i>	2	\$ 180.00	\$ 360.00 360.00
9	REAR FENDER INNER COWLING SET <i>2x new</i>	2 SET	\$ 60.00	\$ 120.00 60.00
10	REAR FENDER INNER TRIM CLIPS <i>2x new</i>	2 SET	\$ 60.00	\$ 120.00 60.00
11	END PANEL INSULATOR SEAL <i>new</i>	2	\$ 80.00	\$ 160.00 80.00
Total Special Nett Items				\$ 2,220.00

1450

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 2,000.00 2,000.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 2,000.00 2,000.00

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 200.00 60 200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ 150.00 80 150.00
TO APPLY SEALANT AND UNDERCOATING TO THE AFFECTED AREAS	\$ 280.00 60 280.00
TO REMOVE/ REFIT WIRING CHECKS FOR REAR TAILLAMPS	\$ 120.00 30 120.00
TO CONDUCT WATER LEAKAGE TEST	\$ 150.00 150.00
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING	\$ 150.00 50 150.00
TO REMOVE/ REFIT REVERSE CAMERA	\$ 150.00 50 150.00
TO REMOVE AND REPLACE BOOTLID MECHANISM	\$ 120.00 120.00
Total Others Cost	\$ 1,320.00

GRAND TOTAL

\$ **16,968.96**

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allangoh.cas@gmail.com
 Fax: +65 6509 9501

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Alan Lj
 r/s 21/11/19

06 Days

total: 8400.86

4/s: 6.7K ✓