

ASS. REC. BY:

REF: CS/SM019020666/Dydz¹²

Special Instruction:

Assigning: Bryan

ASSIGNMENT (Office)

From (Person):

Yong Kang Melvin

of

SMO

Date/Time:

21/11/19 @ 12:27pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8HC 8407Y

Insured:

SLX7552J

at Workshop m/s

Chunni Motor

Tel:

65425119

of

10 msk Ind. park 2A #0605/06

Policy No:

Claim No:

CMTD1905432/PC

Sum Insured:

Excess:

Make of Veh:

D.O.A.

20/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1:11pm @ 21/11/19

Person Contacted:

JynnVehicle IN OUT

Date/Time


Action/Instruction

Estimate25/11/19Email preli revised to melvin

ASSIGNMENT

COB July 2023
2015 July

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No. _____
at Workshop n/s _____
of _____
Insured: ☐ _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Est. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 6 days Res.: Yes or No
Turn Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 8407 Y ☒ Prime Mover /
Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /
Truck / Trailer or
Make: Hyundai I40 cc: 1685
Colour: Blue A/C: ☒ Insured / Std / NI / NA
Sp. Reading: 606023 T/Radio: Insured / Std / NI / NA
Eng/No: D4FDFEU461321
C/No: KMHLB41UMGU075469
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ In order / Jammed / Leaked / Burnt or
Brake: ☒ In order / Jammed / Leaked / Burnt or
Modi: ☒ Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/60 R16
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Westlake
Front: _____ Rear: _____
R/Bal: S mm R/Bal: S mm
L/Bal: S mm L/Bal: S mm
D.O.A: 20/11/2019 D.O.I: 21/11/2019
Survey held at: Chunni AMK
Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Sompo SLX 75525

07/01/2020 pinenr 2/5 8550/- with 6 days of rev (Red \$11204.74, 56%)

RECEIVED 08 JAN 2020

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Date/Time, File Return to?

2) 7/1/20 Typist

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Inve (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation

S + R5. \$

Photos

Others

TOTAL

For ☒ Form 1

Turn Sum D.E.E: \$8550/-

450



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: CMTD1905432/RE

Our ref: CS/SMO19020666/Dyd3

Date: 25/11/2019

The Motor Claims Department
M/s Sompo Insurance Singapore Pte Ltd

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SHC 8407Y


We thank you for your instruction on 21/11/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21/11/2019 at the premises of M/s CHUNNI MOTOR WORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	19,754.74
Revised Estimate Amount	: S\$	10,743.90
"Check" Items Amount	: S\$	
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

Bryan Ang

Automotive Assessor / Investigator

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 25 November 2019 10:32 AM
To: SUR; melvin.ye
Cc: Chan, Shu Hui Agnes; 'Henry, Irene James'
Subject: RE: SOMPO REF:CMTD1905432/RE: Accident involving veh no: SHC 8407Y & SLX 7552J on 20.11.19
Attachments: SHC 8407Y PRELI ADVISED.pdf

Dear Melvin,

Enclosed preliminary revised of vehicle SHC 8407Y
Date of survey: 21/11/2019
Number of days (estimated) : 6 days

Best Regards,

Veron Chen | Case Handler **on behalf of Yvonne**

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Thursday, 21 November, 2019 12:27 PM
To: Chunni Motor <chunnimotor@gmail.com>; SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: RE: SOMPO REF:CMTD1905432/RE: Accident involving veh no: SHC 8407Y & SLX 7552J on 20.11.19

Hi LKK Auto,

Please make arrangement to conduct survey for SHC8407Y.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Chunni Motor <chunnimotor@gmail.com>

Sent: Thursday, 21 November, 2019 10:15 AM

To: Henry, Irene James <irene.henry@sompo.com.sg>

Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: Re: SOMPO REF:CMTD1905432/RE: Accident involving veh no: SHC 8407Y & SLX 7552J on 20.11.19

Dear Sir,

We appoint LKK Auto Consultants - Rasul

Thank you

Regards,
Chunni Motor Work P/I

On Thu, Nov 21, 2019 at 9:39 AM Henry, Irene James <irene.henry@sompo.com.sg> wrote:

Our Reference : CMTD1905432/AGC

Your Reference: SHC 8407Y

Without Prejudice

Date: 20.11.2019

Attention:

CHUNNI MOTOR

ACCIDENT INVOLVING SLX 7552J & SHC 8407Y ON 20.11.2019

We refer to your Notice of Accident dated 20.11.2019.

Please be informed that **Agnes Chan** the handler of this case who can be contacted at 6329 5327/
agnes.chan@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Chunni Motor <chunnimotor@gmail.com>

Sent: Wednesday, 20 November, 2019 5:00 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: Accident involving veh no: SHC 8407Y & SLX 7552J on 20.11.19

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

Nivitha (LKK Auto)

From: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Sent: Thursday, 21 November 2019 12:27 PM
To: Chunni Motor; SUR; assignments
Cc: Chan, Shu Hui Agnes; Henry, Irene James
Subject: RE: SOMPO REF:CMTD1905432/RE: Accident involving veh no: SHC 8407Y & SLX 7552J on 20.11.19

Hi LKK Auto,

Please make arrangement to conduct survey for SHC8407Y.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Chunni Motor <chunnimotor@gmail.com>

Sent: Thursday, 21 November, 2019 10:15 AM

To: Henry, Irene James <irene.henry@sompo.com.sg>

Cc: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: Re: SOMPO REF:CMTD1905432/RE: Accident involving veh no: SHC 8407Y & SLX 7552J on 20.11.19

Dear Sir,

We appoint LKK Auto Consultants - Rasul

Thank you

Regards,
Chunni Motor Work P/l

On Thu, Nov 21, 2019 at 9:39 AM Henry, Irene James <irene.henry@sompo.com.sg> wrote:

Our Reference : CMTD1905432/AGC

Your Reference: SHC 8407Y

Without Prejudice

Date: 20.11.2019

Attention:

CHUNNI MOTOR

ACCIDENT INVOLVING SLX 7552J & SHC 8407Y ON 20.11.2019

We refer to your Notice of Accident dated 20.11.2019.

Please be informed that **Agnes Chan** the handler of this case who can be contacted at 6329 5327/
agnes.chan@sompo.com.sg .

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Chunni Motor <chunnimotor@gmail.com>
Sent: Wednesday, 20 November, 2019 5:00 PM
To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>
Subject: Accident involving veh no: SHC 8407Y & SLX 7552J on 20.11.19

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 8407Y

DATE : 20.11.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Compd

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>kt</i>			\$ 2,174.90
	Boot Lid Rubber <i>g/c</i>			\$ 96.50
	Boot Lid Lock Upper <i>hnl</i>			\$ 102.60
	Boot Lid Lock Lower <i>hnl</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>hnl</i>			\$ 28.70
	Boot Lid CRDI Plate <i>hnl</i>			\$ 27.90
	Boot Lid Lamp (RH) <i>crack</i>			\$ 565.60
	Boot Lid Trimboard <i>hnl</i>			\$ 116.40
	Boot Lid Trimboard Clips (10pcs) <i>hnl</i>			\$ 11.00
	Bootlid Moulding <i>hnl</i>			\$ 85.00
	Bootlid i40 Emblem <i>hnl</i>			\$ 27.90
	Bootlid Lower Garnish <i>hnl</i>			\$ 227.90
	Rear Bumper <i>form</i>			\$ 553.00
	Rear Bumper Reinforcement <i>crack</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>o/s</i> <i>hnl</i>	<i>N/S</i>	\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>hnl</i>			\$ 22.00
	Rear Bumper Bracket, RH <i>hnl</i>			\$ 35.60
	Rear Bumper Sponge <i>form</i>			\$ 118.40
	Rear Bumper Under Cover <i>destroyed</i> <i>cut</i>			\$ 228.00
	Rear Bumper Reflector Lamp (RH) <i>hnl</i>			\$ 30.60
	Tail Lamp (RH) <i>crack</i> <i>wandy</i>			\$ 697.80
	Tail Lamp Quarter Panel (RH) <i>hnl</i>			\$ 226.50
	Rear Panel <i>Destroyed</i>			\$ 526.70
	Rear Panel Garnish <i>hnl</i>			\$ 57.70
	Rear Panel Lower Panel <i>Destroyed</i>			\$ 495.50
	Spare Tyre Holder <i>broken</i> <i>hnl</i>			\$ 248.00
	Spare Tyre Panel <i>Destroyed</i>			\$ 852.80
	Spare Tyre Panel Cushion <i>hnl</i>			\$ 209.05
	Rear Towing Hook <i>hnl</i>			\$ 94.60
	Member Assy- Rear Floor Centre <i>hnl</i>			\$ 570.40
	Panel Assy-Rear Floor Side (RH) <i>hnl</i>			\$ 90.10
	Exhaust Pipe Insulator <i>hnl</i>		\$ 58.55	\$ 117.10
	Exhaust Silencer <i>o/s</i> <i>Destroyed</i> <i>hnl</i>		\$ 967.70	\$ 1,935.40
	Exhaust Pipe Hanger <i>hnl</i>		\$ 58.55	\$ 117.10
	Exhaust Pipe Centre <i>hnl</i>			\$ 730.10
	Rear Fender With Housing (RH) <i>Destroyed</i>			\$ 4,736.80
	Rear Fender Inner Lining (RH) <i>hnl</i>			\$ 169.30
	Rear Fender Air-Duct <i>hnl</i>			\$ 51.60
	Rear Fender Trim Board (RH) <i>form</i>			\$ 188.75
	Rear Windscreen Moulding <i>hnl</i>			\$ 28.30
			10252.75	
			8202.22	
	SUB TOTAL			\$ 17,216.30
	LESS 20%			\$ 3,443.26
	DISCOUNTED TOTAL			\$ 13,773.04




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS/SMO19020666/Dyd3n2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date : 10-01-2020	
			Code : INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLX 7552J	Veh. Inspected	SHC 8407Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1905432/AGC	Excess (\$)	0.00	
Assign From	YONG KANG MELVIN	Assign Date	21/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMGU075469	Colour	BLUE	
Odometer	606023	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/11/2019	Inspection Date	21/11/2019	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8407Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID	BENT	2,174.90	2,174.90
1	BOOT LID RUBBER	SERVICEABLE	96.50	-
1	BOOT LID LOCK UPPER	NOT NECESSARY	102.60	-
1	BOOT LID LOCK LOWER	NOT NECESSARY	31.70	-
1	BOOT LID "H" EMBLEM	NECESSARY	28.70	28.70
1	BOOT LID CRDI PLATE	NECESSARY	27.90	27.90
1	BOOT LID LAMP (RH)	CRACKED	565.60	565.60
1	BOOT LID TRIMBOARD	NOT NECESSARY	116.40	-
10	BOOT LID TRIMBOARD CLIPS	NOT NECESSARY	11.00	-
1	BOOTLID MOULDING	NOT NECESSARY	85.00	-
1	BOOTLID I40 EMBLEM	NOT NECESSARY	27.90	-
1	BOOTLID LOWER GARNISH	NOT NECESSARY	227.90	-
1	REAR BUMPER	TORN	553.00	553.00
1	REAR BUMPER REINFORCEMENT	CRACKED	428.40	428.40
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30	O/S BENT / N/S NOT NECESSARY	160.60	80.30
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER BRACKET RH	NOT NECESSARY	35.60	-
1	REAR BUMPER SPONGE	TORN	118.40	118.40
1	REAR BUMPER UNDER COVER	DISTORTED / CUT	228.00	228.00
1	REAR BUMPER REFLECTOR LAMP (RH)	NOT NECESSARY	30.60	-
1	TAIL LAMP (RH)	MOUNTING CRACKED	697.80	697.80
1	TAIL LAMP QUARTER PANEL (RH)	NOT NECESSARY	226.50	-
1	REAR PANEL	DENTED	526.70	526.70
1	REAR PANEL GARNISH	NOT NECESSARY	57.70	-
1	REAR PANEL LOWER PANEL	DENTED	495.50	495.50
1	SPARE TYRE HOLDER	BROKEN / BENT	248.00	248.00
1	SPARE TYRE PANEL	DENTED	852.80	852.80
1	SPARE TYRE PANEL CUSHION	NOT NECESSARY	209.05	-
1	REAR TOWING HOOK	NOT NECESSARY	94.60	-

Report Ref No. CS/SMO19020666/Dyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	MEMBER ASSY-REAR FLOOR CENTRE	NOT NECESSARY	570.40	-
1	PANEL ASSY-REAR FLOOR SIDE (RH)	NOT NECESSARY	90.10	-
2	EXHAUST PIPE INSULATOR @\$58.55	NOT NECESSARY	117.10	-
2	EXHAUST SILENCER @\$967.70	O/S DENTED / N/S NOT NECESSARY	1,935.40	967.70
2	EXHAUST PIPE HANGER @\$58.55	NOT NECESSARY	117.10	-
1	EXHAUST PIPE CENTRE	NOT NECESSARY	730.10	-
1	REAR FENDER (RH)	DENTED	4,736.80	2,020.00
1	REAR FENDER INNER LINING (RH)	NOT NECESSARY	169.30	-
1	REAR FENDER AIR-DUCT	NOT NECESSARY	51.60	-
1	REAR FENDER TRIM BOARD (RH)	TORN	188.75	188.75
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
	LESS 20% DISCOUNT		-3,443.26	-2,050.55
			13,773.04	8,202.20
	SPECIAL NETT ITEMS			
1	BOOT LID COMFORT LOGO & TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	BOOT LID ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
			611.70	611.70
	LABOUR			
	PANEL BEATING.		2,000.00	800.00
	SPRAY PAINTING CHARGE.		1,500.00	800.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		100.00	40.00
	REAR CHASSIS ALIGNMENT CHARGE.	NOT NECESSARY	400.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00

Report Ref No. CS/SMO19020666/Dyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	REMOVE/REFIX EXHAUST PIPE.		300.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
			5,370.00	1,930.00
	GRAND TOTAL		19,754.74	10,743.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,550.00

Report Ref No. CS/SMO19020666/Dyd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.