



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 8517D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT (N)	BADLY DENTED	1,617.50	1,617.50
1	SET REAR BOOT GLASS MOULDING (N)	NECESSARY	49.50	49.50
1	REAR BOOT NISSAN LOGO (N)	NECESSARY	59.70	59.70
1	REAR BOOT X-TRAIL WORDING (N)	NECESSARY	95.70	95.70
1	REAR BOOT OUTER CHROME (N)	SCRATCHED / CRACKED	264.00	264.00
1	REAR BOOT WIPER MOTOR (N)	NOT NECESSARY	516.50	-
1	REAR BOOT TOP LOCK (N)	NOT NECESSARY	214.80	-
1	REAR BOOT BOTTOM LOCK (N)	NOT NECESSARY	38.40	-
1	TAILLAMP ASSY - RH (N)	NOT NECESSARY	329.70	-
1	REAR BUMPER (N)	TO REPAIR SEE LABOUR	660.60	-
10	REAR BUMPER CLIPS @ \$4.40 (N)	NOT NECESSARY	44.00	-
1	REAR BUMPER SIDE HOLDER - LH (N)	NOT NECESSARY	16.90	-
1	REAR BUMPER SIDE HOLDER - RH (N)	NOT NECESSARY	16.90	-
	LESS 10% DISCOUNT		-392.42	-208.64
			3,531.78	1,877.76
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE LAMP - LH (SN)	NOT NECESSARY	89.60	-
1	REAR NUMBER PLATE LAMP - RH (SN)	NOT NECESSARY	89.60	-
1	SPONGE TAPE (SN)	NECESSARY	20.00	20.00
2	SEALANT @ \$20.00 (SN)	NECESSARY	40.00	40.00
1	REAR BUMPER SENSOR (SN)	NOT NECESSARY	220.00	-
			459.20	60.00
<u>LABOUR</u>				
	TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		750.00	400.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		800.00	600.00
	TO CHECK WIRING.		20.00	20.00
	TO REMOVE, REFIT REAR BOOT GLASS.		120.00	120.00
	TO TUFF-KOTE.		50.00	30.00

Report Ref No. CC4/LPC19020668/Uda3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REFIT REAR GARNISH.		80.00	80.00
			1,820.00	1,250.00
GRAND TOTAL			5,810.98	3,187.76
RECOMMENDED COST OF REPAIR SUM				2,800.00

Report Ref No. CC4/LPC19020668/Uda3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.