

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
 GST:201006949C RCB NO:201006949C

NOT Authorised
 24/11/20
 31/1/20
 Take photo After rep
 4 hrs.

M/S : SUMITHRA RAVISHANKER
 BLK 115 EDGEFIELD PLAINS #02-348
 SINGAPORE 820115

Estimate No: EST1505468
 Date: 14 Nov 2019
 Policy No: GA103288
 Veh Reg No: SGG8517D
 Make/Model: NISSAN X-TRAIL 2.5A
 Chassis No: JN1TBNT30Z0104842
 Engine No: QR25348908A
 Reg. Date: 24/05/2006

ATTN: LONPAC
 Your Ref No: TP 1119-5752
 Claim Type: Third Party
 Accident Date: 14/11/2019
 TP Veh Reg No: YN 6626 K

Estimate Repair Cost to Vehicle No :SGG8517D

Description	U/Price	Quantity	Price SS	Amount SS
Net Price				
1 REAR BOOT	1,617.500	1 PCS	1,617.50	
2 REAR BOOT GLASS MOULDING	49.5000	1 SET	49.50	
3 REAR BOOT NISSAN LOGO	59.7000	1 PCS	59.70	
4 REAR BOOT X-TRAIL WORDING	95.7000	1 PCS	95.70	
5 REAR BOOT OUTER CHROME	264.0000	1 PCS	264.00	
6 REAR BOOT WIPER MOTOR	516.5000	1 PCS	516.50	
7 REAR BOOT TOP LOCK	214.8000	1 PC	214.80	
8 REAR BOOT BOTTOM LOCK	38.4000	1 PC	38.40	
9 TAILLAMP ASSY - RH	329.7000	1 PC	329.70	
10 REAR BUMPER	660.6000	1 PC	660.60	
11 REAR BUMPER CLIPS	4.4000	10 PC	44.00	
12 REAR BUMPER SIDE HOLDER - LH	16.9000	1 PCS	16.90	
13 REAR BUMPER SIDE HOLDER - RH	16.9000	1 PCS	16.90	
			3,924.20	
		Less 10%	392.42	3,531.78
Special Net				
14 REAR NUMBER PLATE LAMP - LH	89.6000	1 PC	89.60	
15 REAR NUMBER PLATE LAMP - RH	89.6000	1 PC	89.60	
16 SPONGE TAPE	20.0000	1 PCS	20.00	
17 SEALANT	20.0000	2 PC	40.00	
18 REAR BUMPER SENSOR	220.0000	1 PC	220.00	
			459.20	459.20
Labour				
19 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	750.0000	1 JOB	750.00	
20 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.0000	1 JOB	800.00	
21 TO CHECK WIRING	20.0000	1 JOB	20.00	
22 TO REMOVE, REFIT REAR BOOT GLASS	120.0000	1 PC	120.00	
23 TO TUFF-KOTE	50.0000	1 JOB	50.00	
24 TO REMOVE, REFIT REAR GARNISH	80.0000	1 JOB	80.00	
			1,820.00	1,820.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

M/S : SUMITHRA RAVISHANKER
BLK 115 EDGEFIELD PLAINS #02-348
SINGAPORE 820115

Estimate No: **EST1505468**
Date: 14 Nov 2019
Policy No: GA103288
Veh Reg No: **SGG8517D**
Make/Model: NISSAN X-TRAIL 2.5A
Chassis No: JN1TBNT30Z0104842
Engine No: QR25348908A
Reg. Date: 24/05/2006

ATTN: LONPAC
Your Ref No: TP 1119-5752
Claim Type: Third Party
Accident Date: 14/11/2019
TP Veh Reg No: YN 6626 K

Estimate Repair Cost to Vehicle No :SGG8517D

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 5,810.98
			Add GST @ 7%	406.77
			Total Amount Payable	<u>S\$ 6,217.75</u>

TOTAL: SINGAPORE DOLLAR SIX THOUSAND TWO HUNDRED SEVENTEEN AND CENTS SEVENTY FIVE ONLY

For Progressive Car Care Pte Ltd


LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


AUTHORISED SIGNATURE