



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

19 December 2019

QUOT201912-000024
HHTPCLAIMS19-225

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET, #04-00 / #05-00
IOB BUILDING
SINGAPORE 049711

Attn: Motor Claims Department

ACCIDENT INVOLVING SMM2420K & SHC1982Z ON 06/11/2019 ALONG STEVENS ROAD AT ABOUT 2035 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No. : SMM2420K
Vehicle Make : TOYOTA
Vehicle Model : C-HR HYBRID 1.8S CVT
Vehicle Chassis No. : ZYX102173763
Policy No. : 5087272209-03
Date of Accident : 06/11/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Door (LH) X R		\$ 1,168.30
2	1	Front Door Tape (LH) X		\$ 82.40
3	1	Front Door Weather Strip (LH) X		\$ 232.10
4	1	Front Door Garnish (LH) / SCH		\$ 380.00
5	1	Rear Door (LH) ✓ PR		\$ 1,084.90
6	1	Rear Door Garnish (LH) / SCH.		\$ 321.70
7	1	Rear Door Tape (LH) ✓ Nec		\$ 81.70
8	1	Rear Door Weather Strip (LH) ?		\$ 245.70
9	1	Rear Fender Arch Garnish (LH) / SCH.		\$ 278.50
10	1	Side Skirt (LH) / SCH		\$ 529.10
11	10	Side Skirt Clip / Nec.	\$ 5.10	\$ 51.00
				\$ 4,455.40
Less 20%				\$ 891.08
				\$ 3,564.32
12	1	Rear Rim (RH) / Local Repair	NETT	\$ 350.00 50

To dismantle & change Front LH door, Rear LH door, LH side skirt, knocking & pull straight all area affected by accident / Rim Repair \$ 600.00 400

To perform wire checking \$ 20.00 /

To dismantle & refit Front LH door, Rear LH door mechanism and fitting to new door \$ 120.00 60

To dismantle & refit LH Rear rim & balancing \$ 40.00 20

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

25D SUNGAI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

19 December 2019

QUOT201912-000024

HHTPCLAIMS19-225

ACCIDENT INVOLVING SMM2420K & SHC1982Z ON 06/11/2019 ALONG STEVENS ROAD AT ABOUT 2035 HOURS

Estimate Repair List for vehicle SMM2420K - TOYOTA C-HR HYBRID 1.8S CVT

S/N	Quantity	Description	Unit Price S\$	Amount S\$
		To spray Front LH door, Rear LH door and all area affected by accident		\$ 600.00 400
				\$ 5,294.32
			7% GST	\$ 370.60
			Total	\$ 5,664.92

Repair day - 4 days.

P/P Repair

& Before spray photo

Sun Pm (Lkk)

27/12/2019

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Authorised by Claims Dept