

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 20177

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1389/2019/NS
Date : 21-Nov-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Ng Jin Puay (Huang Renpei)
Address : Blk 13 Fernvale Lane
#16-08
Singapore 797496
Telephone : HP +65 96411899
Type of Claim : Own Damage Claims
Policy No. : 1900086751
Vehicle No : **SJK 3239 H**
Model Code : Audi Q2 TFSI S TRONIC
Model / Year : Apr-19
Engine No : CHZ C28340
Chassis No : WAUZZZGA3KA044570
Mileage : 12108KM
Date In : 21-Nov-19
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Nov-19
Place of Accident : South BridGE Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJK 3239 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00	✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	✓
3	To dislodge and reinstall rear wire harness for tail lights, use and relay trays battery manager, electrical and audio equipment.	S/N \$ 480.00	✓
4	To dismantle rear bumper and rear lid. Inspect lhs rear fender for damages. Cut out and weld rear outer and inner rear cross panels. Renew rear bumper and rear lid, align to position. Re-organise rear crash management components. Reinstall all parts removed.	\$ 4,800.00	500.
SUB TOTAL LABOUR CHARGES		: \$ 5,840.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJK 3239 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
5	To respray rear bumper, rear lid, lhs rear fender and end panelling. To carry out stone chip treatment.	\$ 3,800.00	400 1650
6	To renew rear windscreen.	S/N \$ 480.00	?
7	To install solar film on rear windscreen.	S/N 400	?
8	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,712.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3239 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER / <i>EL.</i>	\$	1,074.00
2	REAR BUMPER FIXING PARTS ?	\$	314.00
3	REAR BUMPER SPOILER - LH / <i>TN</i>	\$	259.00
4	REAR LIGHT REFLECTOR - LH / RH <i>< LH - at RH x N/A</i>	\$	54.00
5	REAR PARKING AID SENSOR - INNER ?	2 \$	462.00
6	REAR BUMPER CARRIER / <i>BT.</i>	\$	501.00
7	REAR BUMPER HOLDING STRAP - LH / RH ?	2 \$	24.00
8	REAR BUMPER GUIDE SECTION - LH / RH <i>< LH - RH x</i>	2 \$	98.00
9	REAR WHEEL COVER - LH / RH / <i>ACC.</i>	2 \$	312.00
10	REAR LID ?	\$	2,195.00
11	REAR LID ATTACHMENT PARTS ?	\$	109.00
12	AUDI EMBLEM / <i>4 m/c.</i>	\$	113.00
13	Q2 INSCRIPTION /	\$	87.00
14	SPOILER FIXING PARTS ?	\$	121.00
15	FOAM STRIPS SET ?	\$	121.00
16	REAR WINDSCREEN ?	\$	711.00
17	PRIMER ?	\$	19.00
18	TAIL LIGHT - LH / <i>CRA.</i>	\$	1,207.00
19	TAIL LIGHT TRIM - LH ?	\$	27.00
20	REAR VENT TRIM ?	\$	30.00
SUB TOTAL SPARE PARTS		\$	7,838.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJK 3239 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR CROSS PANEL ?	\$	224.00
22	REAR CROSS PANEL REINFORCEMENT ?	\$	669.00
23	REAR CROSS PANEL CONNECTING PLATE - LH ?	\$	37.00
24	REAR SILENCER ?	\$	653.00
25	REAR SILENCER DUAL CLIP X	\$	55.00
26	REAR WINDSCREEN SEALANT ?	S/N \$	200.00
27	ACRYLIC SEALANT ?	S/N \$	180.00
28	CAVITY WAX ?	S/N \$	140.00
29	STONE CHIP ?	S/N \$	180.00
30	SUNDRIES ?	\$	500.00

TOTAL SPARE PARTS	:	\$ 10,676.00
TOTAL LABOUR CHARGES	:	\$ 10,712.00
GRAND TOTAL	:	\$ 21,388.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Not Authorised.
Gino Quay - 82880282
6 Days.
before paint photos.

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant