

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 16:32

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014917 Date : 27/02/2020 Order : SJK3239H Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SJK3239H (V 41653) Regn Date: 10/04/2019 Mileage: 12109 WIP No.: 20177

Model: Q2 1.0 TFSI S tronic GABANG Chassis: WAUZZZGA3KA044570 Engine: CHZ C28340 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	280.00	1.00	280.00
S	BODYWORK	M: TO DISMANTLE REAR BUMPER AND REAR LID. INSPECT LHS REAR FENDER FOR DAMAGES. CUT OUT AND WELD REAR OUTER AND INNER REAR CROSS PANELS.RENEW REAR BUMPER AND ALIGN TO POSITION.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER,REAR LID AND LHS REAR FENDER.TO CARRY OUT STONE CHIP TREATMENT	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M: TO REPAIR LHS REAR FENDER	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY END PANELLING	550.00	1.00	550.00
X	A81A807521B 4W3	SPOILER(LAST) Less 020%	1.00	259.00	207.20
X	A81A945105	REFLECTOR Less 020%	1.00	26.90	21.52
X	A81A807253	GUIDE(LAST) Less 020%	1.00	48.40	38.72
X	A81A853817 4W3	COVER Less 020%	1.00	155.50	124.40
X	A81A853818 4W3	COVER Less 020%	1.00	155.50	124.40
X	A8V0853742 2ZZ	AUDI SIGN Less 020%	1.00	112.50	90.00
X	A81A853741A 2ZZ	INSCRIPTION 'Q2' Less 020%	1.00	86.60	69.28
X	A81A945091C	TAILLIGHT(LAST) Less 020%	1.00	1207.00	965.60
X	A81A807067A GRU	COVER Less 020%	1.00	1074.00	859.20
X	A81A807309A	BRACKET BORROW Less 020%	1.00	500.50	400.40

Parts 2,900.72
Labour 0.00
Sublet 3,672.00
Menus 0.00
Lubricant 0.00

Sub-Total 5,772.72

7% GST 404.09

Grand Total 6,176.81



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SJK 3239 H

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1389/2019/TG
04 Dec 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

1 total pages

Make & Model : Audi Q2 1.0 TFSI S TRONIC
Vehicle Chassis No. : WAUZZZGA3KA044570
Vehicle Regn No. : SJK 3239 H
Vehicle Mileage : 12109 KM
Vehicle Owner : Ms.Ng Jin Puay (Huang RenPei)
Certificate No : 1900086751
Own Damage Excess : \$ 856.00 (Inclusive GST)
Accident Date : 21/11/2019
Place : South Bridge Road
Repair Cost : SS 6176.81
WIP No. : 20177
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :