

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

21, NOV 2019

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
AIG Building
#07-16 S 079120

*Not Withheld
11 Days @ ?
Pursuing After Paint
4 days*

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: GBF8103D
Accident involving vehicle no: SKX4028M/GBF8103D
DOA: 19/11/2019 AT Serangoon North Avenue 4 carpark

Dear officer incharge
Re: Estimate cost of repair for vehicle no: SKX4028M
To supply--

Description	Qty	Amount
Front fender,Lh	1 <i>R</i>	773.40 ✓
Front wheel bearing	1	119.43 7
Front wheel bearing hup	1	179.90 7
Front absorber,Lh	1	425.50 7
Linkage,Lh	1	178.70 7
Lower arm	1	459.33 7
Rim,Lh	1 <i>m</i>	280.00 250m
Headlamo	1 <i>L</i>	1,050.00 X
Parts		3,466.26
Parts less 25%		866.57
		2,599.69
<i>Rt bumper</i>	<i>cm</i> ✓	

To remove damaged parts and attachments.
Repair/reshape dented areas
Straighten front pillar
Replace/align above parts into position.
To spray paint
To remove/replace undercarriage parts
Redo wheel alignment

950.00 *400*
800.00 *400*
350.00 *7*
80.00 *60*

4,779.69

LKK Auto Consultants hence notify --
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: