

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTLonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555**Our File No:** CS/LPC19020700/BYD3S2**Date:** 08/04/2020**REFERENCE**Insured/Claimant: WILLIAM SECURE SOLUTIONS PTE LTD Policy No: Z19VC05003605
Date of Loss: 11/11/2019 Nature of Claim: OD Claim No: 19/19/19/VC05/022634**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBH9214A**
Make & Model: RENAULT KANGOO, 1.5 D dCi (M) Engine No: K9KF647D087436
Reg. Date: 29/10/2018 (Man. Year: 2018) Chassis No: VF1FWT2H359570077
Colour: White Odometer: 20396 km
Engine Capacity: 1461 cc
Market Value/New Car Price: S\$62,000.00
Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:**CONDITION OF TYRES**Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Continental 5 mm Rear Left Side: Continental 5 mm
Front Right Side: Continental 5 mm Rear Right Side: Continental 5 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,010.55	5,010.55	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	1,860.00	370.00	16.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,240.55	6,870.55	370.00	5.11
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	7,240.55	6,270.55	970.00	13.40
+ GST 7.00/7.00% (S\$)	506.84	438.94	67.90	13.40
Nett Amount (S\$)	7,747.39	6,709.49	1,037.90	13.40

INSPECTIONDate of Assignment: 22/11/2019 Present Location: Falcon-Air Auto Services Pte Ltd (Sin Ming)
Date Inspected: 26/11/2019 Inspected At: Falcon-Air Auto Services Pte Ltd (Sin Ming)
176 Sin Ming Drive #01-06, Sin Ming Autocare
Singapore 575721
Estimated Period of Repair: 7.0 days**Adjuster:** Lim Teow Guan**Manager:** YVONNE WONG YIN CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 08 Apr 2020)	
Parts:	N/A	RENAULT KANGOO 1.5 D dCi (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH9214A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*LH Front Door Protector (WCP)	Cut	182.00 F	*182.00 F	
2	1		*LH Front Door Company Sticker	Necessary	40.00 FS	*40.00 FS	
3	1		*LH Rear Door (WCP)	Dented	1,950.00 F	*1,950.00 F	
4	1		*LH Rear Door Protector (WCP)	Cut	160.00 F	*160.00 F	
5	1		*LH Rear Door Glass Moulding (WCP)	Necessary	205.00 F	*205.00 F	
6	1		*Glass Sealant	Necessary	40.00 FS	*40.00 FS	
7	1		*LH Rear Fender (WCP)	Dented	1,480.00 F	*1,480.00 F	
8	1		*LH Rear Fender Protector Moulding (WCP)	Missing	180.00 F	*180.00 F	
9	1		*LH Rear Rim Cover - 15	Cut	150.00 FS	*150.00 FS	
					Sub Total (\$\$)	4,387.00	4,387.00
					+ Margin on L,N Items 15.00/15.00% (\$\$)	623.55	623.55
					Total Parts (\$\$)	5,010.55	5,010.55

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To remove/refit LH rear door glass	New	80.00	80.00
2	To remove/refit LH rear door parts and mechanism	New	100.00	80.00
3	To cut out/re-weld LH rear fender, straighten LH front door and LH rocker panel including replacement of parts	New	950.00	800.00
4	Spray paint on LH front door, LH rear door, LH rear fender, LH rocker panel	New	1,100.00	900.00
			Gross Labour Cost (S\$)	2,230.00
				1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >