

ASS. REC. BY:

REF:

MS419020706/RIvd302

Special Instruction:

Sympt: RASU

Merimen

ASSIGNMENT (Office)

From (Person): Richard Ang

of

M81C1

Date/Time: 22/11/19 @ 2:43pm

Estimate Cost:

Bill to:

OD IP/ NS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 1638K

Insured:

at Workshop n/s

Borneo Motor

Tel:

9336 6875.

of

2 Pandan Crescent

Policy No:

24127060AT2

Claim No:

311884

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

18/11/2019

CA / REV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:43pm @ 22/11/19

Person Contacted:

Shashi

Vehicle IN/OUT

Date/Time

Action/Instruction

Follow up?

✓ pls Revert with market value and Repair limit.

SJS 1638K - X

25/11/19

Revert via merimen

27/11/19

Rece approved \$35000 from Chen How by merimen

27/11/19

Informed Shashi c/A repair cost not exceeding \$35000 & \$500 by email

ASSIGNMENT

From: _____ Date: 22/11/19 Veh No: SJS 1638K Yr Regn: 2019 / MAY

Estimated Cost: _____ Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV Make: TOYOTA Vios 1.5E A c.c. 1496

To Inspect Vehicle No: SJS 1638K Colour: Grey A/C: Insured / Std / NI / NA

at Workshop m/s: Borneo Motor Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

of: 2 Penden Crescent Eng/No: _____

Insured: _____ C/No: MR 2B 23F 3301176341

Policy No: _____ Gen. Cond: Good / Fair / Poor / Burnt

Claims No: _____ Steering: Order / Jammed / Leaked / Burnt or _____

Sum Insured: _____ Excess: \$500.00 Brake: Order / Jammed / Leaked / Burnt or _____

(Client's Record) Make of Veh: Sashi Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 185/60R15 R: _____

(Policy Condition) Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 74K \$70K BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

IDAC Accident Rpt: _____ Consistent? : Yes or No 27/11/19 Front R/Bal. 6 mm Rear R/Bal. 6 mm

GIA / PR Seen: _____ Consistent? : Yes or No 27/11/19 L/Bal. 6 mm L/Bal. 6 mm


Est. Repairs: _____ days Res.: Yes or No 27/11/19 D.O.A. 18/11/19 D.O.I. 22/11/19

Lum Sum: _____ % 3 Val.: Yes or No 27/11/19 Survey held at: BORNEO MOTOR

CA / REV / REP. / 24 HRS Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or _____

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
	<u>Pls Revert with market value and Repair limit.</u>
<u>17/12/19</u>	<u>@4:30pm Shashi said vehicle still under repair</u>
<u>20/12/19</u>	<u>Confirmed \$35000 by email (Ref 8235.99, 1990)</u>
	<u>20/12/2019</u>

Date/Time, File Pass to? ☐ : Prel. Report

i) ☐ : Final Report

Date/Time, File Return to? 20/12 - typist

Report Format: merimen

Lump Sum / L.B.: 35000/-

Days Of Repair: 12

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

☐ : Wheel end (\$)

Survey Fee: 300

Transportation: 5 + RS 21

Photos: 11

Other: _____

TOTAL: 311

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Nov 2019		22 Nov 2019 14:43 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [\[Created by insurer\]](#)

Insured:	TOMY PRINTING COMPANY, Co. Reg. No.: 33129300E		
Vehicle Reg. No.:	SJS1638K	Date of Loss:	16/11/2019 12:00 - :59
Claim Type:	OD / 611884	Policy/Cover Note No.:	29127060AT2 (Comprehensive) Coverage: 30/05/2019 - 29/05/2020
		Excess:	S\$500.00
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Richard Ang Wei Guang - 6594 2560]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/11/2019]		
Driver/Custodian:	ONG CHAI PENG (47 / Female) , NRIC: S7240290A, Tel: +6597860991 Email: dannusong@gmail.com		
Adj Asg. Remarks:	Car in, please arrange survey ASAP. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please revert with Market Value and Repair Limit (if applicable).		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***SJS1638K (611884)**
OD
Nov 18 2019 12:00PM
[TOMY PRINTING COMPANY]
Borneo Motors (S) Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 19/12/2019 16:50 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$35000.00) - SJS1638K - Claim Handler: Richard Ang Wei Guang

Approved:35000.00:Repair cap at \$35000.00

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Richard Ang Wei Guang	Date: 19 Dec 2019
<u>Preliminary Advice</u>	

Vehicle No	: SJS1638K	Accident Date	: 18/11/2019
Make	: TOYOTA VIOS	Policy No.	: 29127060AT2
Assignment Date	: 22/11/2019	Excess	: S\$500.00
Date of Inspection	: 22/11/2019	Est. Duration of Repair	: 12.00
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	57,374.70	(incl.supplementary \$5372.17)
Revised Amount	:S\$	35,000.00	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	35,000.00	(incl.supplementary \$5372.17)
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	38,096.00
Salvage Value	:S\$	
Margin for Repair	:S\$	35,904.00

Remarks

(X)	The vehicle is economical for repair.
()	The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 27 November 2019 12:30 PM
To: Shashitharan PTCBC; Rasul (LKKAUTO); SUR
Subject: RE: SJS 1638K DOA : 18/11/19 (MSIG OD)

Dear Shashi,

As instructed by our client , please proceed to repair the **insured vehicle SJS 1638K ,repair cost Not exceeding \$35,000/-(all-inclusive of check items and before excess and GST) or whichever lower (Excess \$500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shashitharan PTCBC <Shashitharan@borneomotors.com.sg>
Sent: Wednesday, 27 November 2019 8:33 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SJS 1638K DOA : 18/11/19 (MSIG OD)

Hi we accept the offer

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, November 26, 2019 10:14 AM
To: Shashitharan PTCBC; Rasul (LKKAUTO); SUR
Subject: RE: SJS 1638K DOA : 18/11/19 (MSIG OD)

CAUTION: This email originated from outside of the organization (Inchcape). Do not click links or open attachments unless you recognise the sender and know the content is safe.

Dear Shashi,

MSIG proposed offer repair cost **\$35,000/- (all-inclusive of check items and before excess and GST).**

Please revert with a confirmation of acceptance.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shashitharan PTCBC <Shashitharan@borneomotors.com.sg>

Sent: Monday, 25 November 2019 11:01 AM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: RE: SJS 1638K DOA : 18/11/19

Noted will check and get back to you .

Thanks

Shashi

Motor Claim Assessor

D:6631 1864 | M: 9336 6875 | F:6773 3094

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]

Sent: Monday, November 25, 2019 9:02 AM

To: Shashitharan PTCBC

Cc: Veron Chen (LKKAuto)

Subject: SJS 1638K DOA : 18/11/19

CAUTION: This email originated from outside of the organization (Inchcape). Do not click links or open attachments unless you recognise the sender and know the content is safe.

Hi Shashi,

Take note that this vehicle repair limit is 35K

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

View Received Message

This mail is associated with :

***SJS1638K (611884)**

OD

Nov 18 2019 12:00PM

[TOMY PRINTING COMPANY]

Borneo Motors (S) Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 27/11/2019 12:06 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$35000.00) - SJS1638K - Claim Handler: Richard Ang Wei Guang

Approved:35000.00:Repair cap at \$35000.00

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 27 Nov 2019

Preliminary Advice

Vehicle No	: SJS1638K	Accident Date	: 18/11/2019
Make	: TOYOTA VIOS	Policy No.	: 29127060AT2
Assignment Date	: 22/11/2019	Excess	: S\$500.00
Date of Inspection	: 22/11/2019	Est. Duration of Repair	: 12.00
Inspection At	BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	52,002.53
Revised Amount	:S\$	30,697.45
Check Items (Estimated)	:S\$	15,169.27
Total	:S\$	45,866.72

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	38,096.00
Salvage Value	:S\$	
Margin for Repair	:S\$	35,904.00

Remarks

(X) The vehicle is economical for repair.

(X) Repairer accept repair cost **\$35,000/- (all-inclusive of check items and before excess and GST)**.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 25 Nov 2019

Preliminary Advice

Vehicle No	: SJS1638K	Accident Date	: 18/11/2019
Make	: TOYOTA VIOS	Policy No.	: 29127060AT2
Assignment Date	: 22/11/2019	Excess	: S\$500.00
Date of Inspection	: 22/11/2019	Est. Duration of Repair	: 12.00
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	52,002.53
Revised Amount	:S\$	30,697.45
Check Items (Estimated)	:S\$	15,169.27
Total	:S\$	45,866.72

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	74,000.00
COE / PARF Rebate	:S\$	38,096.00
Salvage Value	:S\$	
Margin for Repair	:S\$	35,904.00

Remarks

() The vehicle is economical/not economical for repair.

(X) Kindly advice on offer repair cost to repairer. Please note the margin repair cost is \$35,904.00

Calvin 25/11/19

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	300E
Vehicle Details	
Vehicle No.:	5J51638K
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5 E (AUTO)
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	2NRX438843
Chassis No.:	MR2B23F3301176341
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,788.00
Original Registration Date:	30 May 2019
First Registration Date:	30 May 2019
Transfer Count:	0
Actual ARF Paid:	\$13,788.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2029
PARF Rebate Amount:	\$10,341.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$29,159.00
COE Rebate Amount:	\$27,755.00
Total Rebate Amount:	\$38,096.00

The information contained herein is correct as at 22 Nov 2019

OK

74,000
38,096

35904

(35k)



toyota vios Min Price No Max Depreciation Vehicle Type Category

Advanced Search

Home » New Cars » toyota vios Search Results

toyota vios Search Results (1 vehicles)

Sort by Most Popular

15 results/page

Car Model	Price	Dealer	Built in	User Rating
Toyota Vios		Borhoo Motors	Thailand	
1.5 E Grade (A)	\$83,988 \$7,700 /yr	• 17.2km/l 106bhp 7-speed (A) CVT		4 User Reviews
1.5 G Grade (A)	\$89,988 \$8,300 /yr	• 17.2km/l 106bhp 7-speed (A) CVT		Promotion Editor's Review

Car Model	Price	Dealer	Built in	User Rating

15 results/page

3 result(s) for **toyota vios** models no longer being sold by local distributors
View all [past Toyota cars](#)



Toyota Vios
(2013-2017)



Toyota Vios
(2007-2013)



Toyota Vios
(2003-2007)



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.4
Company Ownership

Toyota DriveElite 360
Comprehensive

Certificate No. A 29127060 AT2

Excess : SGD500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle

SJS1638K

2. Name of Policyholder

Tomy Printing Company

3. Effective Date of the Commencement of Insurance for the purposes of the Act

30/05/2019

4. Date of Expiry of Insurance

29/05/2020

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT BORNEO MOTORS (S) PTE LTD OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers


for Chief Executive Officer

TYPE OF CLAIM: ☒ DOD ☐ OD/UL ☐ DS

MCA:

Shashy

MOTOR ACCIDENT REPORT

Date Of Report: 17/11/2019 Time: Date Of Accident: 18/11/19 Time: 1200 hrs
Exact Location Of Accident: PIE/TAS PKP/SS 1909
Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SJS 1638K Co. Reg. No (for Co. Vehicle)/NRIC/PP/FIN No: 33129300E
Name Of Registered Owner: Tony PRINTING CO
Mobile Number: 97860971 Alternative No: Email Address: dannusory@gmail.com

Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model: VIOS
Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):
Are you claiming under your own insurance policy for repair to your vehicle? Yes ☒ Reporting Only ☐ Third Party ☐
Vehicle Category: Private Car ☐ Commercial Vehicle ☒ Others ☐

Insurance Company

Name of Insurance Company:
Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐
Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: A29127066 AT2

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: Ong Chee Hong NRIC/ Passport / FIN No: S7240290A
Date Of Birth: 29/10/1972 Occupation: Indoor ☒ Outdoor ☐
Date Of Driving Pass: 23/2/1995 Gender: Male ☐ Female ☒
Mobile Number: 97860971 Fax No: Alternative No:
Address: Bk 605 Btj Rd #19-150 Postal Code:
Email Address: dannusory@gmail.com

Was driver an employee of the Insured's Company? Yes ☒ No ☐ State relationship of the driver with the insured:

Vehicle Registration Number of Driver's Own Vehicle (if applicable):

Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Front collision
Number of Passengers in the above vehicle (Including Driver): / If more than 2 Pax Please fill ANNEX B

PASSENGER 1

Name: Ong Chee Hong Gender: Male ☐ Female ☒
Weather Conditions: Clear ☒ Raining ☐ Others ☐ (if others, please state condition):
Road Surface: Wet ☐ Dry ☒ Others ☐ (if others, please state condition):
Was any body injured in the Accident? No ☒ Yes ☐
Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐
Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:
Number of vehicles involved in the accident: SDS 5588R
Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below
Witness Name: | Contact No.: | Email:
Was there any other vehicle or property damaged? No ☒ Yes ☐
Was there any video captured by Car Camera? No ☒ Yes ☐ Are accident scene photos available for attachment? No ☐ Yes ☒
Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):
Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):
I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: SDS 5588R Vehicle Make/Model/Colour: NISSAN QASHQAI
Details Of Properties Damage in Accident:
Vehicle Category:
Name of Driver: Chun How Yang
NRIC/Passport/FIN Number: S71064386 Contact Number: 9880 4965
Address: Postal Code:
Insurance Company Name:
Nature Of Damage: No. Of Passenger (Including Driver): 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/11/2017 at around 12:05pm I was driving my car on lane 3 of PIE towards Tuas after Amp Lekar exit. Suddenly veh SDS 5588R which was in front of me jarrs it brake I couldn't stop it in time while apply my brake and collided into its rear. No one was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

東米印刷公司



TOMY PRINTING CO.

Bik 20 #02-21 Woodlands Link Singapore 738733

Tel: 6753 5355 Fax: 6753 5055 Email: tomy@singnet.com.sg

Company & GST Reg. No: 33129300E

Date: 18 November 2019

To : Whom It Shall Concern

Dear Sir/ Madam,

RE : AUTHORISED DRIVER FOR COMPANY'S REGISTERED VEHICLE - SJS1638K

We hereby confirmed that Mdm Ong Chai Peng, NRIC no.: S7240290A whom currently under our employment as Sales & Marketing Executive, is the authorised driver under the company's registered vehicle SJS1638K.

Yours Faithfully,



S H Tan
General Manager

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037/ICCUA2	M/s Tomy Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97860391
	Document No 0	
	Document Date 22/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AXXENT	E1	NSP151R	30/05/2019	SJS1638K	0	50819 60D/SJS1638K/21111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3301176341	ZNRX438843	50	Rashitharan	---	0.00	---	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	B	BP-SUNDRY SUNDRIES POLICY NO.:A29127060AT2 ACC DATE:18/11/19 TOW IN:18/11/19 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:			100	50 100.00
2	B	BP-LAB2 CHECK WIRING AND REFOCUS HEADLAMP				✓ 162.00
3	L	BP-LPO SUPPLY REGN PLATE (PO#)				✓ 80.00
4	B	BP-MECH2 R/I AIRCOND PIPE VACUUM AND REGAS				✓ 324.00
5	B	BP-MECH2 REPL DASHBOARD				✓ 1296.00
6	B	BP-LAB2 R/I WHOLE INTERIOR TO FAC REPAIR				✓ 1180.80
7	B	BP-MECH2 REPL WHOLE WIRING HARNESS TO FAC REPAIR				1296 972 1296.00
8	B	BP-MECH2 REPL SEAT BEALT ASSY				✓ 648.00
9	B	BP-MECH2 RESET ECU UPON COMPLETION OF REPAIR				162 180.00
10	B	BP-MECH2 REPL AIRBAG ECU AND SENSOR AND RESET AIR BAG SYSTEM				✓ 648.00
11	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALLIGN ACC AFF AREA				✓ 3240 6480.00
12	B	BP-RES2 RESPRAY ACC AFF AREA				✓ 3717 5720.00
13	Z	BP-SLANT SUPPLY SEALANT (NETT)				100 160 200.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less Amount Due at Prejudice base

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 22/11/2019
TIME 10:16

Authorised by Register

Signature

Time

4135802

4135802

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Inchcape

Co-Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 7 Pandan Crescent
Singapore 129462
Tel no.: 6631 1198

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCJA2	M/s Tomy Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97860991
	Document No 0	
	Document Date 22/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEARXT	S1	NSP151R	30/05/2019	SJS1638K	0	50819 60D/SJS1638K/21111!
Chassis No	Engine No	Terms	Service Engineer	Vehicle in	Collected On		
MR2B23F3301176341	2NRX438843	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	1	S88300-0D530 AIR CON KIT (NEW VIOS 2016) ? x sue ? ✓ nw	1.00	3026.60		3026.60
15	2	SPC593-0D007 S1 LED FOG LAMP SET ? x sue	1.00	387.80		387.80
16	3	S12611-0Y110 COVER, ENGINE, NO.1 ? ✓ cm	1.00	205.30	25.00	153.97
17	4	S16400-0Y191 RADIATOR ASSY b1 ✓	1.00	2052.20	25.00	1539.15
18	5	S16523-0M050 CUSHION, RADIATOR SU NA X an	2.00	6.10	25.00	9.14
19	6	S16361-0M110 FAN ? x sue ? ✓ cm	1.00	241.20	25.00	180.90
20	7	S16711-0Y160 SHROUD, FAN ? ✓ cm	1.00	264.70	25.00	198.52
21	8	S16363-0Y050 MOTOR, COOLING FAN ? x sue	1.00	562.50	25.00	421.87
22	9	S16571-0Y101 HOSE, RADIATOR, NO.1 ? x sue	1.00	51.60	25.00	38.70
23	0	S90916-T2042 BELT, V-RIBBED ? x sue	1.00	147.80	25.00	110.85
24	1	T17167-0Y050 INSULATOR, EXHAUST ? x sue	1.00	103.70	25.00	77.77
25	2	T17168-0Y050 INSULATOR, EXHAUST ? x sue	1.00	103.70	25.00	77.77
26	3	S17700-0Y190 CLEANER ASSY, AIR W/ cm	1.00	1077.90	25.00	808.42
27	4	S17771-0Y080 BRACKET, AIR CLEANER ? x sue	1.00	30.30	25.00	22.72
28	5	S17751-0Y261 INLET, AIR CLEANER ? ✓ cm	1.00	69.90	25.00	52.42
29	6	S17882-0Y140 HOSE, AIR CLEANER, N de x sue	1.00	103.00	25.00	77.25
30	7	S81110-0DF00 HEADLAMP ASSY, RH bro ✓	1.00	1285.00	25.00	963.75
31	8	S81150-0DF00 HEADLAMP ASSY, LH bro ✓	1.00	1285.00	25.00	963.75
32	9	S82115-0U291 WIRE, ENGINE ROOM NA ? x sue	1.00	3378.70	25.00	2534.02
33	0	S82121-0DY51 WIRE, ENGINE ? x sue	1.00	2577.20	25.00	1932.90

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4135803

TO SECURITY GUARD

4135803

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 22/11/2019
TIME 10:16

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Co-Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
M&S Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 S&K Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	M/s Tomy Printing Company 29 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan
	Document No 0	Mobile: 97860991
	Document Date 22/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEXRMT	E1	NSP151R	30/05/2019	SJS1638K	0	50819 60D/SJS1638K/21111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3301176341	2NAX438843	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
34	1	S82140-0D130 WIRE ASSY, INSTRUMEN	1.00	19.00	25.00	14.25
35	2	S82661-52050 COVER, RELAY BLOCK	1.00	22.50	25.00	16.87
36	3	S82741-0D100 BLOCK, ENGINE ROOM	1.00	138.20	25.00	103.65
37	4	S82662-0D520 COVER, RELAY BLOCK	1.00	55.00	25.00	41.25
38	5	S84307-0D170 CABLE SUB-ASSY, SPIR	1.00	1077.90	25.00	808.42
39	6	S89175-0D060 BRACKET, AIR BAG SEN	1.00	30.30	25.00	22.72
40	7	S89173-09C00 SENSOR, AIR BAG, FR	1.00	374.60	25.00	280.95
41	8	S89170-0D810 SENSOR ASSY, AIR BAG	1.00	1203.80	25.00	902.85
42	9	S89831-02260 SENSOR, SIDE AIR BAG	2.00	691.00	25.00	1036.50
43	0	S85315-0D220 JAR ASSY, WINDSHIELD	1.00	145.80	25.00	109.35
44	1	S74431-0D210 TRAY, BATTERY	1.00	59.80	25.00	44.85
45	2	S74404-0D170 CLAMP SUB-ASSY, BATT	1.00	33.30	25.00	24.97
46	3	S63310-0DC20 AO HEADLINING ASSY, ROO	1.00	1827.20	25.00	1370.40
47	4	S55302-0D240 CO PANEL SUB-ASSY, INST	1.00	884.50	25.00	663.37
48	5	S73960-0D160 AIR BAG ASSY, INSTR	1.00	3883.10	25.00	2912.32
49	6	S45130-0D410 CO PAD ASSY, STEERING W	1.00	2867.40	25.00	2150.55
50	7	S52721-0D290 Moulding, FR BUMPER	1.00	72.40	25.00	54.30
51	8	S53112-0D540 GRILLE, RADIATOR, LW	1.00	269.50	25.00	202.12
52	9	S53113-0D020 GRILLE, RADIATOR, LW	1.00	90.90	25.00	68.17
53	0	S52119-0U932 COVER, FR BUMPER, L/	1.00	495.70	25.00	371.77

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle:	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4135804

TO SECURITY GUARD

4135804

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 22/11/2019
TIME 10:16

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Inchcape



Co-Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6531 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
M51G Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037/ICCUA2	M/s Tony Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97860991
	Document No 0	
	Document Date 22/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AXEUT	E1	NSP151R	30/05/2019	SJS1638K	0	50819 60D/SJS1638K/21111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3301176341	2NRX438843	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
54	1	S52127-0D480 COVER, FR BUMPER HOL	1.00	88.50	25.00	66.37
55	2	S52128-0D430 COVER, FR BUMPER HOL	1.00	88.50	25.00	66.37
56	3	S52535-0D230 RETAINER, FR BUMPER	1.00	100.40	25.00	75.30
57	4	S52536-0D230 RETAINER, FR BUMPER	1.00	100.40	25.00	75.30
58	5	S52161-0K040 PIECE, FR BUMPER	10.00	4.10	25.00	30.70
59	6	S81483-0D030 COVER, DAYTIME RUNNI	1.00	74.70	25.00	56.02
60	7	S81484-0D010 COVER, DAYTIME RUNNI	1.00	74.70	25.00	56.02
61	8	S52021-0D140 REINFORCEMENT SUB-AS	1.00	399.50	25.00	299.62
62	9	S53111-0D912 GRILLE, RADIATOR, CU	1.00	71.30	25.00	53.47
63	0	S53123-0D260 MOULDING, RADIATOR G	1.00	39.40	25.00	29.55
64	1	S53124-0D380 MOULDING, RADIATOR G	1.00	35.00	25.00	26.25
65	2	S53114-0D020 GRILLE, RADIATOR, IN	1.00	239.80	25.00	179.85
66	3	S53119-0D010 PROTECTOR, RADIATOR	1.00	14.60	25.00	10.95
67	4	S53301-0D280 HOOD SUB-ASSY	1.00	924.70	25.00	693.52
68	5	S53801-0D100 FENDER SUB-ASSY, FR	1.00	765.30	25.00	573.97
69	6	S53802-0D100 FENDER SUB-ASSY, FR	1.00	765.30	25.00	573.97
70	7	S53341-0D310 INSULATOR, HOOD	1.00	280.80	25.00	210.60
71	8	S90467-09050 CLIP	6.00	2.90	25.00	13.02
72	9	S53866-0D220 SEAL, FR FENDER TO C	1.00	56.50	25.00	42.37
73	0	S53867-0D220 SEAL, FR FENDER TO C	1.00	56.50	25.00	42.37

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4135805

TO SECURITY GUARD

4135805

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 22/11/2019
TIME 10:16

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



CoReg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shearson Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	M/s Tomy Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97960991
	Document No 0	
	Document Date 22/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AXEART	E1	NBP151R	30/05/2019	SJS1638K	0	50819 60D/SJS1638K/211111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MA2B23F3301176341	2NRX438843	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
74	1	S53875-0D660 LINER, FR FENDER, RH	1.00	222.80	25.00	167.10
75	2	S53876-0D660 LINER, FR FENDER, LH	1.00	222.80	25.00	167.10
76	3	S53208-0D901 SUPPORT SUB-ASSY, HO	1.00	149.90	25.00	112.42
77	4	S53141-0D040 COVER, RADIATOR	1.00	273.50	25.00	205.12
78	5	T90541-15111 CUSHION	2.00	6.20	25.00	9.30
79	6	S53210-0D929 SUPPORT ASSY, RADIAT	1.00	978.70	25.00	734.02
80	7	S53285-0D370 SEAL, RADIATOR SIDE	1.00	60.10	25.00	60.07
81	8	S53286-0D370 SEAL, RADIATOR SIDE	1.00	60.10	25.00	60.07
82	9	S53287-0D260 EXTENSION, RADIATOR	1.00	64.60	25.00	48.45
83	0	S53288-0D250 EXTENSION, RADIATOR	1.00	72.40	25.00	54.30
84	1	S53714-0D200 EXTENSION, FR FENDER	1.00	51.20	25.00	38.40
85	2	S53713-0D200 EXTENSION, FR FENDER	1.00	51.20	25.00	38.40
86	3	S53510-0D770 LOCK ASSY, HOOD	1.00	135.60	25.00	101.70
87	4	S53410-0D400 R/FRT BONNET HINGE	1.00	58.90	25.00	44.17
88	5	S53420-0D400 L/FRT BONNET HINGE	1.00	58.90	25.00	44.17
89	6	S53452-0D090 HOLDER, HOOD STAY	1.00	20.30	25.00	15.22
90	7	T90480-T0002 GROMMET	1.00	6.60	25.00	4.95
91	8	S57201-0D021 EXTENSION SUB-ASSY,	1.00	182.80	25.00	137.10
92	9	S57302-0D031 EXTENSION SUB-ASSY,	1.00	182.80	25.00	137.10
93	0	S73220-0D500 A0 BELT ASSY, FR SEAT	1.00	995.10	25.00	746.32

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4135806

TO SECURITY GUARD

4135806

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 22/11/2019
TIME 10:16

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking:
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	M/s Toay Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97860991
	Document No 0	
	Document Date 22/11/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEXRKT	E1	NSP151R	30/05/2019	SJS1638K	0	50819 60D/SJS1638K/21111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
NR2823F3301176341	2NRX438842	EO	Shashitharan	0.00	0.00		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
94	1	S90975-T2008 EMBLEM, SYMBOL	1.00	58.80	25.00	43.80
95	2	S73210-OD510 A0 BELT ASSY, FR SEAT	1.00	395.10	25.00	746.32
96	3	S62170-OD080 AIR BAG ASSY, CURTAIN	1.00	1485.60	25.00	1114.20
97	4	S62180-OD080 AIR BAG ASSY, CURTAIN	1.00	1485.60	25.00	1114.20
98	5	T62189-42010 SPACER, CURTAIN	4.00	2.20	25.00	6.60
99	6	S62211-OD840 A0 GARNISH, FR PILLAR	1.00	129.10	25.00	96.82
100	7	S62212-OD840 A0 GARNISH, FR PILLAR	1.00	129.10	25.00	96.82

Handwritten notes:
Rasul
Hp 900/0068
12 days
22/11/19 @ 15:45
EXCESS: 500
Rasul
Resin before paint

(S) 5372.17

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 34,097.73 Labour 17,824.80 Materials 80.00 Lubrication/Fluid 0.00 Others 0.00	52,002.53
		GST 1.00%	3,640.18
		Less	0.00
		Amount Due	55,642.71

PLEASE TEAR ALONG PERFORATED LINE

4135807

TO SECURITY GUARD

4135807

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 22/11/2019
TIME 10:16

52,275.20

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2 Document No 0 Document Date 18/12/2019	M/s Tomy Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97860991

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AE	RKT E1	NSP151R	30/05/2019	SJS1638K	0	50819 60D/SJS1638K/211111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3301176341	2NRX438843	60	Shashitharan	27/11/2019	8.00	18/12/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:A29127060AT2 ACC DATE:18/11/19 TOW IN:18/11/19 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				100.00
2	B	BP-LAB2 CHECK WIRING AND REFOCUS HEADLAMP	*			162.00
3	L	BP-LPO SUPPLY REGN PLATE (PO#)	833			80.00
4	B	BP-MECH2 R/I AIRCOND PIPE VACCUM AND REGAS				324.00
5	B	BP-MECH2 REPL DASHBOARD				1296.00
6	B	BP-LAB2 R/I WHOLE INTERIOR TO FAC REPAIR	*			1180.80
7	B	BP-MECH2 REPL WHOLE WIRING HARNESS TO FAC REPAIR				1296.00
8	B	BP-MECH2 REPL SEAT BEALT ASSY				648.00
9	B	BP-MECH2 RESET ECU UPON COMPLETION OF REPAIR				162.00
10	B	BP-MECH2 REPL AIRBAG ECU AND SENSOR AND RESET AIR BAG SYSTEM				648.00
11	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	*			3240.00
12	B	BP-RES2 RESPRAY ACC AFF AREA	*			3717.00
13	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 18/12/2019
TIME 08:22

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchope

Borneo Motors

4136347

4136347



Co Reg No : 196700086Z
GST Reg No : MR-B500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No.	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2 Document No 0 Document Date 18/12/2019	M/s Tomy Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97860991

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEKRKT E1	NSP151R	30/05/2019	SJS1638K	0	50819	60D/SJS1638K/21111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3301176341	2NRX438843	60	Shashitharan	27/11/2019	8.00	18/12/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	V	EXC Excess element of insurance repair to be paid by the insured party				-500.00
15	1	S88300-0D530 AIR CON KIT (NEW VIOS 2016)	1.00	3026.60		3026.60
16	2	S12611-0Y110 COVER, ENGINE, NO.1	1.00	205.30	25.00	153.97
17	3	S16400-0Y191 RADIATOR ASSY	1.00	2052.20	25.00	1539.15
18	4	S16711-0Y160 SHROUD, FAN	1.00	264.70	25.00	198.52
19	5	S17700-0Y190 CLEANER ASSY, AIR W	1.00	1077.90	25.00	808.42
20	6	S17751-0Y261 INLET, AIR CLEANER	1.00	69.90	25.00	52.42
21	7	S81110-0DF00 HEADLAMP ASSY, RH22	1.00	1285.00	25.00	963.75
22	8	S81150-0DF00 HEADLAMP ASSY, LH22	1.00	1285.00	25.00	963.75
23	9	S82140-0D130 WIRE ASSY, INSTRUMEN	1.00	19.00	25.00	14.25
24	0	K89173-09C00 SENSOR, AIR BAG, FR	1.00	374.60	25.00	280.95
25	1	S89170-0DB10 SENSOR ASSY, AIR BAG	1.00	1203.80	25.00	902.85
26	2	S85315-0D220 JAR ASSY, WINDSHIELD	1.00	145.80	25.00	109.35
27	3	S63310-0DC20 AO HEADLINING ASSY, ROO	1.00	1827.20	25.00	1370.40
28	4	S55302-0D240 CO PANEL SUB-ASSY, INST	1.00	884.50	25.00	663.37
29	5	S73960-0D160 AIR BAG ASSY, INSTR	1.00	3883.10	25.00	2912.32
30	6	S45130-0D410 CO PAD ASSY, STEERING W	1.00	2867.40	25.00	2150.55
31	7	S52721-0D290 MOULDING, FR BUMPER	1.00	72.40	25.00	54.30
32	8	S53112-0D540 GRILLE, RADIATOR, LW	1.00	269.50	25.00	202.12

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4136348

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 18/12/2019
TIME 08:22

4136348

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	M/s Tomy Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97860991
	Document No 0	
	Document Date 18/12/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEXRKT	E1	NSP151R	30/05/2019	SJS1638K	0	50819 :60D/SJS1638K/21111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3301176341	2NRX438843	60	Shashitharan	27/11/2019	8.00	18/12/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
33	9	S52119-0U932 COVER, FR BUMPER22	1.00	495.70	25.00	371.77
34	0	S52535-0D230 RETAINER, FR BUMPER22	1.00	100.40	25.00	75.30
35	1	S52536-0D230 RETAINER, FR BUMPER22	1.00	100.40	25.00	75.30
36	2	S81483-0D030 COVER, DAYTIME RUNNI	1.00	74.70	25.00	56.02
37	3	S81484-0D010 COVER, DAYTIME RUNNI	1.00	74.70	25.00	56.02
38	4	S53123-0D260 MOULDING, RADIATOR G	1.00	39.40	25.00	29.55
39	5	S53124-0D380 MOULDING, RADIATOR G	1.00	35.00	25.00	26.25
40	6	S53114-0D020 GRILLE, RADIATOR22	1.00	239.80	25.00	179.85
41	7	S53119-0D010 PROTECTOR, RADIATOR	1.00	14.60	25.00	10.95
42	8	S53301-0D280 HOOD SUB-ASSY22	1.00	924.70	25.00	693.52
43	9	S53801-0D100 FENDER SUB-ASSY, FR22	1.00	765.30	25.00	573.97
44	0	S53802-0D100 FENDER SUB-ASSY, FR22	1.00	765.30	25.00	573.97
45	1	S53341-0D310 INSULATOR, HOOD	1.00	280.80	25.00	210.60
46	2	T90467-09050 CLIP	6.00	2.90	25.00	13.02
47	3	S53866-0D220 SEAL, FR FENDER TO C	1.00	56.50	25.00	42.37
48	4	S53867-0D220 SEAL, FR FENDER TO C	1.00	56.50	25.00	42.37
49	5	S53876-0D660 LINER, FR FENDER, LH22	1.00	222.80	25.00	167.10
50	6	S53208-0D901 SUPPORT SUB-ASSY, HO	1.00	149.90	25.00	112.42
51	7	S53141-0D040 COVER, RADIATOR22	1.00	273.50	25.00	205.12
52	8	S53210-0D929 SUPPORT ASSY, RADIAT	1.00	978.70	25.00	734.02

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4136349

TO SECURITY GUARD

4136349

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 18/12/2019
TIME 08:22

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	M/s Tomy Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97860991
	Document No 0	
	Document Date 18/12/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEXRKT	E1	NSP151R	30/05/2019	SJS1638K	0	50819 60D/SJS1638K/21111'
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3301176341	2NRX438843	60	Shashitharan	27/11/2019	8.00	18/12/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
53	9	S53285-0D370 SEAL, RADIATOR SIDE	1.00	80.10	25.00	60.07
54	0	S53286-0D370 SEAL, RADIATOR SIDE	1.00	80.10	25.00	60.07
55	1	S53287-0D260 EXTENSION, RADIATOR	1.00	64.60	25.00	48.45
56	2	S53288-0D250 EXTENSION, RADIATOR	1.00	72.40	25.00	54.30
57	3	S53510-0D770 LOCK ASSY, HOOD	1.00	135.60	25.00	101.70
58	4	S53410-0D400 HINGE ASSY, HOOD RH	1.00	58.90	25.00	44.17
59	5	S53420-0D400 HINGE ASSY, HOOD LH	1.00	58.90	25.00	44.17
60	6	S53452-0D090 HOLDER, HOOD STAY	1.00	20.30	25.00	15.22
61	7	S73220-0D500 AO BELT ASSY, FR SEAT,	1.00	995.10	25.00	746.32
62	8	S73210-0D510 AO BELT ASSY, FR SEAT,	1.00	995.10	25.00	746.32
63	9	S62170-0D080 AIR BAG ASSY, CURTAIN	1.00	1485.60	25.00	1114.20
64	0	S62180-0D080 AIR BAG ASSY, CURTAIN	1.00	1485.60	25.00	1114.20
65	1	S11201-0Y030 COVER SUB-ASSY, CYLINDER	1.00	691.00	25.00	518.25
66	2	S15301-0Y010 GAGE SUB-ASSY, OIL LEVEL	1.00	32.00	25.00	24.00
67	3	S11452-0Y020 GUIDE, OIL LEVEL GAG	1.00	39.20	25.00	29.40
68	4	S27060-0Y300 ALTERNATOR ASSY, W/R	1.00	2805.20	25.00	2103.90
69	5	S73900-0D060 AO AIR BAG ASSY, INSTR	1.00	1907.00	25.00	1430.25
70	6	U89467-30050 SENSOR, AIR FUEL	1.00	567.70	25.00	425.77
71	7	T90980-12A88 HOUSING, CONNECTOR	1.00	17.90	25.00	13.42
72	8	S53630-0D340 CABLE ASSY, HOOD LOC	1.00	54.90	25.00	41.17

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 18/12/2019
TIME 08:22

VEHICLE NO SJS1638K

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

4136350

4136350



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2 Document No: 0 Document Date: 18/12/2019	M/s Tomy Printing Company 20 Woodlands Link #02-21 Singapore 738733 Attn: Mr Tan Mobile: 97860991

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
19	AEXRKT	E1	NSP151R	30/05/2019	SJS1638K	0	50819 :60D/SJS1638K/2111
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3301176341	2NRX438843	60	Shashitharan	27/11/2019	8.00	18/12/2019	18.

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
73	9	K89175-0D060 BRACKET, AIR BAG SEN	1.00	30.30	25.00	22.7
74	0	S90975-T2008 EMBLEM, SYMBOL	1.00	58.40	25.00	43.1
75	1	S53214-0D160 SUPPORT, RADIATOR, U	1.00	78.90	25.00	59.
76	2	S53213-0D160 SUPPORT, RADIATOR, U	1.00	78.90	25.00	59.
77	3	S55708-0D272 LOUVER SUB-ASSY, COW	1.00	710.60	25.00	532.
78	4	T28800-YZZHY TGB, 34B19L	1.00	112.50		112.
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						43,235.99

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 30,182.19 Labour 12,973.80 Materials 80.00 Lubrication/Fluid 0.00 Others 0.00	42,735.99 GST 7.00% 2,991.00 Less 0.00 Amount Due 45,727.00

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 18/12/2019
TIME 08:22

VEHICLE NO SJS1638K

RETURNED

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 20 December 2019 10:40 AM
To: 'Shashitharan PTCBC'; Rasul (LKKAUTO); SUR
Subject: RE: SJS1638K FINAL BILL

Dear ShaShi,

Confirmed repair limit \$35,000/- before excess \$500 and GST @ 12 days.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Shashitharan PTCBC <Shashitharan@borneomotors.com.sg>
Sent: Thursday, 19 December 2019 10:30 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: SJS1638K FINAL BILL
Importance: High

-----Original Message-----

From: Shashitharan@borneomotors.com.sg [mailto:Shashitharan@borneomotors.com.sg]
Sent: Thursday, December 19, 2019 9:40 AM
To: Shashitharan PTCBC
Subject: Scan Data from FX-2F43FF

Sent by: [Shashitharan@borneomotors.com.sg]
Number of Images: 5
Attachment File Type: PDF

Device Name: ApeosPort-VI C3371
Device Location:

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Nov 2019		22 Nov 2019 14:43 Edit Adj Rpt	S\$35,000.00 Edit Estimates	S\$35,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TOMY PRINTING COMPANY, Co. Reg. No.: 33129300E								
Vehicle Reg. No.:	SJS1638K	Date of Loss:	18/11/2019 12:00 - :59 [5 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 611884	Policy/Cover Note No.:	29127060AT2 (Comprehensive) Coverage: 30/05/2019 - 29/05/2020						
		Excess:	S\$500.00						
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Richard Ang Wei Guang - 6594 2560]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 22/12/2019]								
Driver/Custodian:	ONG CHAI PENG (47 / Female) , NRIC: S7240290A, Tel: +6597860991 Email: dannusong@gmail.com								
Adj Asg. Remarks:	Car in, please arrange survey ASAP. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please revert with Market Value and Repair Limit (if applicable).								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (19/12/2019): Alert - Adj Mandate Approved (S\$35000.00) - SJS1638K - Claim Handler: Richard An... - MSIG_SG (27/11/2019): Alert - Adj Mandate Approved (S\$35000.00) - SJS1638K - Claim Handler: Richard An... - MSIG_SG (26/11/2019): Proposed Limit Repair - SJS1638K									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJS1638K (611884)
OD
Nov 18 2019 12:00PM
[TOMY PRINTING COMPANY]
Borneo Motors (S) Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/11/19 11:07	Adjuster Immediate Advice		Load HTM	
2	27/11/19 09:54	Adjuster Immediate Advice		Load HTM	
3	19/12/19 12:36	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Formteam Accident Services Taskforce Pte Ltd (HQ)		Thumbnail	Print
1	18/11/19 16:42	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	18/11/19 16:42	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	18/11/19 16:42	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	18/11/19 16:42	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	18/11/19 16:42	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	18/11/19 16:42	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	18/11/19 16:42	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	18/11/19 16:42	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	18/11/19 16:44	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
10	18/11/19 16:44	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
11	18/11/19 16:44	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
12	18/11/19 16:44	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
13	18/11/19 16:44	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
14	18/11/19 16:44	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/12/19 12:03	General View		Load JPG	☒
2	19/12/19 12:03	General View		Load JPG	☒
3	19/12/19 12:03	General View		Load JPG	☒
4	19/12/19 12:03	General View		Load JPG	☒
5	19/12/19 12:03	General View		Load JPG	☒
6	19/12/19 12:03	General View		Load JPG	☒
7	19/12/19 12:03	General View		Load JPG	☒
8	19/12/19 12:03	General View		Load JPG	☒
9	19/12/19 12:03	General View		Load JPG	☒
10	19/12/19 12:03	General View		Load JPG	☒
11	19/12/19 12:03	General View		Load JPG	☒
12	19/12/19 12:03	General View		Load JPG	☒
13	19/12/19 12:03	General View		Load JPG	☒
14	19/12/19 12:03	General View		Load JPG	☒
15	19/12/19 12:03	General View		Load JPG	☒
16	19/12/19 12:03	General View		Load JPG	☒
17	19/12/19 12:03	General View		Load JPG	☒
18	19/12/19 12:03	General View		Load JPG	☒
19	19/12/19 12:03	General View		Load JPG	☒
20	19/12/19 12:04	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
21	19/12/19 12:04	General View		☒
22	19/12/19 12:04	General View		☒
23	19/12/19 12:04	General View		☒
24	19/12/19 12:04	General View		☒
25	19/12/19 12:04	General View		☒
26	19/12/19 12:04	General View		☒
27	19/12/19 12:04	General View		☒
28	19/12/19 12:04	General View		☒
29	19/12/19 12:04	General View		☒
30	19/12/19 12:04	General View		☒
31	19/12/19 12:04	General View		☒
32	19/12/19 12:04	General View		☒
33	19/12/19 12:04	General View		☒
34	19/12/19 12:04	General View		☒
35	19/12/19 12:04	General View		☒
36	19/12/19 12:04	General View		☒
37	19/12/19 12:04	General View		☒
38	19/12/19 12:04	General View		☒
39	19/12/19 12:04	General View		☒
40	19/12/19 12:04	General View		☒
41	19/12/19 12:04	General View		☒
42	19/12/19 12:04	General View		☒
43	19/12/19 12:04	General View		☒
44	19/12/19 12:04	General View		☒
45	19/12/19 12:04	General View		☒
46	19/12/19 12:04	General View		☒
47	19/12/19 12:04	General View		☒
48	19/12/19 12:04	General View		☒
49	19/12/19 12:04	General View		☒
50	19/12/19 12:04	General View		☒
51	19/12/19 12:04	General View		☒
52	19/12/19 12:04	General View		☒
53	19/12/19 12:04	General View		☒
54	19/12/19 12:04	General View		☒
55	19/12/19 12:04	General View		☒
56	19/12/19 12:04	General View		☒
57	19/12/19 12:04	General View		☒
58	19/12/19 12:04	General View		☒
59	19/12/19 12:04	General View		☒
60	19/12/19 12:04	General View		☒
61	19/12/19 12:04	General View		☒
62	19/12/19 12:04	General View		☒
63	19/12/19 12:04	General View		☒
64	19/12/19 12:04	General View		☒
65	19/12/19 12:04	General View		☒
66	19/12/19 12:04	General View		☒
67	19/12/19 12:04	General View		☒
68	19/12/19 12:04	General View		☒
69	19/12/19 12:04	General View		☒
70	19/12/19 12:04	General View		☒
71	19/12/19 12:04	General View		☒
72	19/12/19 12:04	General View		☒
73	19/12/19 12:04	General View		☒
74	19/12/19 12:04	General View		☒
75	19/12/19 12:04	General View		☒
76	19/12/19 12:04	General View		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
77	19/12/19 12:04	General View		☒
78	19/12/19 12:04	General View		☒
79	19/12/19 12:04	General View		☒
80	19/12/19 12:04	General View		☒
81	19/12/19 12:04	General View		☒
82	19/12/19 12:04	General View		☒
83	19/12/19 12:04	General View		☒
84	19/12/19 12:04	General View		☒
85	19/12/19 12:04	General View		☒
86	19/12/19 12:04	General View		☒
87	19/12/19 12:04	General View		☒
88	19/12/19 12:04	General View		☒
89	19/12/19 12:17	Reinspection Photo		☒
90	19/12/19 12:17	Reinspection Photo		☒
91	19/12/19 12:17	Reinspection Photo		☒
92	19/12/19 12:17	Reinspection Photo		☒
93	19/12/19 12:17	Reinspection Photo		☒
94	19/12/19 12:17	Reinspection Photo		☒
95	19/12/19 12:17	Reinspection Photo		☒
96	19/12/19 12:17	Reinspection Photo		☒
97	19/12/19 12:17	Reinspection Photo		☒
98	19/12/19 12:17	Reinspection Photo		☒
99	19/12/19 12:17	Reinspection Photo		☒
100	19/12/19 12:17	Reinspection Photo		☒
101	19/12/19 12:17	Reinspection Photo		☒
102	19/12/19 12:17	Reinspection Photo		☒
103	19/12/19 12:17	Reinspection Photo		☒
104	19/12/19 12:17	Reinspection Photo		☒
105	19/12/19 12:17	Reinspection Photo		☒
106	19/12/19 12:17	Reinspection Photo		☒
107	19/12/19 12:17	Reinspection Photo		☒
108	19/12/19 12:17	Reinspection Photo		☒
109	19/12/19 12:17	Reinspection Photo		☒
110	19/12/19 12:17	Reinspection Photo		☒
111	19/12/19 12:17	Reinspection Photo		☒
112	19/12/19 12:17	Reinspection Photo		☒
113	19/12/19 12:17	Reinspection Photo		☒
114	19/12/19 12:17	Reinspection Photo		☒
115	19/12/19 12:17	Reinspection Photo		☒
116	19/12/19 12:17	Reinspection Photo		☒
117	19/12/19 12:17	Reinspection Photo		☒
118	19/12/19 12:17	Reinspection Photo		☒
119	19/12/19 12:17	Reinspection Photo		☒
120	19/12/19 12:17	Reinspection Photo		☒
121	19/12/19 12:17	Reinspection Photo		☒
122	19/12/19 12:17	Reinspection Photo		☒
123	19/12/19 12:17	Reinspection Photo		☒
124	19/12/19 12:17	Reinspection Photo		☒
125	19/12/19 12:17	Reinspection Photo		☒
126	19/12/19 12:17	Reinspection Photo		☒
127	19/12/19 12:17	Reinspection Photo		☒
128	19/12/19 12:17	Reinspection Photo		☒
129	19/12/19 12:17	Reinspection Photo		☒
130	19/12/19 12:18	Reinspection Photo		☒
131	19/12/19 12:18	Reinspection Photo		☒
132	19/12/19 12:18	Reinspection Photo		☒

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
133	19/12/19 12:18	Reinspection Photo	 Load JPG	☒	
134	19/12/19 12:18	Reinspection Photo	 Load JPG	☒	
135	19/12/19 12:18	Reinspection Photo	 Load JPG	☒	
136	19/12/19 12:18	Reinspection Photo	 Load JPG	☒	
137	19/12/19 12:18	Reinspection Photo	 Load JPG	☒	
138	19/12/19 12:18	Reinspection Photo	 Load JPG	☒	
139	19/12/19 12:18	Reinspection Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	22/11/19 13:39	Repair Estimates	 Load PDF		
2	22/11/19 13:41	E-filed GIA Report	 Load PDF		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	25/11/19 09:51	MARK ESTIMATE	 Load PDF		
2	19/12/19 12:38	SUPPLEMENTARY	 Load PDF		

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Formteam Accident Services Taskforce Pte Ltd (HQ)	Thumbnail	Print	
1	06/12/19 19:31	Accident Statement	 Load HTM		
2	06/12/19 19:32	Accident Statement	 Load HTM		
3	06/12/19 19:32	Accident Statement	 Load HTM		
4	06/12/19 19:35	Accident Statement	 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	Formteam Accident Services Taskforce Pte Ltd (HQ)	Thumbnail	Print	
1	18/11/19 16:42	Accident Photo	 Load JPG	☒	
2	18/11/19 16:42	Accident Photo	 Load JPG	☒	
3	18/11/19 16:42	Accident Photo	 Load JPG	☒	
4	18/11/19 16:42	Accident Photo	 Load JPG	☒	
5	18/11/19 16:42	Accident Photo	 Load JPG	☒	
6	18/11/19 16:42	Accident Photo	 Load JPG	☒	
7	18/11/19 16:42	Accident Photo	 Load JPG	☒	
8	18/11/19 16:42	Accident Photo	 Load JPG	☒	
9	18/11/19 16:44	Accident Photo	 Load JPG	☒	
10	18/11/19 16:44	Accident Photo	 Load JPG	☒	
11	18/11/19 16:44	Accident Photo	 Load JPG	☒	
12	18/11/19 16:44	Accident Photo	 Load JPG	☒	
13	18/11/19 16:44	Accident Photo	 Load JPG	☒	
14	18/11/19 16:44	Accident Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	Formteam Accident Services Taskforce Pte Ltd (HQ)	Thumbnail	Print	
1	18/11/19 16:41	Sketch Plan	 Load JPG	☒	
2	18/11/19 16:41	Sketch Plan #2	 Load JPG	☒	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19020706/R1VD3E2

Date: 10/01/2020

REFERENCE

Insured/Claimant: TOMY PRINTING COMPANY
Date of Loss: 18/11/2019

Policy No: 29127060AT2
Nature of Claim: OD

Claim No: 611884

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS1638K	Engine No:	2NRX438843
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3301176341
Reg. Date:	30/05/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$74,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,770.40	30,482.19	9,288.21	23.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,604.80	12,753.80	4,851.00	27.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	57,375.20	43,235.99	14,139.21	24.64
Approved Total (Overridden) (S\$)		35,000.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	56,875.20	34,500.00	22,375.20	39.34
+ GST 7.00/7.00% (S\$)	3,981.26	2,415.00	1,566.26	39.34
Nett Amount (S\$)	60,856.46	36,915.00	23,941.46	39.34

INSPECTION

Date of Assignment:	22/11/2019	
Date Inspected:	22/11/2019	Inspected At: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	12.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2020)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS1638K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*100.00 FS
2	1		*SEALANT	Necessary	200.00 FS	*200.00 FS
3	1		*AIR CON KIT (NEW VIOS 2016)	Not Working	3,026.60 FS	*3,026.60 FS
4	1		*SET LED FOG LAMP	Serviceable	387.80 FS	*- FS
5	1		*COVER, ENGINE, NO.1	Cracked	153.97 FS	*153.97 FS
6	1		*RADIATOR ASSY	Bent	1,539.15 FS	*1,539.15 FS
7	2		*CUSHION, RADIATOR SU	Not Necessary	9.14 FS	*- FS
8	1		*FAN	Serviceable	180.90 FS	*- FS
9	1		*SHROUD, FAN	Cracked	198.52 FS	*198.52 FS
10	1		*MOTOR, COOLING FAN	Serviceable	421.87 FS	*- FS
11	1		*HOSE, RADIATOR, NO.1	Serviceable	38.70 FS	*- FS
12	1		*BELT, V-RIBBED	Serviceable	110.85 FS	*- FS
13	1		*INSULATOR, EXHAUST	Serviceable	77.77 FS	*- FS
14	1		*INSULATOR, EXHAUST	Serviceable	77.77 FS	*- FS
15	1		*CLEANER ASSY, AIR W/	Cracked	808.42 FS	*808.42 FS
16	1		*BRACKET, AIR CLEANER	Serviceable	22.72 FS	*- FS
17	1		*INLET, AIR CLEANER	Cracked	52.42 FS	*52.42 FS
18	1		*HOSE, AIR CLEANER, N	Serviceable	77.25 FS	*- FS
19	1		*HEADLAMP ASSY, RH	Broken	963.75 FS	*963.75 FS
20	1		*HEADLAMP ASSY, LH	Broken	963.75 FS	*963.75 FS
21	1		*WIRE, ENGINE ROOM MA	Serviceable	2,534.02 FS	*- FS
22	1		*WIRE, ENGINE	Serviceable	1,932.90 FS	*- FS
23	1		*WIRE ASSY, INSTRUMEN	Cut	14.25 FS	*14.25 FS
24	1		*COVER, RELAY BLOCK	Serviceable	16.87 FS	*- FS
25	1		*BLOCK, ENGINE ROOM R	Serviceable	103.65 FS	*- FS
26	1		*COVER, RELAY BLOCK,	Serviceable	41.25 FS	*- FS
27	1		*CABLE SUB-ASSY, SPIR	Serviceable	808.42 FS	*- FS
28	1		*BRACKET, AIR BAG SEN	Not Necessary	22.72 FS	*- FS
29	1		*SENSOR, AIR BAG, FR	Activated	280.95 FS	*280.95 FS
30	1		*SENSOR ASSY, AIR BAG	Activated	902.85 FS	*902.85 FS
31	2		*SENSOR, SIDE AIR BAG	Serviceable	1,036.50 FS	*- FS
32	1		*JAR ASSY, WINDSHIELD	Deformed	109.35 FS	*109.35 FS
33	1		*TRAY, BATTERY	Serviceable	44.85 FS	*- FS
34	1		*CLAMP SUB-ASSY, BATT	Serviceable	24.97 FS	*- FS
35	1		*HEADLINING ASSY, ROO	Deformed	1,370.40 FS	*1,370.40 FS
36	1		*PANEL SUB-ASSY, INST	Bent	663.37 FS	*663.37 FS
37	1		*AIR BAG ASSY, INSTR	Activated	2,912.32 FS	*2,912.32 FS
38	1		*PAD ASSY, STEERING W	Activated	2,150.55 FS	*2,150.55 FS
39	1		*MOULDING, FR BUMPER	Necessary	54.30 FS	*54.30 FS
40	1		*GRILLE, RADIATOR, LW	Cracked	202.12 FS	*202.12 FS
41	1		*GRILLE, RADIATOR, LW	Serviceable	68.17 FS	*- FS
42	1		*COVER, FR BUMPER, L/	Cracked	371.77 FS	*371.77 FS
43	1		*COVER, FR BUMPER HOL	Serviceable	66.37 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*COVER, FR BUMPER HOL	Serviceable	66.37 FS	*- FS
45	1		*RETAINER, FR BUMPER	Necessary	75.30 FS	*75.30 FS
46	1		*RETAINER, FR BUMPER	Necessary	75.30 FS	*75.30 FS
47	10		*PIECE, RR BUMPER	Not Necessary	30.70 FS	*- FS
48	1		*COVER, DAYTIME RUNNI	Cracked	56.02 FS	*56.02 FS
49	1		*COVER, DAYTIME RUNNI	Cracked	56.02 FS	*56.02 FS
50	1		*REINFORCEMENT SUB-AS	Repair	299.62 FS	*- FS
51	1		*GRILLE, RADIATOR, OU	Serviceable	53.47 FS	*- FS
52	1		*MOULDING, RADIATOR G	Cracked	29.55 FS	*29.55 FS
53	1		*MOULDING, RADIATOR G	Cracked	26.25 FS	*26.25 FS
54	1		*GRILLE, RADIATOR, IN	Cracked	179.85 FS	*179.85 FS
55	1		*PROTECTOR, RADIATOR	Cracked	10.95 FS	*10.95 FS
56	1		*HOOD SUB-ASSY	Buckled	693.52 FS	*693.52 FS
57	1		*FENDER SUB-ASSY, FR	Bent	573.97 FS	*573.97 FS
58	1		*FENDER SUB-ASSY, FR	Bent	573.97 FS	*573.97 FS
59	1		*INSULATOR, HOOD	Deformed	210.60 FS	*210.60 FS
60	6		*CLIP	Necessary	13.02 FS	*13.02 FS
61	1		*SEAL, FR FENDER TO C	Necessary	42.37 FS	*42.37 FS
62	1		*SEAL, FR FENDER TO C	Necessary	42.37 FS	*42.37 FS
63	1		*LINER, FR FENDER, RH	Serviceable	167.10 FS	*- FS
64	1		*LINER, FR FENDER, LH	Deformed	167.10 FS	*167.10 FS
65	1		*SUPPORT SUB-ASSY, HO	Bent	112.42 FS	*112.42 FS
66	1		*COVER, RADIATOR	Cracked	205.12 FS	*205.12 FS
67	2		*CUSHION	Not Necessary	9.30 FS	*- FS
68	1		*SUPPORT ASSY, RADIAT	Buckled	734.02 FS	*734.02 FS
69	1		*SEAL, RADIATOR SIDE	Necessary	60.07 FS	*60.07 FS
70	1		*SEAL, RADIATOR SIDE	Necessary	60.07 FS	*60.07 FS
71	1		*EXTENSION, RADIATOR	Cracked	48.45 FS	*48.45 FS
72	1		*EXTENSION, RADIATOR	Cracked	54.30 FS	*54.30 FS
73	1		*EXTENSION, FR FENDER	Serviceable	38.40 FS	*- FS
74	1		*EXTENSION, FR FENDER	Serviceable	38.40 FS	*- FS
75	1		*LOCK ASSY, HOOD	Bent	101.70 FS	*101.70 FS
76	1		*R/FRT BONNET HINGE	Bent	44.17 FS	*44.17 FS
77	1		*L/FRT BONNET HINGE	Bent	44.17 FS	*44.17 FS
78	1		*HOLDER, HOOD STAY	Bent	15.22 FS	*15.22 FS
79	1		*GROMMET	Not Necessary	4.95 FS	*- FS
80	1		*EXTENSION SUB-ASSY	Serviceable	137.10 FS	*- FS
81	1		*EXTENSION SUB-ASSY	Serviceable	137.10 FS	*- FS
82	1		*BELT ASSY, FR SEAT,	Activated	746.32 FS	*746.32 FS
83	1		*EMBLEM, SYMBOL	Necessary	43.80 FS	*43.80 FS
84	1		*BELT ASSY, FR SEAT,	Activated	746.32 FS	*746.32 FS
85	1		*AIR BAG ASSY, CURTAI	Activated	1,114.20 FS	*1,114.20 FS
86	1		*AIR BAG ASSY, CURTAI	Activated	1,114.20 FS	*1,114.20 FS
87	4		*SPACER, CURTAIN	Not Necessary	6.60 FS	*- FS
88	1		*GARNISH, FR PILLAR,	Serviceable	96.82 FS	*- FS
89	1		*GARNISH, FR PILLAR,	Serviceable	96.82 FS	*- FS
90	1		*COVER SUB-ASSY, CYLI	Cracked	518.25 FS	*518.25 FS
91	1		*GAGE SUB-ASSY, OIL L	Cracked	24.00 FS	*24.00 FS
92	1		*GUIDE, OIL LEVEL GAG	Cracked	29.40 FS	*29.40 FS
93	1		*ALTERNATOR ASSY, W/R	Shorted	2,103.90 FS	*2,103.90 FS
94	1		*AIR BAG ASSY, INSTR	Activated	1,430.25 FS	*1,430.25 FS
95	1		*SENSOR, AIR FUEL	Activated	425.77 FS	*425.77 FS
96	1		*HOUSING, CONNECTOR	Cracked	13.42 FS	*13.42 FS
97	1		*CABLE ASSY, HOOD LOC	Cut	41.17 FS	*41.17 FS
98	1		*BRACKET, AIR BAG SEN	Necessary	22.72 FS	*22.72 FS
99	1		*SUPPORT, RADIATOR, U	Necessary	59.17 FS	*59.17 FS
100	1		*SUPPORT, RADIATOR, U	Necessary	59.17 FS	*59.17 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
101	1		*LOUVER SUB-ASSY, COW	Cracked	532.95 FS	*532.95 FS
102	1		*TGB, 34B19L	Necessary	112.50 FS	*112.50 FS
Total Parts (S\$)					39,770.40	30,482.19

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND REFOCUS HEADLAMP	New	162.00	162.00
2	SUPPLY REGN PLATE (PO#)	New	80.00	80.00
3	R/I AIRCOND PIPE VACUUM AND REGAS	New	324.00	324.00
4	REPL DASHBOARD	New	1,296.00	1,296.00
5	R/I WHOLE INTERIOR TO FAC REPAIR	New	1,180.80	1,180.80
6	REPL WHOLE WIRING HARNESS TO FAC REPAIR	New	1,296.00	1,296.00
7	REPL SEAT BEALT ASSY	New	648.00	648.00
8	RESET ECU UPON COMPLETION OF REPAIR	New	180.00	162.00
9	REPL AIRBAG ECU AND SENSOR AND RESET AIR BAG SYSTEM	New	648.00	648.00
10	REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	New	6,480.00	3,240.00
11	RESPRAY ACC AFF AREA	New	5,310.00	3,717.00
Gross Labour Cost (\$\$)			17,604.80	12,753.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >