

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000176**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 26-NOV-2019
 MAKE : TOYOTA
 MODEL : HIACE MANUAL
 CHASSIS NO : JTFHT02P600001889
 ENGINE NO : 1KD1566856
 SERVICE ADVISOR : SHARIFAH
 PAGE : 1 OF 2

GBA801B**168 TRADING**

5 KAKI BUKIT ROAD 2
 #04-05 CITY WAREHOUSE
 SINGAPORE 417839
 CONTACT NO : 67487995

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	TAIL LAMP RH	0.00	265.20 231.85 ✓
1	TAIL LAMP BRACKET RH	0.00	48.50
1	TAIL LAMP LOWER GARNISH RH	0.00	108.90
1	TAIL LAMP LOWER GARNISH RETAINER RH	0.00	51.60
1	REAR BUMPER	0.00	396.10 ✓
1	REAR BUMPER SIDE RETAINER RH	0.00	51.60 36.80 ✓
1	REAR FENDER RH	0.00	1553.70
1	REAR SLIDING DOOR TRACK RH	0.00	428.90
1	REAR SLIDING DOOR TRACK COVER RH	0.00	56.70
Sub Total		0.00	0.00

SPECIAL NETT

10	REAR BUMPER CLIPS	50.00	20 ✓
1	REAR FENDER RH SEALANT	50.00	
1	REAR SLIDING DOOR TRACK RH SEALANT	50.00	
Sub Total		150.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1,000.00	500 ✓
1	TO SPRAY PAINT ON AFFECTED AREAS	800.00	300 ✓
1	TO CHECK WIRING	120.00	20 ✓
1	TO APPLY UNDERCOATING FOR RUST PROOFING	150.00	
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING	120.00	20 ✓
1	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	120.00	
Sub Total		2,310.00	0.00

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**SUPPLEMENTARY: HQQ000187**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

GBA801B
168 TRADING
 5 KAKI BUKIT ROAD 2
 #04-05 CITY WAREHOUSE
 SINGAPORE 417839
 CONTACT NO : 67487995

DATE : 05-DEC-2019
 MAKE : TOYOTA
 MODEL : HIACE MANUAL
 CHASSIS NO : JTFHT02P600001889
 ENGINE NO : 1KD1566856
 SERVICE ADVISOR : SHARIFAH
 PAGE : 1 OF 1

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
SPECIAL NETT			

1 REVERSE SENSOR

✓ Short

300.00 200 ✓

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey
5/12/19
11.15 Am
H. Arun
8531883

664.75
 parts less 25%

498.56

spe nett 220

1960 840

1558.56

L/s less 20%

1246.84

Total
 L/s amt \$1250

SUB-TOTAL	300.00	0.00
GST - 7 %	21.00	0.00
TOTAL	321.00	0.00

ABWIN SERVICE PTE LTD

Prepared By

8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
Tel: 67139400 Fax: 67139415
Email: servicentre@abwinm9.com Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

ESTIMATED COST: HQQ000176

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

GBA801B
168 TRADING
5 KAKI BUKIT ROAD 2
#04-05 CITY WAREHOUSE
SINGAPORE 417839
CONTACT NO : 67487995

```

DATE          : 26-NOV-2019
MAKE          : TOYOTA
MODEL         : HIACE MANUAL
CHASSIS NO    : JTFHT02P600001889
ENGINE NO     : 1KD1566856
SERVICE ADVISOR : SHARIFAH
PAGE          : 2 OF 2

```

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

SUB-TOTAL	2,460.00	0.00
GST - 7 %	172.20	0.00
TOTAL	2,632.20	0.00

ABWIN SERVICE PTE LTD

Prepared By