

ASS. REC. BY:

REF:

CS/FCT/19020711/R/Hd3m2

Special Instruction:

Assigner: Rasul

ASSIGNMENT (Office)

CWS

From (Person):

Menira chris

of

FCT

Date/Time:

12:15pm @ 22/11/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

GBG 3440H

Insured:

SHD 8561D

at Workshop m/s

Sin Sheng Engineering

Tel:

6863 9595

of

No. 8 Fuis Ave 18

Policy No:

Claim No:

D19007398MFBH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:28pm @ 22/11/19

Person Contacted:

per jin

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate

✓

GBG 3440H-X

SHD 8561D-CS/FCT/18019710/Dgd3n2

D.O.A. 26/10/2018

25/11@2:17

Revised

via email

preli advise.

lump Sum

\$1900/-

4 days

Ured 22/3/19

54%

ASS. REC. BY:

REF: FCE

ASSIGNMENT

From:

Date:

22/11/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

CBA 3440 H

at Workshop m/s

Singsheng Engineering

of

No. 8 Tuas Ave 18 (Level 3)

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

CBA 3440 H

Yr Regn:

2017 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA HIACE DX 3.0A

c.c

2982

Colour

RED

A/C:

Insured / Std / NI / NA

Sp. Reading

82261

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

K04 201 0222278

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195R15C

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ANSTONE

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

18/09/19

D.O.I.

22/10/19

Survey held at

Singsheng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 08 JAN 2020

Date/Time, File Pass to?

1) 311 Typist

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

135

50

50

39

274

Report Format:

Lump Sum / H.R. / F

TP

1900



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007398MFSH

Date: 25/11/2019

Our Ref: CS/FCI19020711/R1td3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. GBG 3440H

Please be informed that we had conducted the inspection of the abovementioned vehicle 22/11/2019 at the premises of M/s Sin Sheng have the following to report: -

Workshop Estimate Amount	: S\$ 4,133.30
Revised Estimate Amount	: S\$ 2,361.38
"Check" Items Amount	: S\$ 0.00
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:
The vehicle sustained damages at the
o/s portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	21-11-2019	Our Ref No. D19007398MFSH
Accident Date	18-09-2019	Claim Type. Third Party
Insured Vehicle	SHD8561D	Third Party Vehicle. GBG3440H
Survey Location	NO 8 TUAS AVE 18 (LEVEL 3)	
Contact Person.	PEI JIN	
Contact No.	6863 9595/ 0	Fax No. 6863 6477
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIN SHENG ENGINEERING SERVICES	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 25 November 2019 2:17 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Merina Chia'; SUR
Subject: RE: SURVEY ASSESSMENT - D19007398MFSH/1
Attachments: PRELI ADVISED OF GBG 3440H.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GBG 3440H**
Number of days (estimated) : 4 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 22 November 2019 12:33 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19007398MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 22 November 2019 12:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007398MFSH/1

Denise Tay (LKKAuto)

From: sinsheng engineering services <sinsheng1981@gmail.com>
Sent: Friday, 3 January 2020 6:24 PM
To: Rasul (LKKAuto)
Subject: Re: Accident Involving GBG3440H & SHD8561D on 18/09/2019

Hi Mr. Rasul,

We are agreed your offer.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin

Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel: 6863 9595
Fax: 6863 6477

On Fri, 3 Jan 2020 at 11:04, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Pei Jin,

Refer to attachment

Finalised amount is \$ 1,900 / 4 days lump sum

Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

196N

Vehicle Details

Vehicle No.:

GBG3440H

Vehicle to be Exported:

Yes

Intended Deregistration Date:

31 Dec 2019

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE DX 3.0 AUTO

Primary Colour:

Silver

Manufacturing Year:

2017

Engine No.:

1KD2708571

Chassis No.:

KDH2010222278

Maximum Power Output:

-

Open Market Value:

\$33,981.00

Original Registration Date:

24 Jul 2017

First Registration Date:

24 Jul 2017

Transfer Count:

0

Actual ARF Paid:

\$1,700.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

23 Jul 2027

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$32,682.00

COE Rebate Amount:

\$24,713.00

Total Rebate Amount:

\$24,713.00

The information contained herein is correct as at 14 Nov 2019

OK

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES003006

Date : 22/11/2019
Vehicle Num. : GBG3440H
Make/Model : TOYOTA KDH 201
Chassis/Eng# : KDH 201-0222278
Accident Date : 18/09/2019
Claim No. : D19007398MFSH
Reference : SHD8561D
Policy No. : 29131844

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS :		
2.	1	SIDE PANEL, RH <i>bt ✓</i>		1,748.50
		SLIDING DOOR <i>repair</i>		1,895.90
		List Total S\$:		3,644.40
		25.00% Discount S\$:		911.10
				2,733.30
		LABOUR :		
		TO PANEL BEAT AND REPAIR RIGHT SIDE BODY		
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
		TO SPRAY PAINTING		
		TO APPLY TUFF KOTE		50.00
		LOSS OF USE : 5 DAYS @ S\$120/DAY		
		Labour Total S\$:		1,400.00

SIN SHENG ENGINEERING SERVICES

Total S\$: 4,133.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Denz

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES003006

Date : 22/11/2019
Vehicle Num. : GBC3440H
Make/Model : TOYOTA KDH 201
Chassis/Eng# : KDH 201-0222278
Accident Date : 18/09/2019
Claim No. : D19007398MFSH
Reference : SHD8561D
Policy No. : 29131844

S/N	Quantity	Particular	Unit Price	Amount SS
-----	----------	------------	------------	-----------

1.	1	LIST ITEMS :		
2.	1	SIDE PANEL, RH <i>bt</i>		
		SLIDING DOOR <i>repair</i>		
		List TotalSS :		
		25.00% Discount SS :		
		LABOUR :		
		TO PANEL BEAT AND REPAIR RIGHT SIDE BODY		
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
		TO SPRAY PAINTING		
		TO APPLY TUFF KOTE		
		LOSS OF USE : 5 DAYS @ SS120/DAY		
		Labour Total SS :		

Repair
HP 90010068
4 days
4/5
22/11/19 @ 1645
Repair after repair

1,748.50	1748.50
1,895.90	1895.90
3,644.40	3644.40
911.10	911.10
2,733.30	2733.30
500	500
650.00	650.00
500	500
700.00	700.00
50.00	50.00
1,400.00	1400.00

1050

Total SS : 4,133.30

SIN SHENG ENGINEERING SERVICES

1311.37
1050.00
2361.37
20%
1889.09
4/5 - 1900



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19020711/R1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-01-2020	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8561D	Veh. Inspected	GBG 3440H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19007398MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	22/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE DX 3.0 (A)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KDH2010222278	Colour	RED	
Odometer	82261	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	AUSTONE	6 mm	
L/H Front Tyre	195 R15C	AUSTONE	6 mm	
R/H Rear Tyre	195 R15C	AUSTONE	6 mm	
L/H Rear Tyre	195 R15C	AUSTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/09/2019	Inspection Date	22/11/2019	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 3440H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SIDE PANEL,RH	BENT	1,748.50	1,748.50
1	SLIDING DOOR	TO REPAIR SEE LABOUR	1,895.90	-
	LESS 25% DISCOUNT		-911.10	-437.13
			2,733.30	1,311.37
	LABOUR			
	TO PANEL BEAT AND REPAIR RIGHT SIDE BODY.TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS.INCLUSIVE OF THE REPAIR OF SLIDING DOOR.		650.00	500.00
	TO SPRAY PAINTING.		700.00	500.00
	TO APPLY TUFF KOTE.		50.00	50.00
			1,400.00	1,050.00
	GRAND TOTAL		4,133.30	2,361.37
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00

Report Ref No. CS/FCI19020711/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.