



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 35148

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
AIG ASIA PACIFIC INSURANCE PTE LTD

DATE : 11/09/2019
CLAIM NO. : 11467
POLICY NO. : AVFMSB0000651901

FROM : HASRIANAH

VEHICLE NO. : FBN1635P
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN <i>cut</i> P/N: 58094	REPLACE	1.00	\$34.00	34.00
2	BOARD FOOTREST LH <i>X cut NN</i> P/N: 59588	REPLACE	1.00	\$52.00	52.00
3	BOARD FOOTREST RH <i>cut</i> P/N: 59589	REPLACE	1.00	\$52.00	52.00
4	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220	REPLACE	1.00	\$208.00	208.00
5	COVER CLUTCH OUTER <i>X cut</i> P/N: 58147	REPLACE	1.00	\$28.00	28.00
6	COVER CLUTCH OUTER DAMPER 1 <i>X NN</i> P/N: 58111	REPLACE	1.00	\$12.00	12.00
7	COVER CLUTCH OUTER DAMPER 2 <i>X</i> P/N: 58172	REPLACE	1.00	\$7.00	7.00
8	COVER CLUTCH OUTER DAMPER 3 <i>X</i> P/N: 58107	REPLACE	1.00	\$7.00	7.00
9	COVER CLUTCH OUTER DAMPER 4 <i>X</i> P/N: 58140	REPLACE	1.00	\$12.00	12.00
10	COVER SIDE CENTRE RH (WHITE) <i>X</i> P/N: 58117	REPLACE	1.00	\$30.00	30.00
11	COWLING FRONT RH (WHITE) <i>cut</i> P/N: 59594	REPLACE	1.00	\$38.00	38.00
12	EMBLEM (YAMAHA) LOGO <i>MC</i> P/N: 57069	REPLACE	2.00	\$11.00	22.00
13	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$294.00	<i>200</i> 294.00

*35148 *

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
14	LEVER BRAKE RH / cut. P/N: 58185	REPLACE	1.00	\$18.00	18.00
15	MIRROR RH / cut. P/N: 58187	REPLACE	1.00	\$37.00	37.00
16	MUDGUARD FRONT (WHITE) / cut. P/N: 58087	REPLACE	1.00	\$52.00	52.00
17	NUT SPRING / ntc. P/N: 59586	REPLACE	4.00	\$2.00	8.00
18	PANEL 1 / cut P/N: 59584	REPLACE	1.00	\$19.00	19.00
19	PANEL 2 X ntc. P/N: 58081	REPLACE	1.00	\$22.00	22.00
20	PROTECTOR EXHAUST / cut. P/N: 58086	REPLACE	1.00	\$38.00	38.00
21	SCREW TAPPING / ntc. P/N: 45991	REPLACE	8.00	\$2.00	16.00
22	STICKER (CISCO) COWLING FRONT RH / ntc. P/N: 58617	REPLACE	1.00	\$37.00	37.00 SN
23	STICKER (CISCO) MUDGUARD FRONT / ntc. P/N: 58618	REPLACE	1.00	\$37.00	37.00 SN
24	TRANSPORT CHARGES P/N: 07169		1.00	\$49.00	49.00 35

SUB TOTAL

\$1,129.00

GST @ 7 %

\$79.03

GRAND TOTAL

\$1,208.03

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

3 Days.
part by part.
before paint photos.
Gmo Qian - 82880282
21/11/19.

Acknowledge & Accepted By

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*35148 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0363
ISO 9001: 2015