

A.S. REC. BY:

REP: CS/FCI/9020713/Kfd3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): ^{OWS} Mexira chira

of FEI

Date/Time: 12:33pm 22/11/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 5271R

Insured: SHA 87924

at Workshop n/s: Trucks-cab

Tel: G2876666

of No-2 Trak St-63

Policy No:

Claim No: D19007395MPH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 18/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS ^{ups}

H.O.D. Endorsement:

Date/Time: 12:59pm 22/11/19

Person Contacted: Candy

Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimate	(✓)
	SHC 5271R - CC3/TMI/9020090/Kfd3		DOA: 9/11/19
	SHA 87924 - CS/FCI/9002946/Aqd3		DOA: 14/12/2019
25/11/19	revised via email preli advice		

ASS. REC. BY:

REF: P021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Ceb

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 242 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHG5271R Yr Regn: 03, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Latitude c.c 1995

Colour M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading 400783 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABL15AUC 276709

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front	Rear
R/Bal. <u>9</u> mm	R/Bal. <u>9</u> mm
L/Bal. <u>9</u> mm	L/Bal. <u>9</u> mm
D.O.A. <u>18/11/19</u>	D.O.I. <u>22/11/19</u>

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to</u> <u>Cost injury</u>
	<u>21 Rep @ 33501 (Red: 21414.35; 85%)</u>

RECEIVED 25 NOV 2019

Date/Time, File Pass to?

: Prel. Report

: Final Report

1) 22/11/19

Date/Time, File Return to?

Days Of Repair: 2.5

Resurvey No. of Trip: _____

Survey Fee:

Transportation: _____ \$ + RS. _____ SI

Fuel/Oil

Others

TOTAL

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$ 33501-)

350



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007395MFSH

Date: 25/11/2019

Our Ref: CS/FCI19020713/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5271R

Please be informed that we had conducted the inspection of the abovementioned vehicle 22/11/2019 at the premises of M/s Trans-cab have the following to report: -

Workshop Estimate Amount	: S\$ <u>24,964.35</u>
Revised Estimate Amount	: S\$ <u>4,169.12</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the Rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	21-11-2019	Our Ref No. D19007395MFSH
Accident Date	18-11-2019	Claim Type. Third Party
Insured Vehicle	SHA8792U	Third Party Vehicle. SHC5271R
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Monday, 25 November 2019 1:52 PM
To: Denise Tay (LKKAuto)
Subject: FW: SHC 5271R / FIRST CAPITAL / DOA: 18/11/2019 -- AAD1911-153
Attachments: SHC 5271R EST.pdf

Hi Denise

Amount confirmed \$ 3,350 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Monday, 25 November, 2019 11:58 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: SHC 5271R / FIRST CAPITAL / DOA: 18/11/2019

Dear Wai Yin,

Lump sum \$3350, 2.5days

Please check and get back confirmation

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 25 November 2019 11:52 AM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Merina Chia'; SUR
Subject: RE: SURVEY ASSESSMENT - D19007395MFSH/1
Attachments: PRELI ADVISED OF SHC 5271R.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHC 5271R**
Number of days (estimated) : 2.5 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 22 November 2019 1:00 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19007395MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 22 November 2019 12:23 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007395MFSH/1

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHC5271R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Nov 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000811
Chassis No.:	VF1ABL15AUC276709
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	07 Mar 2014
First Registration Date:	07 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Mar 2022
PARF Rebate Amount:	\$8,748.00
Intended COE Rebate Details	
COE Expiry Date:	06 Mar 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$58,745.00
COE Rebate Amount:	\$16,837.00
Total Rebate Amount:	\$25,585.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 19 Nov 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5271R

AAD1911-153

*Not Authored
L1 Bny @ 3350/*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

22/11/2019

SHC 5271R
VF1ABL15AUC276709
RENAULT
LATITUDE
18.11.19
FCIL
7/3/2014

	PART	LIST		
1	1 BUMPER COVER REAR	\$ Bu 561.70	✓	
2	1 BUMPER LOWER REAR	\$ Dal/Lu 411.90	✓	
3	1 BUMPER BRACKET CTR REAR	\$ Su 98.10	} X	
4	1 BUMPER BRACKET SIDE RH REAR	\$ Su 82.10		
5	1 BUMPER RETAINER RH REAR	\$ Su 59.80		
6	1 BUMPER REFLECTOR RH	\$ Su 16.60		
7	1 BUMPER BRACKET SIDE LH REAR	\$ Su 80.80		
8	1 BUMPER RETAINER LH REAR	\$ Su 54.20		
9	1 BUMPER REFLECTOR LH	\$ Su 16.60	} X	
10	1 BUMPER BEAM REAR	\$ Bu 547.80		✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ K 114.50		} X
12	1 BUMPER BEAM BRACKET RH REAR	\$ K 100.90		
13	1 OUTER PANEL REAR (End Panel)	\$ K 745.80		
14	1 OUTER PANEL REAR (End Panel) TRIM	\$ Su 404.56		
15	1 TAILLAMP RH	\$ Su 313.10		
16	1 TAILLAMP PANEL RH	\$ K 401.40		
17	1 TAILLAMP LH	\$ Su 401.40	} X	
18	1 TAILLAMP PANEL LH	\$ K 401.40		
19	1 BOOT REAR	\$ Bu 1,677.20	✓	
20	1 BOOT FINISHER	\$ Su 344.70	X	
21	1 BOOT WHEATERSTRIP	\$ Su 178.20	X	
22	1 BOOT REFLECTOR LAMP LH	\$ Su 277.70	X	
23	1 BOOT REFLECTOR LAMP RH	\$ Su 277.70	X	
24	1 BOOT BADGE 'RENAULT'	\$ Nu 82.40	✓	
25	1 BOOT BADGE	\$ Nu 95.80	✓	
26	1 BOOT STRUT LH	\$ Su 145.10	X	

Trans-cab Auto Services Pte Ltd

AAD1911-153

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5271R

20	1	EXHAUST MOUNTING REAR	\$	<i>nn</i> 16.00	X
TOTAL			\$	1,482.20	
TOTAL PARTS			\$	10,454.35	

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>601</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>301</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>151</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>3001</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>4</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	X
To repair and realign rear exhaust pipe.	\$	<i>4</i> 170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1911-153

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5271R

27	1	BOOT STRUT RH	\$	Su	145.10	}
28	1	BOOT HINGE LH	\$	n	254.20	
29	1	BOOT HINGE RH	\$	n	253.80	
30	2	BOOT RUBBER PLUG	\$	Su	139.90	
31	2	BOOT BUFFER	\$	Su	26.80	
32	1	BOOT LOCK LINKAGE	\$	Su	20.60	
33	1	BOOT LOCK LINKAGE HOLDER	\$	Su	99.50	
34	1	BOOT INNER TRIM BOARD	\$	Su	611.00	
35	1	BOOT SWITCH	\$	Su	113.00	
36	1	BOOT LOCK	\$	n	246.60	
37	1	BOOT LOCK CATCH	\$	Su	41.70	
38	1	EXHAUST CAP REAR	\$	Su	125.40	
TOTAL			\$		9,969.06	
10%			\$		996.91	
			\$		8,972.15	

Special Nett

1	1SET	PARKING AID	\$	Su	700.00	X
2	1SET	REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00	✓
11	1	BOOT STICKER "6555-3333"	\$	na	30.00	✓
12	2	REAR WINDSCREEN SEALANT	\$	na	80.00	}
13	1	WINDSCREEN MOULDING	\$	na	100.00	
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
15	1	BOOT INNER TRIM CLIP	\$	na	45.00	
16	1SET	BOOT FINISHER CLIP	\$	na	24.20	
17	1	TAILLAMP CLIP LH	\$	na	5.00	
18	1	TAILLAMP CLIP RH	\$	na	5.00	
19	1	Rear Bumper Protector	\$	na	100.00	X

Trans-cab Auto Services Pte Ltd

AAD1911-153

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5271R

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nr* 380.00 *X*

Putty and spray painting of the affected portion.

\$ 6,000.00 *440*

TOTAL \$ 14,510.00

Over All Total \$ 24,964.35

LUMP SUM (REPAIR DAY)

~~20 DAYS~~

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19020713/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-11-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 8792U	Veh. Inspected	SHC 5271R
Policy No.		Coverage (\$)	0.00
Claim No.	D19007395MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	22/11/2019
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC276709	Colour	METALLIC WHITE / RED
Odometer	400783	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	GITI	9 mm
L/H Rear Tyre	215/60 R16	GITI	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/11/2019	Inspection Date	22/11/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2.500 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5271R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR	BUCKLED	561.70	561.70
1	BUMPER LOWER REAR	DENTED / CUT	411.90	411.90
1	BUMPER BRACKET CTR REAR	SERVICEABLE	98.10	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	82.10	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	59.80	-
1	BUMPER REFLECTOR RH	SERVICEABLE	16.60	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	80.80	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	54.20	-
1	BUMPER REFLECTOR LH	SERVICEABLE	16.60	-
1	BUMPER BEAM REAR	BENT	547.80	547.80
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	114.50	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	100.90	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	745.80	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	TAILLAMP RH	SERVICEABLE	313.10	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	401.40	-
1	TAILLAMP LH	SERVICEABLE	401.40	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	401.40	-
1	BOOT REAR	BENT	1,677.20	1,677.20
1	BOOT FINISHER	SERVICEABLE	344.70	-
1	BOOT WEATHERSTRIP	SERVICEABLE	178.20	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	277.70	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	277.70	-
1	BOOT BADGE "RENAULT"	NECESSARY	82.40	82.40
1	BOOT BADGE	NECESSARY	95.80	95.80
1	BOOT STRUT LH	SERVICEABLE	145.10	-
1	BOOT STRUT RH	SERVICEABLE	145.10	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	254.20	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	253.80	-
2	BOOT RUBBER PLUG	SERVICEABLE	139.90	-
2	BOOT BUFFER	SERVICEABLE	26.80	-
1	BOOT LOCK LINKAGE	SERVICEABLE	20.60	-
1	BOOT LOCK LINKAGE HOLDER	SERVICEABLE	99.50	-
1	BOOT INNER TRIM BOARD	SERVICEABLE	611.00	-
1	BOOT SWITCH	SERVICEABLE	113.00	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	246.60	-
1	BOOT LOCK CATCH	SERVICEABLE	41.70	-
1	EXHAUST CAP REAR	SERVICEABLE	125.40	-
	LESS 10% DISCOUNT		-996.91	-337.68
			8,972.15	3,039.12
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-

Report Ref No. CS/FCI19020713/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	100.00	-
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	16.00	-
			1,482.20	225.00
	LABOUR			
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, OUTER PANEL REAR (END PANEL), TAILLAMP PANEL RH, TAILLAMP PANEL LH, BOOT HINGE LH, BOOT HINGE RH AND BOOT LOCK.		6,000.00	300.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	440.00
			14,510.00	905.00

Report Ref No. CS/FC119020713/Ktd3n2



GRAND TOTAL		24,964.35	4,169.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,350.00

Report Ref No. CS/FCI19020713/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.