



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0117394 / MS FIRST CAPITAL
Chassis No: JHMRU1810GX200697
License No: SLG9508P
Mileage: 78206
Engine No: L15B4530698

Document No: SVO19078244
Printed By: ARYCHUA
Order Date: 10. December 2019
Order Time: 9:52:36 AM
Service Advisor: ARY CHUA WAI NGE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 73827) OWNER: BELLE ONG YAN WEN OWNER INSURER: SOMPO INSURANCE PTE LTD ACC DATE: 20/11/2019@16.35PM ACC: T/J PASIR RIS ST 72 (L/P 13)-PASIR RIS DR 12 SURVEYED BY:MARCUS CHUA(LKKAUTO)10/12/2019@10.10AM REF NO: D19007399MFSH TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHA9172C - HYUNDAI/I40/YELLOW CAB						
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
74410-T7B-003	PROTECTOR,R,RR.WHEEL ARCH	1	180.10	25	135.07	9.45	144.52
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	15.90	25	11.92	0.83	12.75
75722-T7W-A01	EMBLEMRR.	1	14.60	25	10.95	0.77	11.72
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1	96.50	25	72.37	5.07	77.44
71593-T7A-J00	SPACER,R,RR.BUMPER SIDE	1	17.30	25	12.97	0.91	13.88
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.21	18.46
	SUM PARTS:				608.30	42.58	650.88
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BML02I	0760 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	100.00		100.00	7.00	107.00
BA02R	1864 REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BKBU02R	1864 RENEW RR BUMPER & STRAIGHTEN RHR FENDER & TAILGATE	1	560.00		560.00	39.20	599.20
BP03R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	900.00		900.00	63.00	963.00
	SUM LABOUR:				1,710.00	119.70	1,829.70
	TOTAL SGD				2,318.30	162.28	2,480.58
	Total Payable (SGD)						2,480.58

GST Amount is calculated from individual line(s)