

Pass to Asher, Thad's

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
Date 21/11/2019
Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLT5230Y
Chassis No: JM6BN22ABH0157895
MAKE / MODEL: Mazda 3 Sedan 1.5 AT
DATE OF ACCIDENT: 20/11/2019
YOUR INSURED VEHICLE NUMBER: SKR8410Y
MILEAGE: 138059 km

PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1 Rear bumper / DP	1PC	\$1,129.00	\$1,129.00 ✓
2 Rear bumper reinforcement X SVC	1PC	\$564.20	\$564.20 X
3 Rear boot X R.	1PC	\$1,005.30	\$1,005.30 X
4 Rear boot Mazda emblem X SVC	1PC	\$78.50	\$78.50 X
5 Rear boot SKYACTIV emblem X SVC	1PC	\$66.80	\$66.80 X
6 Rear boot M logo X SVC	1PC	\$56.10	\$56.10 X
7 Rear end panel / DP	1PC	\$530.40	\$530.40 ✓
8 Rear bumper RH reflector X SVC	1PC	\$153.40	\$153.40 X
9 Rear bumper LH reflector X SVC	1PC	\$153.40	\$153.40 X
10 Rear bumper LH retainer / BR	1PC	\$58.15	\$58.15 ✓
11 Rear bumper RH retainer / DR	1PC	\$58.15	\$58.15 ✓
12 Rear bumper RH tow cover / MIS	1PC	\$40.00	\$40.00 ✓
			\$3,795.25 1,815.7
		20% DISCOUNT SS:	\$759.05
			\$3,036.20

S/Nett

1 Bumper clips	\$100.00 30
2 Reverse sensor	\$240.00 200
Total	\$340.00

LABOUR CHARGES

- 1 To labour charge for removing out rear boot, rear bumper and end panel out to facilitate repairs and replacement of damaged parts \$900.00 700
- 2 To respray rear boot, rear bumper, end panel and spare tyre panel \$900.00 500

LABOUR TOTAL SS:	\$1,800.00
TOTAL SS:	\$5,176.20
7% GST	\$362.33
GRAND TOTAL SS:	\$5,538.53

Repair by

5 days.

Sun Pin (LKK)

20/11/2019

Tp without pre-judge.

Lump Sum Repair.

After spray photo

$$\begin{array}{r} 1,815.7 \\ - 20\% \\ \hline P = 1,452.56 \\ M = 230 \\ L = 1,200 \\ \hline 2,882.56 \\ - 20\% \\ \hline 2,306.05 \end{array}$$

$$L/S = 2,300$$

5 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
Date 21/11/2019
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLT5230Y
Chassis No: JM6BN22A8H0157895
MAKE / MODEL : Mazda 3 Sedan 1.5 AT
DATE OF ACCIDENT : 20/11/2019
YOUR INSURED VEHICLE NUMBER :SKR8410Y
MILEAGE : 138059 km

PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1 Rear bumper / DP	1PC	\$1,129.00	\$1,129.00
2 Rear bumper reinforcement / XSV	1PC	\$564.20	\$564.20
3 Rear boot / R	1PC	\$1,005.30	\$1,005.30
4 Rear boot Mazda emblem / XSV	1PC	\$78.50	\$78.50
5 Rear boot SKYACTIV emblem / XSV	1PC	\$66.80	\$66.80
6 Rear boot M logo / XSV	1PC	\$56.10	\$56.10
7 Rear end panel / DP	1PC	\$530.40	\$530.40
8 Rear bumper RH reflector / XSV	1PC	\$153.40	\$153.40
9 Rear bumper LH reflector / XSV	1PC	\$153.40	\$153.40
10 Rear bumper LH retainer / BR	1PC	\$58.15	\$58.15
11 Rear bumper RH retainer / BR	1PC	\$58.15	\$58.15
12 Rear bumper RH tow cover / MIS	1PC	\$40.00	\$40.00
			\$3,795.25
		20% DISCOUNT S\$:	\$759.05
			\$3,036.20

S/Nett

1 Bumper clips	\$100.00
2 Reverse sensor	\$240.00
Total	\$340.00

LABOUR CHARGES

- To labour charge for removing out rear boot, rear bumper and end panel out to facilitate repairs and replacement of damaged parts. \$900.00 ~~200.00~~ 700
- To respray rear boot, rear bumper, end panel and spare tyre panel. \$900.00 ~~300.00~~ 500

LABOUR TOTAL S\$:	\$1,800.00
TOTAL S\$:	\$5,176.20
7% GST	\$362.33
GRAND TOTAL S\$:	\$5,538.53

Repair day ~~3 days~~ 5 days.

Sun Pm (Lkk).
20/11/2019
Tp without prejudice.

Lump Sum. Repair.
After spray photo ✓

Lump sum \$2,300.00
5 day

$$P = 1,815.7$$

$$- 20\%$$

$$1,452.56$$

$$N = 230$$

$$L = 1,200$$

$$2,882.56$$

$$- 20\%$$

$$2,306.05$$

$$L/S = 2,300$$

$$1,815.70$$

$$363.14$$

$$1,452.56$$

$$230.00$$

$$1,200.00$$

$$2,882.56$$

Oi Sun Pin (LKK Auto)

From: Siak Tong Sim <siaktong@lioncityrentals.com.sg>
Sent: Wednesday, 18 December, 2019 7:30 AM
To: Oi Sun Pin (LKK Auto)
Subject: Re: Final Bill: SLT5230Y

Sun Pin

Ok confirmed lump sum \$2,300.00/5 days

Regards

S.T.Sim (65-97422188)


Manager

Accident Reporting Center

60 Jalan Lam Huat

#04-35/36 Carros Centre

Singapore 737869



On Tue, Dec 17, 2019 at 6:02 PM Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com> wrote:

Dear Mr Sim,

Kindly refer the finalize amount \$2,300. Repair days 5 days. (L/S repair, before gst).

If agree please reply .

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)