

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms:AIG Asia Pacific Insurance Pte Ltd

Date: 21/11/2019

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLH360B

CHASSIS NO : JTDKB3FU703536490

MAKE / MODEL : Toyota Pirus 1.8 Hybrid

DATE OF ACCIDENT : 20/11/2019

YOUR INSURED VEHICLE NUMBER :SLR4755S

MILEAGE : 220078 Km

| | <u>PARTS DESCRIPTION</u> | <u>QTY</u> | <u>UNIT PRICE</u> | <u>LIST PRICE</u> |
|----------------------|---|------------|-------------------|-------------------|
| 1 | Rear bumper / cut. | 1PC | \$423.90 | \$423.90 |
| 2 | Rear bumper center pad / Nec. | 1PC | \$552.30 | \$552.30 |
| 3 | Rear bumper RH retainer / BR | 1PC | \$112.70 | \$112.70 |
| 4 | Rear bumper LH retainer X SVC | 1PC | \$112.70 | \$112.70 |
| 5 | Rear bumper reinforcement ? | 1PC | \$318.80 | \$318.80 |
| 6 | Rear bumper underside RH cover X SVC | 1PC | \$133.60 | \$133.60 |
| 7 | Rear bumper lower cover X SVC | 1PC | \$303.90 | \$303.90 |
| 8 | Rear bumper RH side extension filler X SVC. | 1PC | \$148.40 | \$148.40 |
| 9 | Rear bumper tow cover X SVC | 1PC | \$35.90 | \$35.90 |
| 10 | Rear end panel ? | 1PC | \$356.80 | \$356.80 |
| 11 | Rear end panel top garnish X SVC. | 1PC | \$105.30 | \$105.30 |
| 12 | R/R combination lamp / CRA | 1PC | \$433.70 | \$433.70 |
| 13 | R/R lamp len and body X SVC. | 1PC | \$481.90 | \$481.90 |
| LIST TOTAL S\$: | | | | \$3,519.90 |
| 25.00% DISCOUNT S\$: | | | | \$879.98 |
| | | | | \$2,639.93 |

SPECIAL NETT

| | | | | |
|-------------------------|----------------------------|-------|----------|----|
| 1 | Bumper and end panel clips | 1 SET | \$200.00 | 30 |
| 2 | Reverse sensor X SVC | 1 SET | \$260.00 | X |
| Special Nett Total S\$: | | | \$460.00 | |

LABOUR CHARGES

- 1 To labour charge for removing rear bumper, rear bumper reinforcement out to facilitate replacement of damaged parts *Repair boot garnish* \$900.00 *300*
- 2 To respray rear bumper, end panel rear boot \$900.00 *400*
- 3 To conduct a standard of operating procedures post scan test as requirements for hybrid cars upon completion of collision repairs \$300.00 *X*
- 4 To deactivate and activate high voltage hybrid battery as a requirement for safety precautions \$300.00 *X*

| | |
|-------------------|--------------------------|
| LABOUR TOTAL S\$: | <u>\$2,400.00</u> |
| TOTAL S\$: | \$5,499.93 |
| 7% GST | <u>\$384.99</u> |
| GRAND TOTAL S\$: | <u><u>\$5,884.92</u></u> |

Repair day - 3 days.

Sun Pm (Akl)

20/11/2019.

T.P without prejudice.

Lump Sum Repair

After Spray photo.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: