

LCRF PTE LTD  
CARROS CENTER  
60 JALAN LAM HUAT #04-01 S(737869)  
Main +65 62524991

Ms:AIG Asia Pacific Insurance Pte Ltd

Date: 21/11/2019

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLH360B

CHASSIS NO : JTDKB3FU703536490

MAKE / MODEL : Toyota Pirus 1.8 Hybrid

DATE OF ACCIDENT : 20/11/2019

YOUR INSURED VEHICLE NUMBER : SLR47555

MILEAGE : 220078 Km

|    | PARTS DESCRIPTION                          | QTY | UNIT PRICE           | LIST PRICE         |
|----|--------------------------------------------|-----|----------------------|--------------------|
| 1  | Rear bumper / C4t.                         | 1PC | \$423.90             | \$423.90 /         |
| 2  | Rear bumper center pad / Nec.              | 1PC | \$552.30             | \$552.30 /         |
| 3  | Rear bumper RH retainer / BR               | 1PC | \$112.70             | \$112.70 83        |
| 4  | Rear bumper LH retainer X SVC              | 1PC | \$112.70             | \$112.70           |
| 5  | Rear bumper reinforcement ?                | 1PC | \$318.80             | \$318.80 X SVC     |
| 6  | Rear bumper underside RH cover X SVC       | 1PC | \$133.60             | \$133.60           |
| 7  | Rear bumper lower cover X SVC              | 1PC | \$303.90             | \$303.90           |
| 8  | Rear bumper RH side extension filler X SVC | 1PC | \$148.40             | \$148.40           |
| 9  | Rear bumper tow cover X SVC                | 1PC | \$35.90              | \$35.90            |
| 10 | Rear end panel ?                           | 1PC | \$356.80             | \$356.80 X R       |
| 11 | Rear end panel top garnish X SVC           | 1PC | \$105.30             | \$105.30           |
| 12 | R/R combination lamp / CRA                 | 1PC | \$433.70             | \$433.70 /         |
| 13 | R/R lamp lens and body X SVC               | 1PC | \$481.90             | \$481.90           |
|    |                                            |     | LIST TOTAL S\$:      | \$3,519.90 1,492.9 |
|    |                                            |     | 25.00% DISCOUNT S\$: | \$879.98           |
|    |                                            |     |                      | \$2,639.93         |

1,522.60  
380.65  
1,141.95

SPECIAL NETT

|   |                            |       |                         |
|---|----------------------------|-------|-------------------------|
| 1 | Bumper and end panel clips | 1 SET | \$200.00 30             |
| 2 | Reverse sensor X SVC       | 1 SET | \$260.00 X              |
|   |                            |       | Special Nett Total S\$: |
|   |                            |       | \$460.00                |

30.00

$$P = 1,492.9 - 25\% = 1,119.68$$

$$N = 30$$

$$L = 700$$

$$1,849.68$$

$$- 20\%$$

$$1,479.74$$

L/S

\$ 1,450

3 days

### LABOUR CHARGES

- 1 To labour charge for removing rear bumper, rear bumper reinforcement out to facilitate replacement of damaged parts Repair boot garnish \$900.00 300
- 2 To respray rear bumper, end panel rear boot \$900.00 400.
- 3 To conduct a standard of operating procedures post scan test as arequirements for hybrid cars upon completion of collision repairs \$300.00 X nn
- 4 To deactivate and activate high voltage hybrid battery as a requirement for safety precautions \$300.00 Xnn 7w

|                   |                   |
|-------------------|-------------------|
| LABOUR TOTAL S\$: | \$2,400.00        |
| TOTAL S\$:        | \$5,499.93        |
| 7% GST            | \$384.99          |
| GRAND TOTAL S\$:  | <u>\$5,884.92</u> |

Repair day - 3 days.

Jun Pm Akk  
20/11/2019.  
TP without prejudice.

Lump Sum Repair  
After-Spray photo.

|        |                 |
|--------|-----------------|
| Parts  | 1,141.95        |
| SN     | 30.00           |
| Labour | 700.00          |
|        | <u>1,871.95</u> |

Lump sum \$1,450.00  
3 days