

LCRF PTE LTD
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms:AIG Asia Pacific Insurance Pte Ltd
Date: 21/11/2019
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLH360B
CHASSIS NO : JTDKB3FU703536490
MAKE / MODEL : Toyota Pirus 1.8 Hybrid
DATE OF ACCIDENT : 20/11/2019
YOUR INSURED VEHICLE NUMBER : SLR47555
MILEAGE : 220078 Km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

	PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1	Rear bumper / C4t.	1PC	\$423.90	\$423.90 /
2	Rear bumper center pad / Nec.	1PC	\$552.30	\$552.30 /
3	Rear bumper RH retainer / BR	1PC	\$112.70	\$112.70 83
4	Rear bumper LH retainer X SVC	1PC	\$112.70	\$112.70
5	Rear bumper reinforcement ?	1PC	\$318.80	\$318.80 X SVC
6	Rear bumper underside RH cover X SVC	1PC	\$133.60	\$133.60
7	Rear bumper lower cover X SVC	1PC	\$303.90	\$303.90
8	Rear bumper RH side extension filler X SVC	1PC	\$148.40	\$148.40
9	Rear bumper tow cover X SVC	1PC	\$35.90	\$35.90
10	Rear end panel ?	1PC	\$356.80	\$356.80 X R
11	Rear end panel top garnish X SVC	1PC	\$105.30	\$105.30
12	R/R combination lamp / CRA	1PC	\$433.70	\$433.70 /
13	R/R lamp lens and body X SVC	1PC	\$481.90	\$481.90
LIST TOTAL S\$:				\$3,519.90 1,492.9
25.00% DISCOUNT S\$:				\$879.98
				\$2,639.93

1,522.60
380.65
1,141.95
30.2

SPECIAL NETT

1	Bumper and end panel clips	1 SET	nec	\$200.00 30
2	Reverse sensor X SVC	1 SET		\$260.00 X
Special Nett Total S\$:				\$460.00

1,492.9
- 25%
P = 1,119.68
N = 30
L = 700
1,849.68
- 20%
1,479.74

L/S
\$ 1,450
3 days

LABOUR CHARGES

- 1 To labour charge for removing rear bumper, rear bumper reinforcement out to facilitate replacement of damaged parts Repair boot garnish \$900.00 300
- 2 To respray rear bumper, end panel rear boot \$900.00 400.
- 3 To conduct a standard of operating procedures post scan test as arequirements for hybrid cars upon completion of collision repairs \$300.00 X nn
- 4 To deactivate and activate high voltage hybrid battery as a requirement for safety precautions \$300.00 Xnn 7w

LABOUR TOTAL S\$:	\$2,400.00
TOTAL S\$:	\$5,499.93
7% GST	\$384.99
GRAND TOTAL S\$:	<u>\$5,884.92</u>

Repair day - 3 days.

Jun Pm Akk
20/11/2019.
TP without prejudice.

Lump Sum Repair
After-Spray photo.

Parts	1,141.95
SN	30.00
Labour	700.00
	<u>1,871.95</u>

Lump sum \$1,450.00
3 days