

ASS. REC. BY:

REF: CS/FWD 1902747/Agf382

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Eileen Bay

of FWD

Date/Time: 22. Nov. 19 18:49 p.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 94564

Insured:

at Workshop m/s

Progressive car

Tel:

67415336

of

BIC 3022 A Ubi Rd 1 #01-45/46

Policy No:

PNPV2019-00014628

Claim No:

1201900036182

Sum Insured:

Excess:

1000

Make of Vch:

D.O.A.

21.11.2019

(Client's Record)

CA / REV

/ REP. / REV 24 HRS

Date/Time:

25.11.19 9:39 a.m.

Person Contacted:

Pei Wen

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLR 94564 -
25/11/19 @ 5:08pm	request to Eileen Bay via Messenger
26/11/19 @ 10:30am	Bar Eileen Bay informed c/a via Messenger.
26/11/19 @ 2:33pm	informed Pei Wen c/a & EX: \$1000 by email.
20/07/20 @ 2:45pm	and request to Eileen Bay via Messenger. (supplementary)
24/11/20 @ 5:11pm	Eileen Bay informed c/a at \$8511 via Messenger.

ASS. FWD BY:

REF: FWD

Adrian

ASSIGNMENT

From: _____ Date: 25.11.2019

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: SLR 94564

at Workshop m/s Progressive Car

of Bik 3022 A Ubi Rd 1 #01-45/46

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$1000.00

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 83K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLR94564 Yr Regn: 2017, August

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: Honda Freed Hybrid . cc 1496

Colour: Black Acc: Insured / Std / NI / NA

Sp. Reading: 26355 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: G871020802

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: 185/65R15

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 25/11/19

Survey held at Progressive (Ubi)

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD FWD.

25/11/2019 @ 3.10pm confirmed with Ray final fig \$8511, 7 days.
(Red \$2290, 11%)

RECEIVED - FEB 2020

Date/Time, File Pass to?

25/12/2019 ☐ : Preli. Report

Date/Time, File Return to?

21

Rep. Form(s):

Long Form / Print:

MED-09

8511

Days Of Repair: 7Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Insp (\$ _____)☐ : Meet and (\$ _____)

Survey Fee:

Transportation:

S + RS \$

Photos

Other

TOTAL

290

50

90

11

361

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Nov 2019 Sendback Est	22 Nov 2019 17:50 S\$10,621.00	22 Nov 2019 18:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	ANG CHUEAN WEE KELVIN, ID: S7703074C, Tel: +6591704824, Email: SUNAKEL24@GMAIL.COM								
Vehicle Reg. No.:	SLR9456Y	Date of Loss:	21/11/2019 18:00 - :59 [26 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 1201900036182	Policy/Cover Note No.:	PNPV2019-00014628 (Comprehensive)						
		Excess:	S\$1,000.00						
Repairer:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/12/2019]								
Driver/Custodian:	ANG CHUEAN WEE KELVIN (42 / Male), NRIC: S7703074C, Tel: +6591704824 Email: SUNAKEL24@GMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 25 February 2020 3:10 PM
To: Ray
Cc: SUR
Subject: RE: SLR9456Y - TO FINALIZE

Dear Ray,

WITHOUT PREJUDICE

Confirm final fig \$8,511.00 before excess \$1,000.00 & GST and 7 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray <ray@procarcare.com.sg>
Sent: Thursday, 20 February 2020 9:53 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: FW: SLR9456Y - TO FINALIZE

Regards,

Ray Lin

Damage Assessment

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg



IMPORTANT NOTICE: The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof.

From: Ray
Sent: Thursday, February 20, 2020 9:52 AM
To: 'Shiau Chan (LKKAUTO)'
Subject: FW: SLR9456Y - TO FINALIZE

Hi Shiau Chan,

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	22 Nov 2019 17:01	Cim Veh Model Changed	(206097) HONDA FREED HYBRID 1.5 (A).		[R] Lily Lim
2	22 Nov 2019 17:01	Cim Created	Reg No: SLR9456Y, Policy No: PNPV2019-00014628, Acct Date: 2019/11/21, Claim Type: OD, Insurer: FWD Singapore Pte. Ltd. (HQ), Workshop: Progressive Car Care Pte Ltd (HQ), Created from SAS:M PA219154154		[R] Lily Lim
3	22 Nov 2019 17:50	Cim Submitted	10621.00.		[R] Lily Lim
4	22 Nov 2019 18:48	Cim Registration Modified	Excess: -> 1000.00.		[I] Eileen Bay
5	22 Nov 2019 18:49	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : LK K Auto Consultants Pte Ltd.		[I] Eileen Bay
6	22 Nov 2019 18:49	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/12/03		[I] Eileen Bay
7	22 Nov 2019 18:49	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.		[I] Eileen Bay
8	25 Nov 2019 08:17	Assignment 1st Accessed			[A] Nivitha Govindasamy
9	25 Nov 2019 09:52	Adj Adjuster Assigned	[None] -> ADRIAN LING		[A] LEE SU THING
10	25 Nov 2019 17:05	Adj Rpt Initiated			[A] SHIAU CHAN
11	25 Nov 2019 17:08	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/12/03		[A] SHIAU CHAN
12	25 Nov 2019 17:08	Adj Mandate Request	Cur.Reg:9850.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL, WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
13	25 Nov 2019 17:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/12/03, Mandate Remarks: Please update surveyor recommendation in the adjuster report to seek our mandate		[I] Eileen Bay
14	25 Nov 2019 17:13	Adj Mandate Set	Maintained:Please update surveyor recommendation in the adjuster report to seek our mandate		[I] Eileen Bay
15	25 Nov 2019 17:35	Adj Mandate Request	Cur.Reg:9850.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL, WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
16	26 Nov 2019 10:23	Adj Next Rpt Changed	Cur Rpt:Final Rpt, Cur Due Date:2019/12/03, Mandate Remarks: Please re-seek mandate after check items are verified.		[I] Eileen Bay
17	26 Nov 2019 10:23	Adj Mandate Set	Approved:7900.00:Please re-seek mandate after check items are verified.		[I] Eileen Bay
18	12 Dec 2019 16:13	Cim Supp Created	(S:896248)		[R] Wendy Soo Yok Chu
19	12 Dec 2019 16:14	Cim Submitted	180.00.		[R] Wendy Soo Yok Chu
20	12 Dec 2019 16:14	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[R] Merimen Administrator
21	13 Dec 2019 09:55	Supp Combined	(S:896248)		[A] SHIAU CHAN
22	20 Feb 2020 14:30	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/12/03		[A] SHIAU CHAN
23	20 Feb 2020 14:45	Adj Mandate Request	Cur.Reg:8511.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL, KINDLY APPROVE ON SUPPLEMENTARY & CHECK ITEMS.		[A] SHIAU CHAN
24	24 Feb 2020 17:11	Adj Mandate Set	Approved:8511.00.		[I] Eileen Bay

Date From



Date To



Audit Type

None



Go

ACTIVITY

[14/01/2020 15:10] SHIAU CHAN:

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eileen Bay

Date: 20 Feb 2020

Preliminary Advice

Vehicle No	: SLR9456Y	Accident Date	: 21/11/2019
Make	: HONDA FREED HYBRID	Policy No.	: PNPV2019-00014628
Assignment Date	: 22/11/2019	Excess	: S\$1,000.00
Date of Inspection	: 25/11/2019	Est. Duration of Repair	: 7.00
Inspection At	: PROGRESSIVE CAR CARE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,801.00	(ESTIMATE \$10,621.00 + SUPPLEMENTARY \$180.00)
Revised Amount	:S\$	8,511.00	(INCLUSIVE OF SUPPLEMENTARY & CHECK ITEMS)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	8,511.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	42,453.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,547.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY & CHECK ITEMS.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 26 November 2019 2:33 PM
To: Peiwen; claims@procarcare.com.sg
Cc: SUR
Subject: OD VEHICLE SLR 9456Y (DOA: 21/11/2019)

Dear Pei Wen,

Instructed by our client, please proceed to repair the insured vehicle **SLR 9456Y (Excess \$1,000)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

Any check item or supplementary are subjected to further approval from our client.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	22 Nov 2019 17:01	Clim Veh Model Changed	(206097) HONDA FREED HYBRID 1.5 (A).		[R] Lily Lim
2	22 Nov 2019 17:01	Clim Created	Reg No: SLR9456Y. Policy No: PNPV2019-00014628. Acct Date: 2019/11/21. Claim Type: OD. Insurer: FWD Singapore Pte. Ltd. (HQ), Workshop: Progressive Car Care Pte Ltd (HQ). Created from SAS:MPA219154154		[R] Lily Lim
3	22 Nov 2019 17:50	Clim Submitted	10621.00.		[R] Lily Lim
4	22 Nov 2019 18:48	Clim Registration Modified	Excess: -> 1000.00.		[I] Eileen Bay
5	22 Nov 2019 18:49	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : LKK Auto Consultants Pte Ltd.		[I] Eileen Bay
6	22 Nov 2019 18:49	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/12/03		[I] Eileen Bay
7	22 Nov 2019 18:49	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.		[I] Eileen Bay
8	25 Nov 2019 08:17	Assignment 1st Accessed			[A] Nivitha Govindasamy
9	25 Nov 2019 09:52	Adj Adjuster Assigned	[None] -> ADRIAN LING		[A] LEE SU THING
10	25 Nov 2019 17:05	Adj Rpt Initiated			[A] SHIAU CHAN
11	25 Nov 2019 17:08	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/12/03		[A] SHIAU CHAN
12	25 Nov 2019 17:08	Adj Mandate Request	Cur.Req:9850.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE N OT AUTHORISE REPAIR.		[A] SHIAU CHAN
13	25 Nov 2019 17:13	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/12/03. Mandate Remarks: Please update survey or recommendation in the adjuster report to seek our mandate		[I] Eileen Bay
14	25 Nov 2019 17:13	Adj Mandate Set	Maintained:Please update surveyor recommendation in the adjuster report to seek our mandate		[I] Eileen Bay
15	25 Nov 2019 17:35	Adj Mandate Request	Cur.Req:9850.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE N OT AUTHORISE REPAIR.		[A] SHIAU CHAN
16	26 Nov 2019 10:23	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2019/12/03. Mandate Remarks: Please re-seek m andate after check items are verified.		[I] Eileen Bay
17	26 Nov 2019 10:23	Adj Mandate Set	Approved:7900.00:Please re-seek mandate after check items are verified.		[I] Eileen Bay

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2354216	22 Nov 2019 17:01:43	OD/TP Case (Repairer)	Motor	Progressive Automotive Pte Ltd	Progressive Car Care Pte Ltd (HQ)	SLR9456Y		XX.XX
2356093	25 Nov 2019 17:05:44	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLR9456Y		11.77

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eileen Bay

Date: 25 Nov 2019

Preliminary Advice

Vehicle No	: SLR9456Y	Accident Date	: 21/11/2019
Make	: HONDA FREED HYBRID	Policy No.	: PNPV2019-00014628
Assignment Date	: 22/11/2019	Excess	: S\$1,000.00
Date of Inspection	: 25/11/2019	Est. Duration of Repair	: 7.00
Inspection At	: PROGRESSIVE CAR CARE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,621.00
Revised Amount	:S\$	6,452.00
Check Items (Estimated)	:S\$	3,398.00
Total	:S\$	9,850.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	42,453.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,547.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	074C
Vehicle Details	
Vehicle No.:	SLR9456Y
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	FREED HYBRID 1.5G AUTO
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	LEB5544770
Chassis No.:	GB71020802
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$25,961.00
Original Registration Date:	31 Aug 2017
First Registration Date:	31 Aug 2017
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$49,899.00
COE Rebate Amount:	\$38,703.00
Total Rebate Amount:	\$42,453.00

The information contained herein is correct as at 22 Nov 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/11/2019 09:56
Date Of Accident	21/11/2019 18:00
Exact Location Of Accident	ALONG PIE TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR8456Y
Insured/Policyholder	
Name Of Registered Owner	ANG CHUEAN WEE KELVIN
NRIC No	S7703074C
Email Address	SUNAKEL24@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91704824
Alternative Phone No	OTHERS-91704824

Vehicle Particulars

Manufacturer	HONDA
Model	FREED HYBRID-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00014628
Cover Note Number	

Driver

Name of Driver	ANG CHUEAN WEE KELVIN
NRIC No	S7703074C
Date Of Birth	21/01/1977
Occupation	INDOOR
Date Of Driving Pass	21/12/1995
Driving Experience	23 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91704824
Fax Number	
Contact Number	OTHERS-91704824
EMail Address	SUNAKEL24@GMAIL.COM

Address	BLK 46 BENDEEMER ROAD #15-1429
Postcode	330046
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP660T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

22/11/19
0920 am

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

PIE towards Tnas

Vehicle
A-SLR9456Y
B-SLP660T

Legend
Vehicle
Motorcycle

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the evening of 21st Nov 2019, I was travelling home on the PIE towards Tuea. It just rained and the road was wet.

I was on the right lane behind SLP6607 when it suddenly came to a complete stop on the PIE. I floored my brakes, but my vehicle could not avoid the front vehicle.

I impacted the vehicle SLP6607 on its rear. I came down to check on the driver who also came out. ~~He~~ He was not injured and we exchange particulars.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please be advised that your Insurer may have a fourteen (14) days Clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time: 22/11/19
0920am

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____



PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/ 46 S408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 1119-7260
Policy No:	PNPV2019-00014628	Date of Loss:	21/11/2019
Vehicle Reg. No.:	SLR9456Y	Driveable?	
Driver Age/Info:	42 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ANG CHUEAN WEE KELVIN	Contact No:	+6591704824
Driver:	ANG CHUEAN WEE KELVIN		
Make/Model:	HONDA FREED HYBRID, 1.5 (A)	Vehicle Reg. Date:	31/08/2017
Vehicle Colour:	BLACK	Chassis No:	GB71020802
Engine No:	LEB5544770		
Odometer:	26355 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336		
Remarks:	VEHICLE IS IN WORKSHOP		
Present Location:	PROGRESSIVE CAR CARE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	8,166.00
Miscellaneous Items	85.00
Labour	1,570.00
Paintwork Labour	800.00
Towing	0.00
Gross Total (S\$)	10,621.00
+ GST 7.00% (S\$)	743.47
Nett Amount (S\$)	11,364.47

This claim is handled by: LILY LIM

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 22 Nov 2019)

Parts: M1-MPV

HONDA FREED HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Progressive Car Care Pte Ltd/SLR9456Y/22/11/2019 17:50

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BONNET <i>Dented</i>	0.00	0.00	✓ *400.00 F
2	1	NA	*BONNET LOCK <i>Dented</i>	0.00	0.00	✓ *85.00 F
3	2	NA	*BONNET HINGE - LH/RH <i>Best</i>	36+36	0.00	✓ *72.00 F
4	2	NA	*BONNET RUBBER - LH/RH <i>new int</i>	22+22	0.00	✓ *44.00 F
5	1	NA	*BONNET INSULATOR <i>new</i>	0.00	0.00	+ *55.00 F
6	10	NA	*BONNET INSULATOR CLIPS <i>new</i>	0.00	0.00	14 ✓ *20.00 F
7	20	NA	*FRONT FENDER COWLING CLIPS - LH/RH <i>new</i>	0.00	0.00	↓ *40.00 F
8	2	NA	*FRONT FENDER HYBRID WORDING - LH/RH <i>new Not New</i>	0.00	0.00	✓ *80.00 F X
9	1	NA	*FRONT BUMPER <i>Distorted</i>	0.00	0.00	✓ *540.00 F
10	10	NA	*FRONT BUMPER CLIPS <i>new</i>	0.00	0.00	✓ *20.00 F
11	2	NA	*FRONT BUMPER SIDE HOLDER - LH/RH <i>new</i>	0.00	0.00	15 ✓ *30.00 F
12	1	NA	*FRONT BUMPER TOWING COVER - RH <i>new</i>	0.00	0.00	+ *17.00 F
13	1	NA	*FRONT BUMPER FOAM <i>new</i>	0.00	0.00	+ *F
14	1	NA	*FRONT BUMPER REINFORCEMENT <i>Best</i>	0.00	0.00	✓ *210.00 F
15	1	NA	*FRONT BUMPER CENTRE LOWER GRILLE <i>new new</i>	0.00	0.00	? *90.00 F X
16	2	NA	*FRONT BUMPER FOGLAMP COVER - LH/RH <i>new</i>	0.00	0.00	+ *90.00 F
17	1	NA	*SUPPORT PANEL ASSY <i>Best</i>	0.00	0.00	✓ *430.00 F
18	1	NA	*GRILLE ASSY W/LOGO <i>new</i>	0.00	0.00	✓ *500.00 F
19	2	NA	*HEADLAMP UNIT - LH/RH <i>RH cracked, LH cracked</i>	ASD+ASD = 1460	0.00	980 ✓ *980.00 F
20	2	NA	*HEADLAMP LOWER RETAINER - LH/RH <i>cracked</i>	38+38 =	0.00	? *56.00 F
21	2	NA	*HORN <i>new Not New</i>	0.00	0.00	? *60.00 F X
22	1	NA	*CONDENSER <i>Dented</i>	0.00	0.00	✓ *530.00 F
23	1	NA	*CONDENSER FAN MOTOR <i>Dented</i>	0.00	0.00	? *180.00 F
24	1	NA	*CONDENSER FAN BLADE <i>new</i>	0.00	0.00	? *40.00 F
25	1	NA	*CONDENSER FAN COWLING <i>new</i>	0.00	0.00	? *55.00 F
26	1	NA	*CONDENSER DISCHARGE PIPE <i>Best</i>	0.00	0.00	? *120.00 F
27	1	NA	*CONDENSER LIQUID TUBE <i>Best</i>	0.00	0.00	135 ? *100.00 F
28	1	NA	*RADIATOR <i>Dented</i>	0.00	0.00	✓ *800.00 F
29	1	NA	*RADIATOR TOP HOSE <i>new new</i>	0.00	0.00	? *22.00 F X
30	1	NA	*RADIATOR BOTTOM HOSE <i>new</i>	0.00	0.00	+ *25.00 F
31	1	NA	*RADIATOR FAN MOTOR <i>Dented</i>	0.00	0.00	? *210.00 F
32	1	NA	*RADIATOR FAN BLADE <i>new</i>	0.00	0.00	? *40.00 F
33	1	NA	*RADIATOR FAN COWLING <i>new</i>	0.00	0.00	? *75.00 F
34	1	NA	*WIPER TANK ASSY <i>new</i>	0.00	0.00	55 ? *115.00 F
35	1	NA	*AIRCLEANER BOX ASSY <i>new</i>	0.00	0.00	+ *180.00 F
36	1	NA	*ENGINE MOUNTING - LH <i>new</i>	0.00	0.00	? *270.00 F X
37	1	NA	*ENGINE MOUNTING - RH <i>new</i>	0.00	0.00	? *210.00 F X
38	1	NA	*ENGINE MOUNTING - REAR <i>new</i>	0.00	0.00	? *75.00 F X
39	1	NA	*INTAKE MANIFOLD <i>new</i>	0.00	0.00	? *320.00 F X
Total Parts (\$\$)						8,166.00

F=Franchise part.

Progressive Car Care Pte Ltd/SLR9456Y/22/11/2019 17:50, Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT <i>New</i>	50.00
2	1	FRONT NUMBER PLATE W/CASING <i>cracked</i>	35.00
Sub Total (S\$)			85.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	750 800.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; CUT/WELD; SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	800 1,000.00
3	TO CHECK WIRING	New	20.00
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00
5	TO REMOVE; ENGINE MOUNTINGS; INTAKE MANIFOLD & RELATED PARTS	New	300.00
6	TO LIFT UP ENGINE	New	80.00
7	TO 4 WHEEL ALIGNMENT	New	70.00
Gross Labour Cost (S\$)			2,370.00

Progressive Car Care Pte Ltd/SLR9456Y/22/11/2019 17:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK II repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

Adrian Ling
25/11/19. 07 Days.
Not Authorised P/P
Excess \$1000.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display "in progress" during resurvey
- Parts price must be subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/ 46 S408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

(SUPPLEMENTARY)

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 1119-7260
Policy No:	PNPV2019-00014628	Date of Loss:	21/11/2019
Vehicle Reg. No.:	SLR9456Y	Driveable?	
Driver Age/Info:	42 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ANG CHUEAN WEE KELVIN	Contact No:	+6591704824
Driver:	ANG CHUEAN WEE KELVIN		

Make/Model:	HONDA FREED HYBRID, 1.5 (A)	Vehicle Reg. Date:	31/08/2017
Vehicle Colour:	BLACK		
Engine No:	LEB5544770	Chassis No:	GB71020802
Odometer:	26355 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) **7**

Description of Accident/Loss: REFER TO ATTACHED STATEMENT RECORD BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

Present Location: PROGRESSIVE CAR CARE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	180.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	180.00
+ GST 7.00% (\$)	12.60
Nett Amount (\$)	192.60
+ Previous Estimates (\$)	11,364.47
Claim Total (\$)	11,557.07

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 12 Dec 2019)**Parts:** M1-MPV HONDA FREED HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Progressive Car Care Pte Ltd/SLR9456Y/12/12/2019 16:14**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*WIPER GARNISH <i>replaced</i>	0.00	0.00	✓ *150.00 F <i>OK</i>
2	1		*AIR DUCT <i>to build</i>	0.00	0.00	*30.00 F <i>OK</i>
Total Parts (S\$)						180.00

F=Franchise part.

Progressive Car Care Pte Ltd/SLR9456Y/12/12/2019 16:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Progressive Car Care Pte Ltd/SLR9456Y/12/12/2019 16:14. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-OWNER MARK 1 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Dec 2019)

Parts: M1-MPV HONDA FREED HYBRID 1.5 (A) (Catalogue:Meriden Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLR9455Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*WIPER GARNISH	0.00	0.00	*150.00 F ✓
2	1		*AIR DUCT	0.00	0.00	*30.00 F ✓
Total Parts (\$\$)						180.00

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Meriden e-Claims IEAS

SUPP	180.00
M1F6	6876.00
SN	85.00
LAB.	1670.00
	8511.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 22 Nov 2019)
Parts:	M1-MPV		HONDA FREED HYBRID 1.5 (A) (Catalogue:Merlimen Singapore 1.0)
Labour:	Repairer's		(Price-denominated Standard List)
Print Code:	Progressive Car Care Pte Ltd/SLR9456Y/22/11/2019 17:50		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *		

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BONNET <i>Dented</i>	0.00	0.00	✓✓ 400.00 F
2	1	NA	*BONNET LOCK <i>Dented</i>	0.00	0.00	✓✓ 85.00 F
3	2	NA	*BONNET HINGE - LH/RH <i>Best</i>	0.00	0.00	✓✓ 72.00 F
4	2	NA	*BONNET RUBBER - LH/RH <i>New</i>	0.00	0.00	✓✓ 44.00 F
5	1	NA	*BONNET INSULATOR <i>New</i>	0.00	0.00	✓✓ 55.00 F
6	10	NA	*BONNET INSULATOR CLIPS <i>New</i>	0.00	0.00	✓✓ 20.00 F
7	20	NA	*FRONT FENDER COWLING CLIPS - LH/RH <i>New</i>	0.00	0.00	✓✓ 40.00 F
8	2	NA	*FRONT FENDER HYBRID WORDING - LH/RH <i>New</i>	0.00	0.00	✓✓ 80.00 F
9	1	NA	*FRONT BUMPER <i>Dented</i>	0.00	0.00	✓✓ 540.00 F
10	10	NA	*FRONT BUMPER CLIPS <i>New</i>	0.00	0.00	✓✓ 20.00 F
11	1	NA	*FRONT BUMPER SIDE HOLDER - LH/RH <i>New</i>	0.00	0.00	✓✓ 30.00 F
12	1	NA	*FRONT BUMPER TOWING COVER - RH <i>New</i>	0.00	0.00	✓✓ 12.00 F
13	1	NA	*FRONT BUMPER FOAM <i>New</i>	0.00	0.00	✓✓ 210.00 F
14	1	NA	*FRONT BUMPER REINFORCEMENT <i>Best</i>	0.00	0.00	✓✓ 90.00 F
15	1	NA	*FRONT BUMPER CENTRE LOWER GRILLE	0.00	0.00	✓✓ 90.00 F
16	2	NA	*FRONT BUMPER FOGLAMP COVER - LH/RH <i>New</i>	0.00	0.00	✓✓ 80.00 F
17	1	NA	*SUPPORT PANEL ASSY <i>Best</i>	0.00	0.00	✓✓ 430.00 F
18	1	NA	*GRILLE ASSY W/LOGO <i>New</i>	0.00	0.00	✓✓ 500.00 F
19	2	NA	*HEADLAMP UNIT - LH/RH <i>RW Canted, LH?</i>	0.00	0.00	✓✓ 500.00 F
20	2	NA	*HEADLAMP LOWER RETAINER - LH/RH	0.00	0.00	✓✓ 56.00 F
21	2	NA	*HORN <i>New</i>	0.00	0.00	✓✓ 90.00 F
22	1	NA	*CONDENSER <i>Dented</i>	0.00	0.00	✓✓ 530.00 F
23	1	NA	*CONDENSER FAN MOTOR	0.00	0.00	✓✓ 180.00 F
24	1	NA	*CONDENSER FAN BLADE	0.00	0.00	✓✓ 40.00 F
25	1	NA	*CONDENSER FAN COWLING	0.00	0.00	✓✓ 65.00 F
26	1	NA	*CONDENSER DISCHARGE PIPE	0.00	0.00	✓✓ 120.00 F
27	1	NA	*CONDENSER LIQUID TUBE	0.00	0.00	✓✓ 100.00 F
28	1	NA	*RADIATOR <i>Dented</i>	0.00	0.00	✓✓ 800.00 F
29	1	NA	*RADIATOR TOP HOSE	0.00	0.00	✓✓ 22.00 F
30	1	NA	*RADIATOR BOTTOM HOSE <i>New</i>	0.00	0.00	✓✓ 22.00 F
31	1	NA	*RADIATOR FAN MOTOR	0.00	0.00	✓✓ 210.00 F
32	1	NA	*RADIATOR FAN BLADE	0.00	0.00	✓✓ 40.00 F
33	1	NA	*RADIATOR FAN COWLING	0.00	0.00	✓✓ 75.00 F
34	1	NA	*WIPER TANK ASSY	0.00	0.00	✓✓ 115.00 F
35	1	NA	*AIRCLEANER BOX ASSY <i>New</i>	0.00	0.00	✓✓ 180.00 F
36	1	NA	*ENGINE MOUNTING - LH	0.00	0.00	✓✓ 270.00 F
37	1	NA	*ENGINE MOUNTING - RH	0.00	0.00	✓✓ 240.00 F
38	1	NA	*ENGINE MOUNTING - REAR	0.00	0.00	✓✓ 75.00 F
39	1	NA	*INTAKE MANIFOLD	0.00	0.00	✓✓ 320.00 F

F=Franchise part.

Total Parts (\$\$)

3,165.00

Progressive Car Care Pte Ltd/SLR9456Y/22/11/2019 17:50, Not valid without Reference section.
Generated using Merlimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT <i>new</i>	50.00
2	1	FRONT NUMBER PLATE W/CASING <i>cracked</i>	35.00
Sub Total (S\$)			85.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	750 800.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; CUT/WELD; SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	800 1,000.00
3	TO CHECK WIRING	New	20.00
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00
5	TO REMOVE; ENGINE MOUNTINGS; INTAKE MANIFOLD & RELATED PARTS	New	X 300.00
6	TO LIFT UP ENGINE	New	X 80.00
7	TO 4 WHEEL ALIGNMENT	New	X 70.00
Gross Labour Cost (S\$)			2,370.00

Progressive Car Care Pte Ltd/SLR9456Y/22/11/2019 17:50. Not valid without Reference section.

Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAN-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repair.

Adrian Ling
25/11/19. 07 Days.
Not Authorised P/P
Excess \$1000.



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE

SINGAPORE 737668 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPERBLADE BLADE
Dept Direct: 9417 9791 / 9748 9928



Dept Direct: 9417 9794

Dept Direct: 9417 9795

Dept Direct: 9417 9796

Dept Direct: 9417 9797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

007260

TAX INVOICE: AR201911-14086

DATE: 28/11/2019

CUSTOMER ID: PRO005

VEH REG. NO.: SLR9456Y

TERMS: 30 days

PO NO.:

PAGE NO.: Page 1 of 1

CURR.: SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
3	H33150-TDK-J61 GB7	HEADLAMP LH LED	U1 HL2-G24	1	980.00 /	980.00 ✓
2	H71190-TDK-003 GB7	UP BEAM L,FR BPR	U1 HL2-N20-E	1	28.00 /	28.00 ✓
3	H74200-TDK-900 GB7	COWL TOP ASSY,FR	U1 HL2-H12	1	150.00 /	150.00 ✓
4	H17252-5JE-000 GB7	CHAMBER ASSY,RESON	U1 HL2-K8-B	1	30.00 /	30.00 ✓

SUB-TOTAL: 1,188.00
ADD GST 7.00 % 83.16

E. & O.E

TOTAL AMOUNT SGD: 1,271.16

[P] 28/11/2019 4:31:28PM

[E] 28/11/2019 11:41:03AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: EDMUND



This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE

SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 8701 / 8743 9520



Wiper blade: HWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL : 67415336 FAX : 67417208 LILY / 68444802 WENDY

ATTN : WENDY

UD 7260

TAX INVOICE : AR201911-14071

DATE : 28/11/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SLR9456Y

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 2

CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	UPRICE	AMOUNT
7 H60100-TDK-000ZZ	BONNET	U1 HL1-F3	1	400.00	400.00 ✓
1 H74120-TDK-003 GB5/7	BONNET LOCK	U1 HL2-C24-G	1	85.00	85.00 ✓
1 H74142-TDK-003 GB5	BONNET SEAL	U1 HL2-L15-A	1	22.00	22.00 ✓
1 H74192-TDK-003 GB7	BONNET SEAL LH	U1 HL2-L15-A	1	22.00	22.00 ✓
1 H04711-TDK-000ZZ GB7	FR BUMPER	U1 HL2-L22	1	540.00	540.00 ✓
1 H91505-TM8-003 GM2	CLIPS	U1 L1-L7-A	10	2.00	20.00 ✓
1 H71193-TDK-003 GB7	SPACER R,FR BPR SIDE	U1 HL2-N20-E	1	15.00	15.00 ✓

CONTINUE NEXT PAGE

[P] 28/11/2019 11:40:34AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[B] 28/11/2019 11:32:29AM



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

80 JALAN LAM HUAT #B1-05/06 CARROS CENTRE

SINGAPORE 737859 TEL: 63625226 FAX: 6362697

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 8417 9791 / 9745 9829



Dept Direct: 8305 9410

Dept Direct: 8305 9411

Dept Direct: 8417 9792



Dept Direct: 8417 8794

Dept Direct: 8417 8795

Dept Direct: 8417 8796

Dept Direct: 8417 8797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),

Porch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

TAX INVOICE : AR201911-14071

DATE : 28/11/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SLR9456Y

TERMS : 30 days

PO NO. :

PAGE NO. : Page 2 of 2

CURR. : SGD

0p7260

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8	H71130-TDK-000	REINFORCEMENT	U1 HL1-P22-A	1	210.00	210.00 ✓
9	H71400-TDK-000/010 GB5 GB7	SUPPORT PANEL	U1 HL1-P15-SD	1	430.00	430.00 ✓
10	H71120-TDL-003/013 GB7	GRILLE ASSY,FRONT	U1 HL1-K14	1	500.00	500.00 ✓
11	H33100-TDK-J61 GB7	HEAD LAMP RH LED	U1 Jager SUPPLIER	1	980.00	980.00 ✓
12	H71140-TDK-003 GB7	UP BEAM R,FR BPR	U1 HL2-D6-C	1	28.00	28.00 ✓

SUB-TOTAL : 3,252.00

ADD GST 7.00 % 227.64

E. & O.E

TOTAL AMOUNT SGD : 3,479.64

[P] 28/11/2019 11:40:34AM

[E] 28/11/2019 11:32:29AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : EDMUND



This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 8761 / 6145 9629



Dept Direct: 6417 8764

Dept Direct: 6417 8765

Dept Direct: 6417 8766

Dept Direct: 6417 8767

Wiper blade: NWB (Nippon Wiper blade), Gilper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY

00720

TAX INVOICE : AR201911-14105

DATE : 28/11/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SLR9456Y

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ	STOCK ID	DESCRIPTION	Slk 1.00	QTY	U/PRICE	AMOUNT
1.	H60120-TDK-000ZZ GB7	HINGE COMP R HOOD	CX @16-E1-3BC	1	36.00	36.00
2.	H60170-TDK-000ZZ GB7	HINGE COMP L HOOD	CX @16-E1-3BE	1	36.00	36.00
3.	H91501-S1K-003	INSULATOR CLIP	CX @16-E1-5CB	7	2.00	14.00
	H76841-TDK-J02 GB7	TANK WASHHK	CX @16-E1-7AC	1	55.00	55.00

SUB-TOTAL : 141.00
AID10 CINT 7.00 % 9.87

E.S.O.E

TOTAL AMOUNT SGD: 150.87

[P] 28/11/2019 11:56:05

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 28/11/2019 11:53:16AM

JAE Auto Pte. Ltd.

Sales Executive: EDMUND



This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



特立機器貿易

MEGA POWER ENGINEERING & TRADING

Automobile Air Conditioning System is Our Business

Head Office: 39 Genting Road Singapore 349405 Tel: 6842 3309 Fax: 6842 3373
Email: mega1989@singtel.com.sg Business Reg. No. 40659100W

TAX INVOICE

GST Reg# : M8-8002998-3

Invoice No. : INV 10235352

Invoice Date : 29-Nov-2019

Terms : 30 DAYS

PO No :

Vehicle No : SLR 9455Y 0D1149-7760

Chassis No :

Staff : YOU FU

Bill To: PRO002

PROGRESSIVE CAR CARE PTE LTD

BLK 3022A UBI ROAD 1

#01-45/46

SINGAPORE 408716

Attn : Account Dept

Ship To: KG1

PROGRESSIVE CAR CARE PTE LTD

BLK 3022A UBI ROAD 1

#01-45/46

Attn : WENDY

Tel: 82585595

0DTL6

Remarks:

MUST KEY IN ORDER PERSON'S NAME & VEHICLE NO.

S/NC	DESCRIPTION	MOQ	BJN	WH	QTY	PRICE	SP	TOTAL(SGD)
PO Number :		DO Number :						
1 RA	HONDA FREED GB7 RADIATOR ORG			KB	1	800.00		800.00 ✓
2 HD	HONDA FREED GB7 DISCHARGE-HOSE			KB	1	120.00		120.00 ✓
3 HL	HONDA FREED GB7 LIQUID-HOSE			KB	1	125.00		125.00 ✓
4 AC	HONDA FREED GB7 A/C FAN HOUSING			KB	1	55.00		55.00 ✓
5 AC-00601	HON VEZEL FAN BLADE - 78L/CW			KB	1	40.00		40.00 ✓
6 AC	HONDA FREED GB7 RADIATOR FAN HOUSING			KB	1	75.00		75.00 ✓
7 AC	HONDA FREED GB7 RADIATOR FAN BLADE			KB	1	40.00		40.00 ✓
8 RM-00033	HON JAZZ FIT FREED VEZEL ORG RAD MOTOR; LONG		KB1-F2-5	KB	1	210.00		210.00 ✓
9 FM-00061	HON VEZEL ORG FAN MOTOR (ACW)		KB1-F2-5	KB	1	180.00		180.00 ✓
10 CD-01228	HON FREED GB7 HYBRID COND W/DESI			KB	1	530.00		530.00 ✓

Rate: 1 SGD: 1,000,000 SGD

Note: Goods sold are not returnable.

All Brand New compressor sold are without warranty.

Late payment is subject to 2% interest per month.

SUB-TOTAL 2,175.00 SGD

DISC 0.00% (-) SGD

GST 7% 152.25 SGD

AMOUNT 2,327.25 SGD

This is a computer-generated document.

No signature is required.

Printed on: 29/11/2019 19:18:44

CUSTOMER COPY

Customer Signature & Stamp



8K 5025, Ang Mo Kio Ind Park 2 #01-5557 S(369328) Tel: 6452 3368 Fax: 6481 1187

No. 13 Kall Bah Rd 4 #01-27 Bentley Biz Centre S(417807) Tel: 6375 3309 Fax: 6385 3329

No. 8 Soon Lee S(1801-38) Pioneer Petrol S(617607) Tel: 6282 3388 Fax: 6275 5388

No. 21 Teh Guan Rd East #01-33 Teh Guan Centre S(608000) Tel: 6760 3388 Fax: 6310 2484



LOCAL

Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Nov 2019 Sendback Est	22 Nov 2019 17:50 \$10,621.00	22 Nov 2019 18:49 Edit Adj Rpt	\$8,511.00 Edit Estimates	\$8,511.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	12 Dec 2019 16:13	12 Dec 2019 16:14 \$180.00	12 Dec 2019 16:14			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: ANG CHUEAN WEE KELVIN , ID: S7703074C, Tel: +6591704824, Email: SUNAKEL24@GMAIL.COM									
Vehicle Reg. No.: SLR9456Y		Date of Loss: 21/11/2019 18:00 - :59 [26 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 1201900036182		Policy/Cover Note No.: PNPV2019-00014628 (Comprehensive)							
		Excess: \$1,000.00							
Repairer: Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 03/12/2019]									
Driver/Custodian: ANG CHUEAN WEE KELVIN (42 / Male), NRIC: S7703074C, Tel: +6591704824 Email: SUNAKEL24@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- FWD_SG (24/02/2020): Alert - Adj Mandate Approved (\$8511.00) - SLR9456Y - Claim Handler: Eileen Bay - FWD_SG (26/11/2019): Alert - Adj Mandate Approved (\$7900.00) - SLR9456Y - Claim Handler: Eileen Bay - FWD_SG (25/11/2019): Alert - Adj Mandate Maintained - SLR9456Y - Claim Handler: Eileen Bay									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLR9456Y (1201900036182)
OD
Nov 21 2019 6:00PM
[ANG CHUEAN WEE KELVIN]
Progressive Car Care Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	22/11/19 11:07	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
2	22/11/19 11:08	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
3	22/11/19 11:08	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
4	22/11/19 11:08	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
5	22/11/19 11:08	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
6	22/11/19 11:20	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
7	22/11/19 11:20	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
8	22/11/19 11:20	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
9	22/11/19 11:21	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
10	22/11/19 11:21	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
11	22/11/19 11:21	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
12	22/11/19 11:21	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
13	22/11/19 11:21	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
Assessment Reports			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	22/11/19 17:50	Repairer Estimates	Load HTM	☐
2	12/12/19 16:14	Repairer Estimates Suppl. #1	Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/11/19 17:08	Adjuster Immediate Advice	Load HTM	☐
2	20/02/20 14:30	Adjuster Immediate Advice	Load HTM	☐
Photos/Images			3 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	22/11/19 17:13	1	Load JPG	☒
2	22/11/19 17:13	2	Load JPG	☒
3	22/11/19 17:13	3	Load JPG	☒
4	22/11/19 17:13	4	Load JPG	☒
5	22/11/19 17:13	5	Load JPG	☒
6	22/11/19 17:13	6	Load JPG	☒
7	22/11/19 17:13	7	Load JPG	☒
8	22/11/19 17:13	8	Load JPG	☒
9	22/11/19 17:13	9	Load JPG	☒
10	22/11/19 17:13	10	Load JPG	☒
11	22/11/19 17:13	11	Load JPG	☒
12	22/11/19 17:13	12	Load JPG	☒

Video			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
13	22/11/19 17:13	13	 Load JPG	☒
14	22/11/19 17:13	14	 Load JPG	☒
15	22/11/19 17:13	15	 Load JPG	☒
16	22/11/19 17:13	16	 Load JPG	☒
17	22/11/19 17:13	17	 Load JPG	☒
18	22/11/19 17:13	18	 Load JPG	☒
19	22/11/19 17:13	19	 Load JPG	☒
20	22/11/19 17:13	20	 Load JPG	☒
21	22/11/19 17:13	21	 Load JPG	☒
22	22/11/19 17:13	22	 Load JPG	☒
23	22/11/19 17:13	23	 Load JPG	☒
24	22/11/19 17:13	24	 Load JPG	☒
25	22/11/19 17:13	25	 Load JPG	☒
26	22/11/19 17:13	26	 Load JPG	☒
27	22/11/19 17:13	27	 Load JPG	☒
28	22/11/19 17:13	28	 Load JPG	☒
29	22/11/19 17:13	29	 Load JPG	☒
30	22/11/19 17:13	30	 Load JPG	☒
31	22/11/19 17:13	31	 Load JPG	☒
32	22/11/19 17:13	32	 Load JPG	☒
33	22/11/19 17:13	33	 Load JPG	☒
34	22/11/19 17:13	34	 Load JPG	☒
35	22/11/19 17:13	35	 Load JPG	☒
36	22/11/19 17:13	36	 Load JPG	☒
37	22/11/19 17:13	37	 Load JPG	☒
38	22/11/19 17:13	38	 Load JPG	☒
39	22/11/19 17:13	39	 Load JPG	☒
40	22/11/19 17:13	40	 Load JPG	☒
41	22/11/19 17:13	41	 Load JPG	☒
42	22/11/19 17:13	42	 Load JPG	☒
43	22/11/19 17:13	43	 Load JPG	☒
44	22/11/19 17:13	44	 Load JPG	☒
45	22/11/19 17:13	45	 Load JPG	☒
46	22/11/19 17:13	46	 Load JPG	☒
47	22/11/19 17:13	47	 Load JPG	☒
48	22/11/19 17:13	48	 Load JPG	☒
49	22/11/19 17:13	49	 Load JPG	☒
50	22/11/19 17:13	50	 Load JPG	☒
51	22/11/19 17:13	51	 Load JPG	☒
52	22/11/19 17:13	52	 Load JPG	☒
53	22/11/19 17:13	53	 Load JPG	☒
54	22/11/19 17:13	54	 Load JPG	☒
55	22/11/19 17:13	55	 Load JPG	☒
56	22/11/19 17:13	56	 Load JPG	☒
57	22/11/19 17:13	57	 Load JPG	☒
58	22/11/19 17:13	58	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/02/20 13:55	General View	 Load JPG	☒
2	20/02/20 13:55	General View	 Load JPG	☒
3	20/02/20 13:55	General View	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
4	20/02/20 13:55	General View	 Load JPG	☒
5	20/02/20 13:55	General View	 Load JPG	☒
6	20/02/20 13:55	General View	 Load JPG	☒
7	20/02/20 13:55	General View	 Load JPG	☒
8	20/02/20 13:55	General View	 Load JPG	☒
9	20/02/20 13:55	General View	 Load JPG	☒
10	20/02/20 13:55	General View	 Load JPG	☒
11	20/02/20 13:55	General View	 Load JPG	☒
12	20/02/20 13:55	General View	 Load JPG	☒
13	20/02/20 13:55	General View	 Load JPG	☒
14	20/02/20 13:55	General View	 Load JPG	☒
15	20/02/20 13:55	General View	 Load JPG	☒
16	20/02/20 13:55	General View	 Load JPG	☒
17	20/02/20 13:55	General View	 Load JPG	☒
18	20/02/20 13:55	General View	 Load JPG	☒
19	20/02/20 13:55	General View	 Load JPG	☒
20	20/02/20 13:55	General View	 Load JPG	☒
21	20/02/20 13:55	General View	 Load JPG	☒
22	20/02/20 13:55	General View	 Load JPG	☒
23	20/02/20 13:55	General View	 Load JPG	☒
24	20/02/20 13:55	General View	 Load JPG	☒
25	20/02/20 13:55	General View	 Load JPG	☒
26	20/02/20 13:55	General View	 Load JPG	☒
27	20/02/20 13:55	General View	 Load JPG	☒
28	20/02/20 13:55	General View	 Load JPG	☒
29	20/02/20 13:55	General View	 Load JPG	☒
30	20/02/20 13:55	General View	 Load JPG	☒
31	20/02/20 13:55	General View	 Load JPG	☒
32	20/02/20 13:55	General View	 Load JPG	☒
33	20/02/20 13:55	General View	 Load JPG	☒
34	20/02/20 13:55	General View	 Load JPG	☒
35	20/02/20 13:55	General View	 Load JPG	☒
36	20/02/20 13:55	General View	 Load JPG	☒
37	20/02/20 13:55	General View	 Load JPG	☒
38	20/02/20 13:56	General View	 Load JPG	☒
39	20/02/20 13:56	General View	 Load JPG	☒
40	20/02/20 13:56	General View	 Load JPG	☒
41	20/02/20 13:56	General View	 Load JPG	☒
42	20/02/20 13:56	General View	 Load JPG	☒
43	20/02/20 13:56	General View	 Load JPG	☒
44	20/02/20 13:56	General View	 Load JPG	☒
45	20/02/20 13:56	General View	 Load JPG	☒
46	20/02/20 13:56	General View	 Load JPG	☒
47	20/02/20 13:56	General View	 Load JPG	☒
48	20/02/20 13:56	General View	 Load JPG	☒
49	20/02/20 13:56	General View	 Load JPG	☒
50	20/02/20 13:56	General View	 Load JPG	☒
51	20/02/20 13:56	General View	 Load JPG	☒
52	20/02/20 13:56	General View	 Load JPG	☒
53	20/02/20 13:56	General View	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
54	20/02/20 13:56	General View	 Load JPG	☒
55	20/02/20 13:56	General View	 Load JPG	☒
56	20/02/20 13:56	General View	 Load JPG	☒
57	20/02/20 13:56	General View	 Load JPG	☒
58	20/02/20 13:56	General View	 Load JPG	☒
59	20/02/20 13:56	General View	 Load JPG	☒
60	20/02/20 13:56	General View	 Load JPG	☒
61	20/02/20 13:56	General View	 Load JPG	☒
62	20/02/20 13:56	General View	 Load JPG	☒
63	20/02/20 13:56	General View	 Load JPG	☒
64	20/02/20 13:56	General View	 Load JPG	☒
65	20/02/20 13:56	General View	 Load JPG	☒
66	20/02/20 13:56	General View	 Load JPG	☒
67	20/02/20 13:56	General View	 Load JPG	☒
68	20/02/20 13:56	General View	 Load JPG	☒
69	20/02/20 13:56	General View	 Load JPG	☒
70	20/02/20 13:56	General View	 Load JPG	☒
71	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
72	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
73	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
74	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
75	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
76	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
77	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
78	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
79	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
80	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
81	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
82	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
83	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
84	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
85	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
86	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
87	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
88	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
89	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
90	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
91	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
92	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
93	20/02/20 13:57	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	22/11/19 17:11	Claimant's NRIC & LIC	 Load JPG	☒
2	22/11/19 17:11	Certificate of Insurance	 Load JPG	☒
3	22/11/19 17:11	E-filed GIA report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/11/19 17:02	ESTIMATE	 Load PDF	
2	20/02/20 14:20	SUPPLEMENTARY LIST	 Load PDF	
3	28/02/20 09:55	Parts Invoice	 Load PDF	

Linked Accident Report Documents

				View	View in Browser
Video				1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	22/11/19 11:07	Video - Accident		Load MP4	
2	22/11/19 11:08	Video - Accident		Load MP4	
3	22/11/19 11:08	Video - Accident		Load MP4	
4	22/11/19 11:08	Video - Accident		Load MP4	
5	22/11/19 11:08	Video - Accident		Load MP4	
6	22/11/19 11:20	Video - Accident		Load MP4	
7	22/11/19 11:20	Video - Accident		Load MP4	
8	22/11/19 11:20	Video - Accident		Load MP4	
9	22/11/19 11:21	Video - Accident		Load MP4	
10	22/11/19 11:21	Video - Accident		Load MP4	
11	22/11/19 11:21	Video - Accident		Load MP4	
12	22/11/19 11:21	Video - Accident		Load MP4	
13	22/11/19 11:21	Video - Accident		Load MP4	
Assessment Reports				1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	06/12/19 19:29	Accident Statement		Load HTM	
2	06/12/19 19:34	Accident Statement		Load HTM	
3	06/12/19 19:35	Accident Statement		Load HTM	
4	06/12/19 19:36	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	22/11/19 10:31	Accident Photo		Load JPG	☒
2	22/11/19 10:31	Accident Photo		Load JPG	☒
3	22/11/19 10:31	Accident Photo		Load JPG	☒
4	22/11/19 10:31	Accident Photo		Load JPG	☒
5	22/11/19 10:31	Accident Photo		Load JPG	☒
6	22/11/19 10:31	Accident Photo		Load JPG	☒
7	22/11/19 10:31	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)		Thumbnail	Print
1	22/11/19 10:44	Sketch Plan		Load JPG	☒
2	22/11/19 10:44	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19020747/AQF3E2

Date: 28/02/2020

REFERENCE

Insured/Claimant: ANG CHUEAN WEE KELVIN Policy No: PNPV2019-00014628
Date of Loss: 21/11/2019 Nature of Claim: OD Claim No: 1201900036182

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR9456Y
Make & Model: HONDA FREED HYBRID, 1.5 (A) Engine No: LEB5544770
Reg. Date: 31/08/2017 (Man. Year: 2017) Chassis No: GB71020802
Colour: Black Odometer: 26355 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$83,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,346.00	6,756.00	1,590.00	19.05
Miscellaneous Items	85.00	85.00	0.00	0.00
Labour	1,570.00	920.00	650.00	41.40
Paintwork Labour	800.00	750.00	50.00	6.25
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,801.00	8,511.00	2,290.00	21.20
- Excess (S\$)	0.00	1,000.00	-1,000.00	
(S\$)	10,801.00	7,511.00	3,290.00	30.46
+ GST 7.00/7.00% (S\$)	756.07	525.77	230.30	30.46
Nett Amount (S\$)	11,557.07	8,036.77	3,520.30	30.46

INSPECTION

Date of Assignment: 22/11/2019 Present Location: Progressive Car Care Pte Ltd (HQ)
Date Inspected: 25/11/2019 Inspected At: Progressive Car Care Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2020)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR9456Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONNET	Dented	400.00 F	*400.00 F
2	1	NA	*BONNET LOCK	Damaged	85.00 F	*85.00 F
3	2	NA	*BONNET HINGE - LH/RH	Bent	72.00 F	*72.00 F
4	2	NA	*BONNET RUBBER - LH/RH	Cut	44.00 F	*44.00 F
5	1	NA	*BONNET INSULATOR	Not Necessary	55.00 F	*- F
6	10	NA	*BONNET INSULATOR CLIPS	Necessary	20.00 F	*14.00 F
7	20	NA	*FRONT FENDER COWLING CLIPS - LH/RH	Not Necessary	40.00 F	*- F
8	2	NA	*FRONT FENDER HYBRID WORDING - LH/RH	Not Necessary	80.00 F	*- F
9	1	NA	*FRONT BUMPER	Distorted	540.00 F	*540.00 F
10	10	NA	*FRONT BUMPER CLIPS	Necessary	20.00 F	*20.00 F
11	2	NA	*FRONT BUMPER SIDE HOLDER - LH/RH	Necessary	30.00 F	*15.00 F
12	1	NA	*FRONT BUMPER TOWING COVER - RH	Not Necessary	17.00 F	*- F
13	1	NA	*FRONT BUMPER FOAM	Not Necessary	0.00 F	*- F
14	1	NA	*FRONT BUMPER REINFORCEMENT	Bent	210.00 F	*210.00 F
15	1	NA	*FRONT BUMPER CENTRE LOWER GRILLE	Not Necessary	90.00 F	*- F
16	2	NA	*FRONT BUMPER FOGLAMP COVER - LH/RH	Not Necessary	90.00 F	*- F
17	1	NA	*SUPPORT PANEL ASSY	Bent	430.00 F	*430.00 F
18	1	NA	*GRILLE ASSY W/LOGO	Necessary	500.00 F	*500.00 F
19	2	NA	*HEADLAMP UNIT - LH/RH	Cracked	1,960.00 F	*1,960.00 F
20	2	NA	*HEADLAMP LOWER RETAINER - LH/RH	Cracked	56.00 F	*56.00 F
21	2	NA	*HORN	Not Necessary	60.00 F	*- F
22	1	NA	*CONDENSER	Dented	530.00 F	*530.00 F
23	1	NA	*CONDENSER FAN MOTOR	Damaged	180.00 F	*180.00 F
24	1	NA	*CONDENSER FAN BLADE	Cut	40.00 F	*40.00 F
25	1	NA	*CONDENSER FAN COWLING	Cracked	55.00 F	*55.00 F
26	1	NA	*CONDENSER DISCHARGE PIPE	Bent	120.00 F	*120.00 F
27	1	NA	*CONDENSER LIQUID TUBE	Bent	100.00 F	*125.00 F
28	1	NA	*RADIATOR	Dented	800.00 F	*800.00 F
29	1	NA	*RADIATOR TOP HOSE	Not Necessary	22.00 F	*- F
30	1	NA	*RADIATOR BOTTOM HOSE	Not Necessary	25.00 F	*- F
31	1	NA	*RADIATOR FAN MOTOR	Damaged	210.00 F	*210.00 F
32	1	NA	*RADIATOR FAN BLADE	Cut	40.00 F	*40.00 F
33	1	NA	*RADIATOR FAN COWLING	Cracked	75.00 F	*75.00 F
34	1	NA	*WIPER TANK ASSY	Deformed	115.00 F	*55.00 F
35	1	NA	*AIRCLEANER BOX ASSY	Not Necessary	180.00 F	*- F
36	1	NA	*ENGINE MOUNTING - LH	Not Necessary	270.00 F	*- F
37	1	NA	*ENGINE MOUNTING - RH	Not Necessary	210.00 F	*- F
38	1	NA	*ENGINE MOUNTING - REAR	Not Necessary	75.00 F	*- F
39	1	NA	*INTAKE MANIFOLD	Not Necessary	320.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Supplementary #1						
40	1		*WIPER GARNISH	Cracked	150.00 F	*150.00 F
41	1		*AIR DUCT	Deformed	30.00 F	*30.00 F
F=Franchise part.						
Total Parts (S\$)					8,346.00	6,756.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	COOLANT (NECESSARY)	50.00	50.00
2	1	FRONT NUMBER PLATE W/CASING (CRACKED)	35.00	35.00
Sub Total (S\$)			85.00	85.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	800.00	750.00
Labour Items				
2	TO KNOCK OUT DENTS; CUT/WELD; SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	1,000.00	800.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00	100.00
5	TO REMOVE; ENGINE MOUNTINGS; INTAKE MANIFOLD & RELATED PARTS	New	300.00	0.00
6	TO LIFT UP ENGINE	New	80.00	0.00
7	TO 4 WHEEL ALIGNMENT	New	70.00	0.00
Gross Labour Cost (S\$)			2,370.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >