

13000001

ASS. REC. BY:

REF: CI/TPD19020760/P

Special Instruction:

Surveyor

ASSIGNMENT (Office)

Date/Time: 21/11/2019From (Person): Kamaliah Kamie

of

SPF

Bill to:

Estimated Cost:

OD/TP+WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMJ 1564 B

Insured:

at Workshop m/s

Tel:

of

Policy No:

MYASPP0600002842/1

Claim No:

TP/1P/69597/2019

Sum Insured:

Excess:

D.O.A.

9/11/2019

Make of Vch:

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	<u>SMJ 1564 B-X</u>

500/9

D48

mck

Resil

Vehicles to be inspected: SHB8692U - Driver (Involved party)

IO In-Charge: SIO Saleha

h) Case IAFP-IB-20191115 - Mechanical Inspection of Motorcycle, FBH640L (TP/IP/59353/2019)

On 19 September 2019 (Thursday) at about 5.09 pm, motor cycle was travelling along Buangkok East Drive towards Buangkok Dr, on the right of 3 lanes, when the deceased's motor cycle lost control and collided onto the right kerb at a gradual left bend. As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene at 5.26pm by Paramedic Nabila.

Vehicles to be inspected: FBH640L - Rider (Deceased)

IO In-Charge: SIO Saleha

i) Case IAFP-IB-20191115 - Mechanical Inspection of Motorcycle, FBE735M (TP/IP/59379/2019)

On 20 September 2019, at about 2.14 a.m., the Deceased (Rider of motor cycle) was believed to be travelling on Lane 1 of 4-lanes along SLE towards CTE (10km), when she collided onto a portable directional sign, collided onto a few cones and skidded. Due to the impact, Deceased's motorcycle landed on Lane 2. There were ongoing road works at that time but there was no contact with the stationary LTA TMA truck. As a result of the accident, the Deceased sustained head injuries and was pronounced dead at scene at 2.34 am by Paramedic Christine.

Vehicles to be inspected: FBE735M - Rider (Deceased)

IO In-Charge: SIO Saleha

j) Case IAFP-IB-20191115 - Mechanical Inspection of Motor Car, SMA1288X (TP/IP/60507/2019)

On 26 September 2019 at about 1.10 a.m., the Deceased (pedestrian) was walking on the left lane of the 3 lanes of Jalan Bukit Merah and suddenly knelt down on the road facing oncoming traffic. The Witness, who was travelling on the left lane of the 3 lanes of Jalan Bukit Merah towards Queensway, saw the Deceased walking onto the left lane and kneel on the road. He immediately came to a stop before the Deceased and switched on the hazard lights and called for the Police. The defendant (motor car) who was travelling on the centre of the 3 lanes of Jalan Bukit Merah towards Queensway, then made left turn into the carpark entrance of Blk 110 Jalan Bukit Merah and ran over the Deceased. Due to the accident, the Deceased was conveyed to the Singapore General Hospital (SGH) however, he succumbed to his injuries and was pronounced dead on the same day at 2.33 a.m.

Vehicles to be inspected: SMA1288X - Driver (Potential defendant)

IO In-Charge: SIO Saleha

k) Case IAFP-IB-20191115 - Mechanical Inspection of Motor Car, SMJ1564B (TP/IP/69597/2019)

l) Case IAFP-IB-20191115 - Mechanical Inspection of Motorcycle, JRR7688 (TP/IP/69597/2019)

On 9 November 2019 (Saturday) at about 4.33 a.m., the Involved Party (SMJ1564B) was driving his motor car on the extreme right lane of the 4 lanes of BKE towards Woodlands checkpoint. Somewhere after KJE, he suddenly felt an impact from the rear right portion and saw the Deceased's motorcycle (without any rider), approaching from the right side of his motor car. The motorcycle continued to veer to the left

across the 4 lanes and landed on the grass verge near the road shoulder. The Involved Party came to a stop and realised that the Deceased had landed on the grass verge along the centre divider. As a result of the accident, the Deceased sustained multiple injuries and was conveyed unconscious to the Khoo Teck Phuat Hospital by ambulance. The Deceased succumbed to his injuries and was pronounced dead in hospital on the same day at 5.35 a.m., by Dr Ng Zheng Han Ernest Clement.

Vehicles to be inspected: SMJ1564B - Driver (Involved party) - *cont.*
JRR7688 - Rider (Deceased)

IO In-Charge: SIO Saleha

- m) **Case IAFP-IB-20191115 - Mechanical Inspection of Malaysian Motor Lorry, JAH 1469 (TP/IP/63795/2019)**
- n) **Case IAFP-IB-20191115 - Mechanical Inspection of Malaysian Motorcycle, JQA 2128 (TP/IP/63795/2019)**
- o) **Case IAFP-IB-20191115 - Mechanical Inspection of Malaysian Motorcycle, JSV 1224 (TP/IP/63795/2019)**

On 11 October 2019 (Friday) at about 7.56 p.m., the 2nd Deceased, the driver of motor lorry, JAH 1469 was travelling on the single lane, two way road along Mandai Estate towards Woodlands Road when his motor lorry veered onto the opposite direction along Mandai Estate. Location has a mild slope along the way up from Woodlands Road towards Mandai Estate. While the 2nd Deceased's motor lorry went onto the opposite direction, his motor lorry continued moving down the mild gradual slope towards Woodlands Road and collided onto the 1st Deceased, rider of Malaysian Motorcycle: JQA 2128, 1st Deceased's motorcycle and the Involved Party's motorcycle, rider of Malaysian Motorcycle JSV 1224 which was turning onto Mandai Estate from Woodlands Road. After the collision, the 2nd Deceased's motor lorry continued moving forward with the 1st Deceased and his motorcycle underneath his motor lorry when his motor lorry eventually came to a stop along the center divider along Woodlands Road. The 2nd Deceased's motor lorry was stopped by a traffic light pole. 3 portions of green railing and 1 traffic light pole uprooted. Due to the accident, the 1st Deceased was pronounced dead at the scene of accident by Paramedic SGT Azmi at 8.22 am. The 2nd Deceased conveyed by ambulance to the Khoo Teck Puat Hospital however, he succumbed to his injuries and was pronounced dead in hospital on the same day, at 9.02 a.m. by Dr Alethea. The Involved Party refused conveyance to the hospital.

Vehicles to be inspected: JAH 1469 - Driver (Deceased)
JQA 2128 - Rider (Deceased)
JSV 1224 - Rider (Involved Party)

IO In-Charge: IO Clarence Lim

- p) **Case IAFP-IB-20191115 - Mechanical Inspection of Malaysian Motor Lorry, YP 9377 Z (TP/IP/65989/2019)**
- q) **Case IAFP-IB-20191115 - Mechanical Inspection of Motorcycle, FBF 3707 U (TP/IP/65989/2019)**

On 23 October 2019 (Wednesday) at about 7.31 a.m., the Deceased was travelling alone on his motorcycle along KJE (PIE) 7.3 km and was riding in between lanes 1 and 2 of the 4-lanes road. While riding, the Deceased self-skidded and fell to his left, under the Involved Party's lorry, which was travelling on lane 2 of the 4 lanes road. The Deceased was subsequently run over by the right rear tyre of the Involved Party's motor lorry. As a result of the accident, the Deceased sustained facial injuries and was pronounced dead at the scene by Paramedic Joshua at 7.52 a.m.

Vehicles to be inspected: YP 9377 Z - Driver (Involved Party)
FBF 3707 U - Rider (Deceased)