

ASS. REC. BY:

REF:

08/CTI19020776/A4d3

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of CTI

Date/Time: 22/11/19 @ 5:58pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLR3311X

Insured:

WC4734B

at Workshop m/s

Suo Hark Lee

Tel:

67431913

of

Blk 3007 ubi Road 1 #01-106

Policy No:

DmCV9N1911451900

Claim No:

SNM19D205562

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:26am @ 29/11/19

Person Contacted:

Bridget

Vehicle IN/OUT

Date/Time	Action/Instruction	Is Approved
	SLR3311X-X	✓
	WC4734B-CC3/CTI19012288/Kira3n2	20A: 9/7/2019
2/12-	lump sum \$36507 (Red: 2483.60; 40%)	

ASS. REQ. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLR3311X Yr Regn: 2017 August
 Type: MCaf DM Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hold, Shuttle C.O. 1496
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 61539 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: GP71117462

Gen. Cond: Good Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 185/60 R15
 R: 185/60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>25/11/19</u>

Survey held at JHK

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chirn

RECEIVED 03 DEC 2019

MV :
 PV :
 Nett:

Date/Time, File Pass to?

1) 2/12 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / Rpt: TP 36507-

Days Of Repair: 6

Resurvey No. of Trip: -

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Wheel std (\$)

Survey Fee:

Transportation:

3 + PS \$

Fines

Other

T-T-L

220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 22 November 2019 5:58 PM
To: shimin poh
Cc: 'assignments'
Subject: RE: OUR REF: SNM19D205562-WC4734B-CBS- NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SLR3311X/WC4734B DOA 21/11/2019

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: shimin poh [mailto:shimin@jhk.com.sg]
Sent: Friday, November 22, 2019 5:25 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D205562-WC4734B-CBS- NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SLR3311X/WC4734B DOA 21/11/2019

Dear Boon Seng:

We choose LKK

Thank You !
Bridget Poh (Shimin)
Joo Hak Kee Auto Pte Ltd
Blk 3007 Ubi Road 1
#01-406 Singapore 408701
Office: 67431913

On Fri, Nov 22, 2019 at 5:21 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without prejudice

Dear Sir,

LKK

STA

LBS

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Friday, November 22, 2019 3:25 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; shimin poh <shimin@jhk.com.sg>

Subject: OUR REF: SNM19D205562-WC4734B-CBS- NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SLR3311X/WC4734B DOA 21/11/2019

Dear Boon Sen,

Please conduct PRS for SLR3311X.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: shimin poh [<mailto:shimin@jhk.com.sg>]

Sent: Friday, 22 November, 2019 1:36 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: NEW THIRD PARTY DIRECT SETTLEMENT VEH NO : SLR3311X/WC4734B DOA 21/11/2019

Dear Sir/Mdm,

Kindly arrange pre-repair survey for the above and if possible would like to do direct settlement.

Please provide us your list of surveyors for our selection. **veh in our premises**

Attached is the accident report for your reference and we're currently in the midst of preparing the estimate.

Thank you and hope to hear from you soon.

Thank You !

Bridget Poh (Shimin)

Joo Hak Kee Auto Pte Ltd

Blk 3007 Ubi Road 1

#01-406 Singapore 408701

Office: 67431913

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: Phan Sewe Siang Robson
 INSURER: China Taiping Insurance (Singapore) Pte. Ltd
 POLICY NO: 5093346194-02
 DOA: 21/11/2019 *Denise.*

REPAIR ESTIMATE

Est No. : EST19110007
 Date : 22-Nov-19
 Vehicle Num : SLR3311X
 Make/Model : Honda Shuttle Hybrid
 Chassis # : GP71117462
 Engine # : LEB6321532
 Yr. Of Manu : 2017

No.	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	Rear Bumper <i>Rehnd</i>	1.00	1150.60	1150.60 ✓
2	Rear Bumper Side Retainers <i>new</i>	2.00	26.50	53.00 ✓
3	Rear Bumper Reflector <i>new</i>	2.00	120.50	241.00 +
4	Rear Bumper Reflector Cover <i>new</i>	2.00	45.00	90.00 +
5	Rear Bumper Clips <i>new</i>	10.00	3.50	35.00 ✓
6	Tailgate RH Outer Lamp <i>cracked</i>	1.00	520.50	520.50 -
7	Tailgate LH Inner Lamp <i>new</i>	1.00	340.80	340.80 +
8	Rear RH Fender <i>3887.50</i>	1.00	1010.90	1010.90 ✓
9	Rear RH Door <i>Distorted</i>	1.00	799.50	799.50 -
10	Rear RH Door Handle <i>cut</i>	1.00	108.00	108.00 ✓
11	Rear RH Door Lock <i>Damaged</i>	1.00	210.00	210.00 ✓
12	Rear RH Door Stay <i>new</i>	1.00	320.10	320.10 +
				Amt S\$ 4879.40
				Discount (20.00%) S\$ 975.80
				Subtotal S\$ 3903.60
				<i>52</i>
Section: SPECIAL NETT ITEMS				
13	Rear Number Plate With Cover <i>new</i>	1.00	50.00	50.00 +
				Amt S\$ 50.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 50.00

Continue on next page...

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: Phan Sewe Siang Robson
 INSURER: China Taiping Insurance (Singapore) Pte. Ltd
 POLICY NO: 5093346194-02
 DOA: 21/11/2019

REPAIR ESTIMATE

Est No. : EST19110007
 Date : 22-Nov-19
 Vehicle Num : SLR3311X
 Make/Model : Honda Shuttle Hybrid
 Chassis # : GP71117462
 Engine # : LEB6321532
 Yr. Of Manu : 2017

No.	Description	Qty	U/P	Amt
Section: LABOUR				
14	To Remove and Install RH Quarter Glass	1.00	150.00	150.00 ⁸⁰
15	To Panel Beat on Necessary Damaged Parts	1.00	1350.00	1350.00 ⁸⁰⁰
16	To Sand Down, Putty and Spray Paint on Necessary Damaged Parts	1.00	680.00	680.00 ⁶⁰⁰
				Amt S\$ 2180.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 2180.00

Total: 4590
 L/s 13650

Adrian Lj
 L/s 25/11/19
 06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LIST ITEMS Subtotal S\$ 3903.60
SPECIAL NETT ITEMS Subtotal S\$ 50.00
LABOUR Subtotal S\$ 2180.00
Total S\$ 6133.60 ⁵²

BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701
 BLK 3014 UBI ROAD 1 #01-406, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234
 EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
 WEBSITE: www.jhk.com.sg

bizSAFE₃

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19020776/ATD3N2

Date: 03/12/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19114519000	
Claimant Vehicle No :	SLR3311X	Insured Vehicle No :	WC4734B	
Date of Loss:	21/11/2019	Nature of Claim:	TP	Claim No: SNM19D205562C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR3311X	Engine No:	LEB6321532
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71117462
Reg. Date:	10/08/2017 (Man. Year: 2017)	Odometer:	61539 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,953.52	3,110.00	843.52	21.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	1,480.00	700.00	32.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,133.52	4,590.00	1,543.52	25.17
Approved Total (Overridden) (S\$)		3,650.00		
(S\$)	6,133.52	3,650.00	2,483.52	40.49
+ GST 7.00/7.00% (S\$)	429.35	255.50	173.85	40.49
Nett Amount (S\$)	6,562.87	3,905.50	2,657.37	40.49

INSPECTION

Date of Assignment:	03/12/2019	
Date Inspected:	25/11/2019	Inspected At: Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406 Singapore 408701
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Dec 2019)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR3311X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,150.60 FL	*1,150.60 FL
2	2		*REAR BUMPER SIDE RETAINERS	Necessary	53.00 FL	*53.00 FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	241.00 FL	*- FL
4	2		*REAR BUMPER REFLECTOR COVER	Not Necessary	90.00 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
6	1		*TAILGATE RH OUTER LAMP	Cracked	520.50 FL	*520.50 FL
7	1		*TAILGATE LH INNER LAMP	Not Necessary	340.80 FL	*- FL
8	1		*REAR RH FENDER	Distorted	1,010.90 FL	*1,010.90 FL
9	1		*REAR RH DOOR	Distorted	799.50 FL	*799.50 FL
10	1		*REAR RH DOOR HANDLE	Cut	108.00 FL	*108.00 FL
11	1		*REAR RH DOOR LOCK	Damaged	210.00 FL	*210.00 FL
12	1		*REAR RH DOOR STAY	Not Necessary	320.10 FL	*- FL
13	1		*REAR NUMBER PLATE WITH COVER	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,929.40	3,887.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	975.88	777.50
Total Parts (\$\$)	3,953.52	3,110.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND INSTALL RH QUARTER GLASS	New	150.00	80.00
2	TO PANEL BEAT ON NECESSARY DAMAGED PARTS	New	1,350.00	800.00
3	TO SAND DOWN,PUTTY AND SPRAY PAINT ON NECESSARY DAMAGED PARTS	New	680.00	600.00
Gross Labour Cost (\$\$)			2,180.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >