

Kd

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) Fax: 64514658

GST Reg No. 201629438M

10/11/19
Morday
Kenneth

21/11/2019

Owner: LE MOTOR CAR RENTAL PTE LTD

Not available
C1 Rn @ 1800h
Resuming After Rainy
3 days

ESTIMATE TO REPAIR TOYOTA AXIO - SLG1468Z

1pc	front bonnet
1pc	front bonnet inner lock
2pcs	front headlamp @\$781.90
1pc	front centre grille
1pc	front centre grille "TOYOTA" logo
1pc	front bumper
2pcs	front bumper side retainer @\$132.25
1pc	front bumper sponge
1pc	front bumper reinforcement
1pc	front support panel
1pc	front support panel centre pillar

R	\$	972.45	X
n	\$	182.10	X
NLS mgc	\$	1,563.80	2x
cm	\$	374.25	—
mc	\$	123.05	—
mg car	\$	481.10	2
sn	\$	264.50	X
sn	\$	141.45	X
R	\$	374.75	X
R	\$	972.10	X
sn	\$	182.25	X

less 25%

\$ 5,631.80

\$ 1,407.95

\$ 4,223.85

1 set front number plate & casing

No s.nett \$ 50.00 45/

wiring
tuffkote
spray painting
labour charges
Total

\$	80.00	201
nn	\$	100.00 X
\$	1,000.00	400
\$	1,000.00	500
\$	6,453.85	



L&K Auto Care works hereby
the Repairer of the following:

- To remove surface after spray painting
- To repair (or damaged parts) using resin
- To repair (or damaged parts) using resin
- To repair (or damaged parts) using resin
- To repair (or damaged parts) using resin
- To repair (or damaged parts) using resin
- To repair (or damaged parts) using resin
- To repair (or damaged parts) using resin

Authorised Signature: [Signature]