



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

28 November 2019

QUOT201911-000039

HHTPCLAIMS19-215

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET, #04-00 / #05-00
IOB BUILDING
SINGAPORE 049711

Attn: Motor Claims Department

ACCIDENT INVOLVING GBE1696K & SHB4155E ON 14/11/2019 ALONG ROAD CLEMENTI ROAD LAMP POST 33 AT ABOUT 2210 HOURS

Insured : INTEGRATE ENGINEERS PTE. LTD.
Vehicle Registration No. : GBE1696K
Vehicle Make : TOYOTA
Vehicle Model : TOYOTA DYNA 150 MANUAL
Vehicle Chassis No. : JTFAT35Y00K204370
Policy No. : D19MTPCVE002027
Date of Accident : 14/11/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper / CR4		\$ 556.20
2	1	Front Grille / CR4		\$ 450.00
3	1	Front Grille Moulding / CRA		\$ 45.10
4	10	Front Grille Clip / NEC	\$ 3.50	\$ 35.00
5	1	Emblem / NEC		\$ 69.10
6	1	Front Logo (DYNA) / NEC		\$ 58.40
7	1	Front Panel Garnish (RH) X		\$ 127.90
8	1	Front Panel / CR4		\$ 1,019.30
9	1	Front Lower Corner Panel (RH) / CR4		\$ 241.70
10	1	Front Headlamp (RH) / CR4		\$ 573.30
11	1	Front Door Step (RH) / CRA		\$ 235.90
12	1	Front Door (RH) / DD		\$ 1,950.20
13	2	Front Door Hinge (RH) (Upper/Lower) ?	\$ 72.40	\$ 144.80
14	1	Side Mirror (RH) / SCR		\$ 313.80
15	1	Rear Lock Lever (LH) / CR4		\$ 390.00
16	1	Rear Gate / DD		\$ 1,137.67
17	1	Rear Gate Logo (TOYOTA) / NEC		\$ 127.40
18	4	Rear Gate Hinge / CR4	\$ 159.40	\$ 637.60
19	1	Rear Side Gate (LH) / CR4		\$ 1,596.10
20	6	Rear Side Gate Hinge ?	\$ 231.70	\$ 1,390.20
21	1	Rear Taillamp (LH) / MIS		\$ 255.10
22	1	Rear Taillamp Bracket (LH) / MIS		\$ 184.10
23	1	Rear Axle (Complete) ?		\$ 3,542.50
24	2	Rear Absorber (LH/RH) / CR4	\$ 222.50	\$ 445.00
25	1	Rear Leaf Spring (LH) ?		\$ 1,575.80

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

28 November 2019

QUOT201911-000039

HHTPCLAIMS19-215

ACCIDENT INVOLVING GBE1696K & SHB4155E ON 14/11/2019 ALONG ROAD CLEMENTI ROAD LAMP POST 33 AT ABOUT 2210 HOURS

Estimate Repair List for vehicle GBE1696K - TOYOTA TOYOTA DYNA 150 MANUAL

S/N	Quantity	Description	Unit Price S\$	Amount S\$
26	2	Rear Leaf Spring Shackle Kit (LH/RH) / BT	\$ 127.50	\$ 255.00
27	4	Rear Leaf Spring U-Bolt (LH/RH) ?	\$ 111.70	\$ 446.80
28	1	Rear Leaf Spring Bumper Stopper (LH) / Nec		\$ 166.70
29	2	Rear Leaf Spring Seat (LH) ?	\$ 199.70	\$ 399.40
30	1	Propeller Shaft X SVC		\$ 2,221.70
31	2	Propeller Shaft Universal Joint ?	\$ 295.00	\$ 590.00
32	3	Rear Exhaust Pipe Stopper ?	\$ 59.10	\$ 177.30
33	2	Rear Wheel Bearing (LH/RH) Outer / Jan	\$ 111.70	\$ 223.40
34	2	Rear Wheel Bearing (LH/RH) Inner / Jan	\$ 159.40	\$ 318.80
35	2	Rear Mud Guard (LH) Front/Back / BT	\$ 265.40	\$ 530.80
36	1	Rear Carrier Floor Panel / BT		\$ 2,350.00
				\$ 24,782.07
Less 20%				\$ 4,956.41
				\$ 19,825.66
37	1	Towing Fee ? Receipt	NETT	\$ 150.00 100 ?
38	1	Rear Tyre (LH) Outer X SVC	NETT	\$ 200.00
39	1	Reverse Sensor / CR4	NETT	\$ 250.00 200
40	1	Company Sticker / Nec	NETT	\$ 25.00
41	1	Door Company Logo (RH) / NEC	NETT	\$ 250.00 150
42	1	Side Gate Company Name / NEC	NETT	\$ 450.00 200
43	1	Sticker (13 pax) / Nec	NETT	\$ 10.00
44	1	Sticker (70km/h) / Nec	NETT	\$ 10.00
To dismantle, cut & weld front panel, change front bumper, front RH corner panel, front grille, front RH door, front RH headlamp, rear LH mud guard, rear LH taillamp, rear tailgate, LH side gate, rear carrier floor panel, knocking & pull straight front RH lower panel, front RH floor panel, rear cabin panel and all area affected by accident				\$ 2,600.00 1,800
To perform wire checking				\$ 20.00
To dismantle & refit front RH door mechanism and fitting to new door				\$ 60.00
To dismantle & refit rear axle				\$ 250.00 200
To dismantle & refit rear propeller shaft				\$ 250.00 X
To dismantle & refit rear LH/RH undercarriage				\$ 300.00 200
To perform 4 wheel alignment				\$ 150.00 80

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

28 November 2019

QUOT201911-000039

HHTPCLAIMS19-215

ACCIDENT INVOLVING GBE1696K & SHB4155E ON 14/11/2019 ALONG ROAD CLEMENTI ROAD LAMP POST 33 AT ABOUT 2210 HOURS

Estimate Repair List for vehicle GBE1696K - TOYOTA TOYOTA DYNA 150 MANUAL

S/N	Quantity	Description	Unit Price S\$	Amount S\$
		To dismantle & refit rear LH tyre		\$ 80.00 X
		To dismantle & supply rear canopy / BT		\$ 2,000.00 1,500
		To dismantle & refit engine and gearbox mounting		\$ 350.00 X
		To dismantle & refit front seat, inner trim to facilitate repair		\$ 100.00 60
		To dismantle & refit rear exhaust pipe system		\$ 100.00 60
		To spray front panel, front RH corner panel, front grille, front bumper, front RH door, front RH floor panel, front LH corner panel, rear cabin panel, rear tailgate, rear LH side gate and all area affected by accident		\$ 2,000.00 1,700

\$ 29,430.66

7% GST \$ 2,060.15

Total \$ 31,490.81

L/S

After paint.

Repair day - 13 days

Sun Pin (Ltd)
TP without prejudice.

Authorised by Claims Dept