

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C**AAD1911-177***Not Authorized**1 Snp @ 9350p*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 NOV 2019

SHC 5980C

VF1ABL15AUC281511

RENAULT

LATITUDE

21.11.19

CHINA TAIPING

23/3/2015

PART

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	BUMPER BLOCK LH REAR
14	1	BUMPER BLOCK RH REAR
15	1	BUMPER HARNESS REAR
16	1	BOOT REAR
17	1	BOOT FINISHER
18	1	BOOT WHEATERSTRIP
19	1	BOOT REFLECTOR LAMP LH
20	1	BOOT REFLECTOR LAMP RH
21	1	BOOT BADGE 'RENAULT'
22	1	BOOT BADGE
23	1	BOOT STRUT LH
24	1	BOOT STRUT RH
25	1	BOOT HINGE LH
26	1	BOOT HINGE RH
27	1	BOOT INNER BOARD

LIST

\$	<i>Bz</i>	561.70	—
\$	<i>Bz</i>	411.90	—
\$	<i>CM</i>	98.10	—
\$	<i>Sn</i>	82.10	X
\$	<i>Sn</i>	59.80	X
\$	<i>Brv</i>	16.60	—
\$	<i>D1</i>	80.80	—
\$	<i>D1</i>	54.20	—
\$	<i>CM</i>	16.60	—
\$	<i>Bz</i>	547.80	—
\$	<i>Bz</i>	114.50	—
\$	<i>Bz</i>	100.90	—
\$	<i>R</i>	75.70	X
\$	<i>R</i>	76.50	X
\$	<i>Sn</i>	301.10	X
\$	<i>BT</i>	1,677.20	—
\$	<i>CM</i>	344.70	—
\$	<i>DIS/AD</i>	178.20	<i>5065m 89.105m</i>
\$	<i>CM</i>	277.70	—
\$	<i>CM</i>	277.70	—
\$	<i>Re</i>	82.40	—
\$	<i>Re</i>	95.80	—
\$	<i>Sn</i>	145.10	X
\$	<i>Sn</i>	145.10	X
\$	<i>R</i>	254.20	X
\$	<i>R</i>	253.80	X
\$	<i>Sn</i>	611.00	X

Trans-cab Auto Services Pte Ltd**AAD1911-177**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C

28	1	BOOT SWITCH	\$	SL	113.00	
29	1	BOOT LOCK	\$	K	246.60	
30	1	BOOT LOCK CATCH	\$	K	41.70	
31	2	LICENCE PLATE LAMP	\$	SL	26.30	
32	2	BOOT RUBBER PLUG	\$	SL	139.30	
33	2	BOOT BUFFER	\$	SL	26.80	
34	1	BOOT LOCK LINKAGE	\$	SL	20.60	
35	1	BOOT LOCK LINKAGE HOLDER	\$	SL	99.50	
36	1	BOOT TRIM BOARD	\$	SL	611.00	
37	1	FENDER PANEL INNER TRIM REAR LH	\$	SL	671.45	
38	1	FENDER PANEL REAR LH	\$	Bu	1,933.20	
39	1	WHEELARCH REAR LH	\$	SL	181.60	X
40	1	FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45	X
41	1	FENDER PANEL REAR RH	\$	K	1,933.20	X
42	1	WHEELARCH REAR RH	\$	SL	275.40	X
43	1	AIR VENT LH	\$	SL	59.40	X
44	1	AIR VENT RH	\$	SL	59.40	X
45	1	TAILLAMP RH	\$	not chg	313.10	
43	1	TAILLAMP PANEL RH	\$	K	401.40	X
44	1	TAILLAMP LH	\$	Bu	401.40	
45	1	TAILLAMP PANEL LH	\$	Bu	401.40	
46	1	OUTER PANEL REAR (End Panel)	\$	Bu	745.80	
47	1	OUTER PANEL REAR (End Panel)TRIM	\$	not chg	404.56	
48	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	K	1,229.40	
49	1	SPARE WHEEL PANEL TRIM	\$	SL	612.21	
50	1	SPARE TYRE BOARD	\$	SL	680.90	
51	1	EXHAUST REAR	\$	K	5,263.60	
52	1	EXHAUST CAP REAR	\$	K	125.40	
53	1	FUEL FLAP	\$	SL	244.70	
TOTAL			\$		24,874.97	
10%			\$		2,487.50	
			\$		22,387.47	

Special Nett

1	1SET PARKING AID	\$	Shom	700.00	400.00
2	1SET REAR BUMPER CLIP	\$	rec	66.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C**AAD1911-177**

3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i>	33.00	<i>✓</i>
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	<i>X</i>
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i>	20.00	<i>X</i>
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	<i>X</i>
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i>	20.00	<i>X</i>
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	<i>X</i>
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	<i>✓</i>
10	1 EXHAUST MOUNTING REAR	\$	<i>sn</i>	16.00	<i>X</i>
11	1 EXHAUST BRACKET REAR	\$	<i>sn</i>	24.80	<i>X</i>
12	1SET BOOT FINISHER CLIP	\$	<i>na</i>	24.20	<i>X</i>
13	1 BOOT STICKER "Trans-cab"	\$	<i>na</i>	30.00	<i>✓</i>
14	1 BOOT STICKER "6555-3333"	\$	<i>na</i>	30.00	<i>✓</i>
15	1 BOOT INNER TRIM CLIP	\$	<i>na</i>	45.00	<i>X</i>
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>na</i>	35.00	<i>X</i>
17	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sn</i>	385.00	<i>X</i>
18	1 SPARE TYRE	\$	<i>sn</i>	330.00	<i>X</i>
19	1 FENDER INNER TRIM CLIP LH	\$	<i>na</i>	28.00	<i>X</i>
20	1 TAILLAMP CLIP RH	\$	<i>na</i>	5.00	<i>✓</i>
21	2 REAR WINDSCREEN SEALANT	\$	<i>na</i>	80.00	<i>40sm</i>
22	1 WINDSCREEN MOULDING	\$	<i>na</i>	100.00	<i>X</i>
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	<i>30sm</i>
24	1 TAILLAMP CLIP LH	\$	<i>na</i>	5.00	<i>✓</i>
25	1 Rear Bumper Protector	\$	<i>na</i>	100.00	<i>X</i>
26	1 REAR LEFT TYRE	\$	<i>sn</i>	300.00	
27	1 REAR LEFT TYRE RIM	\$	<i>sn</i>	380.00	
28	1 REAR RIGHT TYRE	\$	<i>sn</i>	300.00	
29	1 REAR RIGHT TYRE RIM	\$	<i>sn</i>	380.00	
30	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>na</i>	35.00	<i>45sm</i>
31	1 FENDER INNER TRIM CLIP RH	\$	<i>na</i>	28.00	
32	1SET Rear licence plate with holder	\$	<i>na</i>	80.00	
TOTAL		\$		3,788.00	

TOTAL PARTS \$ 26,175.47**LABOUR**

Putty And Spray Painting Of The Affected Portion.

\$

7,500.00

*1100h**1200h*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C**AAD1911-177**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	12001
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	601
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 1001
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	901
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	1201

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C**AAD1911-177**

To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	na 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	↪ 380.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	↪ 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	↪ 380.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	↪ 380.00	X
TOTAL	\$	19,580.00	
Over All Total	\$	45,755.47	

(LUMP SUM) Repair Days~~25 DAYS~~

8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: