



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF19020807/Atd3s2

ACCIDENT CLAIMS SECTION (SPORE POLICE
FORCE) POLICE LOGISTICS BASE (PLB) 1
HEMMANT ROAD SINGAPORE 438675

Date : 03-02-2020



ATTN: HAFIZUL FARHAN

Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	TP 123H	Veh. Inspected	SJE 3270Y
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/114	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	25/11/2019

2. Vehicle Particulars & Condition

Make & Model	RENAULT FLUENCE	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	VF1LZB50TUC245401	Colour	WHITE
Odometer	311900	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	CONTINENTAL	6 mm
L/H Front Tyre	205/60 R16	CONTINENTAL	6 mm
R/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm
L/H Rear Tyre	205/60 R16	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/11/2019	Inspection Date	26/11/2019
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------