

4/5 \$ 3300
 Not Authorized
 27/11/19
 Take photo. Attach paper
 4 day.

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50
 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
 TEL: 6886 9097 FAX: 6886 9095 Email: claims@focusauto.com.sg
 GST:200712509E RCB NO:201004495RM/s :

Estimate No: EST0001059

Date: 26 Nov 2019

Veh Reg No: **SMK3178P**

Make/Model: BYD E6H ELECTRIC

Chassis No: LCOCE4DB4K1000314

Reg. Date: 04/04/2019

ATTN: Motor Claim Department
 Your Ref No: SMK3178P BYD E6H
 Claim Type: Third Party
 Accident Date: 22/11/2019

Estimate Repair Cost to Vehicle No :SMK3178P

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			\$S	\$S
List Price				
1 Front Fender - LH	659.00	1 PC	659.00	✓
2 Front Head Lamp - LH	890.20	1 PC	890.20	✓
3 Front Bumper - LH	1,100.20	1 PC	1,100.20	✓
4 Front Bumper Side Retainer - LH	48.60	1 PC	48.60	✓
5 Front Bumper Reflector - LH	56.20	1 PC	56.20	✓
6 Front Bumper Lamp	289.40	1 PC	289.40	✓
7 Front Bumper Reinforcement	482.20	1 PC	482.20	✓
8 Front Bumper Sensor	296.40	1 PC	296.40	2005. ✓
			3,822.20	3,822.20
Labour				
9 Panel Beating	850.00	1 PC	850.00	580
10 Check Wiring	60.00	1 PC	60.00	20
11 To Remove & Replace Bumper Sensor	80.00	1 PC	80.00	50
12 Spray Painting	800.00	1 PC	800.00	700
			1,790.00	1,790.00
			Total	\$S 5,612.20

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SIX HUNDRED TWELVE AND CENTS TWENTY ONLY

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

7-2866.80
 102
 7-2880.12
 200-200.00
 1-1350.00
 4130.12
 202

For FOCUS AUTO PTE LTD

AUTHORISED SIGNATURE