

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate : Accident Repairs
Workshop : 24 Benoi Sector
Contact No : 6474 3323
Fax No : 6264 6786
Reference : PAC/TP/0074/2019/GW
Date : 23-Nov-19

Vehicle not in workshop . Kindly arrange for survey.

Your insured vehicle no: SFZ 2800 L

NTUC Income Insurance Co - Claims Department

73 Bras Basah Road

#05-01 NTUC Trade Union House

Singapore 189556

**Hi Steve (LKK),
Total 3 days**

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Mr. Chow Ho Yin
Address : 107 Bukit Batok West Ave 6
#06-112
Singapore 650107
Telephone : (HP)91173172
Type of Claim : Third Party Claims
Policy No. : 5112646522
Vehicle No : **SLS 2782 X**
Model Code : Mazda 6 Sedan 2.0 AT
Model / Year : Jan-16
Engine No : PE20957474
Chassis No : JM6BM4278G0328992
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 17-Nov-19
Place of Accident : PIE Towards Changi

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Estimated Labour Charges for Accident Vehicle SLS 2782 X

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
				Remarks
1	To remove and transfer rear parking sensor wiring, check function.	S/N	\$ 80.00	\$ 50.00
2	To dislodge and reinstall rear wiring harness to repair spare wheel housing.	S/N	\$ 100.00	
3	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.		\$ 1,200.00	\$ 200.00
4	To respray rear bumper.		\$ 1,000.00	\$ 200.00
5	To carry out diagnostic check.	S/N	\$ 150.00	\$ 120.00
TOTAL LABOUR CHARGES		:	<u>\$ 2,530.00</u>	<u>\$ 570.00</u>

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No.SLS 2782 X

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
			Parts -20%
1	REAR BUMPER	\$ 1,000.00	\$ 800.00
2	REAR BUMPER TOW EYE COVER-RH	\$ 38.00	\$ 30.40
3	REAR BUMPER RETAINER-LH/RH	2 \$ 80.00	\$ 64.00
4	REAR BUMPER LIGHT REFLECTOR-LH/RH	2 \$ 100.00	
5	REAR BUMPER PARKING SENSOR-LH/RH	2 \$ 400.00	\$ 320.00
6	REAR REINFORCEMENT BAR	\$ 488.00	
7	REAR BUMPER BRACKET-LH/RH	2 \$ 100.00	
8	REAR END PANEL - OUTER	\$ 625.00	
9	ACRYLIC SEALANT	S/N \$ 180.00	
10	CAVITY WAX	S/N \$ 140.00	
11	STONE CHIP	S/N \$ 180.00	
12	SUNDRIES	\$ 50.00	
TOTAL SPARE PARTS CHARGES		: \$ 3,381.00	\$ 1,214.40
TOTAL LABOUR CHARGES		: \$ 2,530.00	\$ 570.00
GRAND TOTAL		: \$ 5,911.00	\$ 1,784.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
[Tel:6474 3323 for appointment.](tel:64743323)

Yours faithfully,
Premium Autocare Centre

Allan Wu
Body Shop Manager