

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) , Fax: 64514658
GST Reg No. 201629438M

20/11/2019

Owner: ACE FLEET MANAGEMENT PTE LTD

ESTIMATE TO REPAIR HONDA FREED - SME5850A

1pc	rear bumper	BT	\$	991.20	✓
1pc	rear bumper RH side retainer		\$	121.25	X
1pc	rear bumper RH side refector		\$	185.20	X
				\$ 1,297.65	
	less 20%			\$ 259.53	
				\$ 1,038.12	

1 set	rim half cap			
	wiring		\$ 60.00	101
	spray painting		\$ 600.00	2201
	labour charges		\$ 600.00	1501
	Total		<u>\$ 2,478.12</u>	

Not with arrow
C1 by 8?
2 days



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company