

...CLAIM SUBFOLDER...(Pending for Survey Report)

Non-Reporting WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Nov 2019 Edit Reg		25 Nov 2019 00:00 Edit Adj Rpt	S\$1,000.00 Edit Estimates	S\$1,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: ACE FLEET MANAGEMENT PTE. LTD., Co. Reg. No.: 201710914N									
Vehicle Reg. No.: SME5850A		Date of Loss: 20/11/2019 15:00 - :59 [13 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MFL2019D0001488		Policy/Cover Note No.: D19MFL0005549							
Vehicle Reg. No. (Insured): GBJ5378B		Policy No. (Claimant): DMHCSN1930791900							
Excess:									
Repairer: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Bhargari Purushothaman Dhanya]									
Claimant's Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/12/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
III_SG (07/04/2020): Alert - Adj Mandate Maintained - SME5850A - Claim Handler: Bhargari Purushothama...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SME5850A (MFL2019D0001488)**
[GBJ5378B]
TP
ACE FLEET MANAGEMENT PTE. LTD.
Nov 20 2019 3:00PM
[-]
Hui Yang Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#) ▼

Documentation			1 per page ▼	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/11/19 18:03	EMAIL FROM III DD 25.11.19	Load PDF	
2	25/11/19 18:03	TP ESTIMATE + TP GIA REPORT	Load PDF	
3	20/02/20 11:36	TP ESTIMATE - MARKED	Load PDF	
4	12/04/20 12:36	EMAIL TO TP	Load PDF	
5	13/04/20 10:48	LKK RESURVEY PHOTO 2 (REINSPECTION)	Load PDF	
6	13/04/20 10:48	LKK RESURVEY PHOTO (REINSPECTION)	Load PDF	
7	13/04/20 10:48	LKK SURVEY PHOTO (GENERAL VIEW)	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:
☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III19020836/KGA3S2**Date:** 20/04/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SME5850A	Insured Vehicle No :	GBJ5378B
Date of Loss:	20/11/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0001488

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME5850A	Engine No:	LEB5604498
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71070440
Reg. Date:	05/10/2018 (Man. Year: 2018)	Odometer:	113034 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	West Lake 9 mm	Rear Left Side:	West Lake 9 mm
Front Right Side:	West Lake 9 mm	Rear Right Side:	West Lake 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,218.12	972.96	245.16	20.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	380.00	880.00	69.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,478.12	1,352.96	1,125.16	45.40
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	2,478.12	1,000.00	1,478.12	59.65
+ GST 7.00/7.00% (S\$)	173.47	70.00	103.47	59.65
Nett Amount (S\$)	2,651.59	1,070.00	1,581.59	59.65

INSPECTION

Date of Assignment:	25/11/2019	
Date Inspected:	26/11/2019	Inspected At: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2020)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME5850A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	991.20 FL	*991.20 FL
2	1		*REAR BUMPER RH SIDE RETAINER	Serviceable	121.25 FL	*- FL
3	1		*REAR BUMPER RH SIDE REFLECTOR	Serviceable	185.20 FL	*- FL
4	1		*SET HALF CAP	Dented / Scratched	180.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,477.65	1,171.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	259.53	198.24
Total Parts (\$\$)	1,218.12	972.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRING.	New	60.00	10.00
2	SPRAY PAINTING.	New	600.00	220.00
3	LABOUR CHARGES.	New	600.00	150.00
Gross Labour Cost (\$\$)			1,260.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >