

輝陽汽車有限公司  
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658  
GST Reg No. 201629438M

20/11/2019

Owner: ACE FLEET MANAGEMENT PTE LTD

**ESTIMATE TO REPAIR HONDA FREED - SME5850A**

|          |                               |             |      |
|----------|-------------------------------|-------------|------|
| 1pc      | rear bumper                   | \$ 991.20   | 7    |
| 1pc      | rear bumper RH side retainer  | \$ 121.25   | X    |
| 1pc      | rear bumper RH side reflector | \$ 185.20   | X    |
|          |                               | \$ 1,297.65 |      |
| less 20% |                               | \$ 259.53   |      |
|          |                               | \$ 1,038.12 |      |
| 1set     | rim half cap                  | \$ 180.00   | ✓    |
|          | wiring                        | \$ 60.00    | 101  |
|          | spray painting                | \$ 600.00   | 2201 |
|          | labour charges                | \$ 600.00   | 1501 |
|          | Total                         | \$ 2,478.12 |      |

Not with arm  
C/Ly 8?  
2day



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: