

INS. CASE OWNER:

SALIHA

CC4/AIG19020841/Ada352

LKK:

IDAC:

Surveyor:

ADRIAN

DOI:

26/11/2019

Date / Time:

25.11.2019

Registered in Merimen:

25.11.2019

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLX 6562L

Name of Insured:

HO TUCK CHUEN

Insured Tel No.:

62983673

HP: +65-98325290

Excess Sec II :SS

D.O.A: 21/11/2019 18:40

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

7022655634SG

Policy No.:

1900246734

Make / Model:

MITSUBISHI OUTLANDER-2.0 (A)

Place of Accident:

CTE TOWARDS SLE BETWEEN BRADDELL & AMK

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKJ 9730J

SLX 6562L

SMN 787K

SLS 6866L



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

OI



INSRS:

WSP: DYNAMIC

Tel: AUTOWORK

Liability:

RMKS: TP



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SMN 787K- X

SLX 6562L - X

STAGE

DATE / PIC

5/2/2020 - FILE PASS TO TYPE MANDATE

6/3/2020 - FILE PASS TO MMU TO WORK

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with: Michelle

Email ☐Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 26

Repair Cost: (w/hst)

SS 15622.00

If NO or B 28, Ass. Lia : OL

4 veh C.C. 02 was 3rd

Loss of Rental (LOR):

SS 1000.00

(

10 days) x \$100

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 7.45

Medical:

SS -

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS -

(e.g. Tow/ Independent)

2) Report Format: TP

Legal Cost

SS -

3) Survey fee: \$320

Total:

SS 16629.45

Global Sum SS: 16600.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

SS 16600.00

Name 1:

Dynamic Autowork Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF:

ALG

ASSIGNMENT

From:

Date:

26/11/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SMN 787K

at Workshop m/s

Dynamic Autowork

of

8 Kaki Bulkit Ave 4 #08-09 premier

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

16

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMN 787K

Yr Regn: 2009 August

Type: ☒ M. Car / ☐ M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Premio

c.c 1496

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

116837

T/Radio: Insured / Std / NI / NA

Eng/No:

NZT2603037476

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fulker

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

26/11/19

Survey held at

Dynamic

Des. of Damages ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP A/G.

L/S - \$14600 (Red \$10921.40 / 54%)

COE Expiry: 26/08/24

MV: 30K.

PV: 14K.

Net: 16K

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos:

Other:

TOTAL

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Week end (\$)

Report Format:

Lump Sum / L&M (\$)

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 25.11.19

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMN787K**
MODEL : **TOYOTA PREMIO**
DATE OF ACCIDENT : 21.11.19
TIME OF ACCIDENT : 17:50HRS

Jiale

NZT2603087476

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Rebond</i>	1	\$ 791.10	\$ 791.10
2	FRONT BUMPER LOWER GRILLE <i>crackd</i>	1	\$ 113.40	\$ 113.40
3	FRONT BUMPER LOWER COVER GARNISH <i>new</i>	1	\$ 125.10	\$ 125.10
4	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 60.30	\$ 120.60
5	FRONT BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 211.60	\$ 211.60
6	FRONT BUMPER SPONGE <i>crackd</i>	1	\$ 183.50	\$ 183.50
7	FRONT RADIATOR GRILLE WITH LOGO <i>crack</i>	1	\$ 317.70	\$ 317.70
8	HEADLAMP <i>crackd</i>	2	\$ 791.10	\$ 1,582.20
9	FRONT FENDER LH <i>Repair</i>	1	\$ 531.10	\$ 531.10
10	FRONT FENDER INNER COWLING <i>new</i>	2	\$ 151.10	\$ 302.20
11	BONNET <i>Buckled</i>	1	\$ 624.40	\$ 624.40
12	BONNET MOULDING <i>crack</i>	1	\$ 167.10	\$ 167.10
13	BONNET HINGE <i>new</i>	2	\$ 68.10	\$ 136.20
14	BONNET STOPPER <i>new</i>	2	\$ 18.00	\$ 36.00
15	BONNET LOCK <i>new</i>	1	\$ 79.40	\$ 79.40
16	BONNET LOCK BRACE PANEL <i>Bent</i>	1	\$ 98.10	\$ 98.10
17	BONNET INSULATOR <i>new</i>	1	\$ 312.40	\$ 312.40
18	FRONT SUPPORT PANEL <i>Buckled</i>	1	\$ 744.60	\$ 744.60
19	AIR CONDENSOR <i>Dented</i>	1	\$ 731.40	\$ 731.40
20	RADIATOR <i>Bent</i>	1	\$ 794.10	\$ 794.10
21	RADIATOR CENTER TOP BRACKET <i>crackd</i>	1	\$ 139.40	\$ 139.40
22	RADIATOR TOP BRACKET <i>3 new</i>	2	\$ 18.00	\$ 36.00
23	RADIATOR MOUNTING	4	\$ 28.40	\$ 113.60
24	TEMPERATURE SENSOR <i>new</i>	1	\$ 198.00	\$ 198.00
25	BOOT LID <i>Distorted</i>	1	\$ 801.30	\$ 801.30
26	BOOT LID MOULDING <i>crack</i>	1	\$ 238.10	\$ 238.10
27	BOOT LID NUMBER PLATE LAMP <i>shot new</i>	2	\$ 166.30	\$ 332.60
28	BOOT LID LOGO <i>new</i>	1	\$ 65.00	\$ 65.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMN787K**
 MODEL : **TOYOTA PREMIO**
 DATE OF ACCIDENT : 21.11.19
 TIME OF ACCIDENT : 17:50HRS

29	BOOT LID EMBLEM 'PREMIO' <i>Neu</i>	1	\$ 63.30	\$ 63.30	✓
30	BOOT LID EMBLEM 'F' <i>Neu</i>	1	\$ 55.90	\$ 55.90	✓
31	BOOT LID DETECTOR <i>Cracked</i>	1	\$ 194.10	\$ 194.10	✓
32	BOOT LID LAMP <i>Cracked</i>	2	\$ 310.20	\$ 620.40	✓
33	BOOT LID STOPPER <i>Not Neu</i>	4	\$ 15.00	\$ 60.00	+
34	BOOT LID TOP LOCK <i>Damaged</i>	1	\$ 313.40	\$ 313.40	✓
35	BOOT LID LOWER LOCK <i>Not Neu</i>	1	\$ 24.60	\$ 24.60	X.
36	BOOT LID SWITCH BUTTOM <i>Not Neu</i>	1	\$ 131.60	\$ 131.60	+
37	BOOTLID HINGE <i>Best</i>	2	\$ 135.50	\$ 271.00	✓
38	BOOTLID HINGE GARNISH <i>Not Neu Deland</i>	2	\$ 110.30	\$ 220.60	✓
39	BOOTLID INSULATOR <i>Not Neu</i>	1	\$ 221.10	\$ 221.10	+
40	BOOT LID WEATHERSTRIP <i>Cr</i>	1	\$ 198.30	\$ 198.30	✓
41	REAR FENDER <i>LH Buckled</i>	2	\$ 1,235.10	\$ 2,470.20	1235.10
42	REAR FENDER INNER COWLING <i>Not Neu</i>	2	\$ 98.70	\$ 197.40	+
43	REAR FENDER INNER TRIM <i>torn</i>	2	\$ 421.10	\$ 842.20	659.
44	REAR FENDER AIR VENT <i>Not Neu</i>	1	\$ 58.30	\$ 58.30	+
45	REAR WINDSCREEN MOULDING <i>Neu</i>	1	\$ 128.10	\$ 128.10	✓
46	REAR DOOR INNER LOCK <i>2</i>	2	\$ 328.70	\$ 657.40	+
47	REAR DOOR WEATHERSTRIP <i>Neu</i>	2	\$ 113.60	\$ 227.20	+
48	REAR DOOR INNER TRIM	2	\$ 605.10	\$ 1,210.20	+
49	REAR BUMPER <i>Distorted</i>	1	\$ 769.80	\$ 769.80	✓
50	REAR BUMPER SIDE RETAINER <i>Neu</i>	2	\$ 89.60	\$ 179.20	✓
51	REAR BUMPER BRACKET <i>Distorted</i>	2	\$ 55.10	\$ 110.20	✓
52	TAIL LAMP <i>cracked</i>	2	\$ 321.40	\$ 642.80	✓
53	TAIL LAMP LOWER BRACKET <i>Not Neu</i>	2	\$ 39.30	\$ 78.60	+
54	TAIL LAMP PANEL <i>Buckled</i>	2	\$ 226.10	\$ 452.20	✓
55	REAR END PANEL <i>Distorted</i>	1	\$ 411.10	\$ 411.10	✓
56	REAR END PANEL TOP GARNISH <i>Deland</i>	1	\$ 143.10	\$ 143.10	✓
57	REAR FLOOR PANEL <i>Distorted Repair</i>	1	\$ 853.40	\$ 853.40	X.
58	REAR FLOOR PANEL TOP BOARD <i>Deland</i>	1	\$ 138.60	\$ 138.60	✓
59	REAR FLOOR PANELSIDE TOP BOARD <i>Deland</i>	2	\$ 113.10	\$ 226.20	✓
60	REAR CHASSIS MEMBER RH <i>Repair</i>	1	\$ 221.10	\$ 221.10	+
61	REAR TOOLS TRAY <i>cut</i>	1	\$ 192.30	\$ 192.30	✓
62	SPARE TYRE BOLT <i>Best</i>	1	\$ 46.70	\$ 46.70	✓
63	CENTER EXHAUST <i>Not Neu</i>	1	\$ 1,483.50	\$ 1,483.50	+
64	CENTER EXHAUST INSULATOR <i>Not Neu</i>	1	\$ 189.10	\$ 189.10	+
65	CENTER EXHAUST GASKET (SET) <i>Not Neu</i>	1	\$ 60.10	\$ 60.10	+

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SMN787K
 MODEL : TOYOTA PREMIO
 DATE OF ACCIDENT : 21.11.19
 TIME OF ACCIDENT : 17:50HRS

66	REAR EXHAUST BOX	1	\$ 796.10	\$ 796.10
67	REAR EXHAUST INSULATOR	1	\$ 121.40	\$ 121.40
68	REAR EXHAUST BOX MOUNTING	3	\$ 29.40	\$ 88.20

15791.10
 11843.32

TOTAL PRICE \$ 25,295.20
 LESS 25% \$ 6,323.80
SUB TOTAL PRICE \$ 18,971.40

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP (SET)	1	\$ 50.00	\$ 50.00
3	BONNET SEALANT	1	\$ 150.00	\$ 150.00
4	BONNET MOULDING CLIP (SET)	1	\$ 50.00	\$ 50.00
5	BONNET INSULATOR CLIP (SET)	1	\$ 50.00	\$ 50.00
6	FRONT FENDER SEALANT LH	1	\$ 120.00	\$ 120.00
7	FRONT FENDER INNER COWLING (SET)	1	\$ 50.00	\$ 50.00
8	FRONT SUPPORT PANEL SEALANT	1	\$ 120.00	\$ 120.00
9	RADIATOR COOLANT	1	\$ 80.00	\$ 80.00
10	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00
11	REAR BUMPER CLIP (SET)	1	\$ 50.00	\$ 50.00
12	BOOT LID SEALANT	1	\$ 120.00	\$ 120.00
13	BOOT LID MOULDING CLIP (SET)	1	\$ 50.00	\$ 50.00
14	BOOTLID HINGE GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
15	BOOTLID INSULATOR CLIP (SET)	1	\$ 50.00	\$ 50.00
16	TAIL LAMP CLIP (SET)	1	\$ 80.00	\$ 80.00
17	TAIL LAMP PANEL SEALANT	1	\$ 120.00	\$ 120.00
18	REAR FENDER SEALANT	2	\$ 80.00	\$ 160.00
19	REAR FENDER INNER COWLING CLIP (SET)	1	\$ 30.00	\$ 30.00
20	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 50.00	\$ 50.00
21	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00
22	REAR WINDSCREEN INNER SHIELD	1	\$ 60.00	\$ 60.00
23	REAR DOOR INNER TRIM CLIP (SET)	1	\$ 80.00	\$ 80.00
24	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00
25	REAR END PANEL TOP GARNISH CLIP (SET)	1	\$ 80.00	\$ 80.00
26	REAR FLOOR PANEL INSULATION SEAL	1	\$ 350.00	\$ 350.00
27	REAR REVERSE SENSOR (4PCS)	1	\$ 380.00	\$ 380.00
28	REVERSE CAMERA	1	\$ 550.00	\$ 550.00

1040

TOTAL \$ 3,260.00

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SMN787K
 MODEL : TOYOTA PREMIO
 DATE OF ACCIDENT : 21.11.19
 TIME OF ACCIDENT : 17:50HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	800
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	800
3	REFOCUS HEADLAMP BEAM	\$ 80.00	x
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60

1720

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	\$ 2,800.00	1600
2	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	\$ 2,000.00	1400
3	TUFF COAT	\$ 250.00	120
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	100
6	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
7	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
8	REAR CHASSIS ALIGNMENT	\$ 250.00	x
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
10	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	80
12	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMN787K**
 MODEL : **TOYOTA PREMIO**
 DATE OF ACCIDENT : 21.11.19
 TIME OF ACCIDENT : 17:50HRS

13	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00	✓
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 9,290.00 3690

ESTIMATE REPORT

TOTAL PARTS COST : \$ 22,231.40
 TOTAL LABOUR COST : \$ 9,290.00
 TOTAL REPAIR COST : \$ 31,521.40

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY
 SERVICE ADVISOR
 ABBY
 HP : 9856 4815

Adrian L
 2/s 26/11/19.
 16 days.
 Total: 18293.32.
 1/s 14.61c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

PQP Paid:

COE Rebate Amount:

Total Rebate Amount:

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Nov 2019

Singapore NRIC
7291

SMN787K

No

21 Nov 2019

TOYOTA

PREMIO 1.5F A

Silver

2008

1NZD284885

NZT2603037476

81.0 kW (108 bhp)

\$19,708.00

27 Aug 2009

27 Aug 2009

2

\$19,708.00

Forfeited

-

\$0.00

26 Aug 2024

A - Car (1600cc & below)

5

\$14,664.00

\$13,970.00

\$13,970.00

COE till 08/2024



\$16530

OK

SUSS
SINGAPORE UNIVERSITY
OF SOCIAL SCIENCES



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) | [Advertiser Login](#) | [Ways of Selling](#)

Full service record with Wearnes, 69k km, \$8.3k rep



Full service record with Wearnes,
Wearnes only 69k km, wearnes
repaid 80.2k
360 VR Cars. 014 401



Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

1 vehicles

Toyota Premio (COE till 2024)

Advanced Search

	Name	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Premio (COE till 2024		Any	Any	Any	Any	Any	Any	Available
	Toyota Premio 1.5A F (COE till 08/2024)		\$30,500	\$6,470 /yr	07-Aug-2009	1,496 cc	140,000 km	Sedan	Available
	The Only Mid-Sized Car With Luxury Feels. Bank And In House Full Loan Available! Well Kept And Maintained By Previous Owner, New Paintwork With Clean And Neat Interior! View To Believe, Contact Our Name Sales Person Now For Viewing. Price Is Negotiable.								PREMIUM
	Ka-Hup Vehicles Trading								
	Posted: 16-Nov-2019 Tags: 2009 Toyota Premio, 2009 toyota premio, Toyota Premio, toyota premio, Toyota, Premio, premio, Used Toyota								

Save this search criteria, to get email alerts whenever a match is found.

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota Premio (COE till 2024, Toyota Premio (COE till 2024 Singapore, used Toyota Premio (COE till 2024 Singapore, used Toyota Premio (COE till 2024, used vehicles Singapore or even buy used Toyota Premio (COE till 2024 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.


 WATCH
SERIES 5

You've never

Toyota Premio (COE till 2024)

Price Range ▼

Depreciation ▼

Year Reg ▼

Vehicle Type ▼

Advanced
Search

Home » Used Cars » Ka-Hup Vehicles Trading » Toyota Premio 1.5A F (COE till 08/2024)

Toyota Premio 1.5A F (COE till 08/2024)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD



ESTABLISHED SINCE 1989



Price \$30,500

Depreciation \$6,470 /yr

Reg Date 07-Aug-2009
(4yrs 8mths 16days COE left)

Mileage 140,000 km (13.6k /yr)

Manufactured 2009

Road Tax \$682 /yr

Transmission Auto

Dereg Value \$13,820 as of today (change)

OMV \$18,852

COE \$14,664

ARF \$18,852

Engine Cap 1,496 cc

Power 81.0 kW (106 bhp)

Curb Weight 1,200 kg

No. of Owners 4

Type of Vehicle Mid-Sized Sedan

Features

16 Valves DOHC VVT-i Engine, 5 Speed CVT Automatic Transmission, SRS Airbags, Keyless Entry (Start/Stop), Climatic Control Aircon, View specs of the Toyota Allion (2007-2012)

Accessories

Leather Seats, Sports Rims, Auto Retractable Side Mirrors, Audio Player, Fog Lamps, Reverse Sensors/Camera, Integrated Remote Key.

Description

The Only Mid-Sized Car With Luxury Feels. Bank And In House Full Loan Available! Well Kept And Maintained By Previous Owner, New Paintwork With Clean And Neat Interior! View To Believe, Contact Our Name Sales Person Now For Viewing. Price Is Negotiable.

Category

COE Car, Premium Ad Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posters
Compare

©-2019



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Ka-Hup Vehicles Trading

45 vehicles for sale, 89 sold in past 3 mths

61 Ubi Avenue 2 #05-17
Automobile Megamart
Tel: 67419997
Search cars nearby

Alex Teo 92233133
Johnson Lim 90722292
Fun Heng 97507601

Upfront Payment

[More Financial Info](#)[used car list](#) | [company info](#)

Transfer Fee	\$25	
Down Payment	\$9,150 (change)	Maximum 70% Loan
1st Instalment	\$448	Based on 3.75% interest rate
Insurance	\$588 onwards (Get a quote) Extra 15% Off for MINDEF, MHA & POGIS policyholders Quote assumes a standard profile. "Get a quote" for exact figure.	
Total Upfront Payment	\$10,211	Check with seller for exact figure

Powered by

AVIVA

Products and Services

[View All](#)

Delivers Superior Handling
With Quieter Ride Comfort



Door Visor



Door Visor



LED Scuff Plate



Day Running Light



Bidded Carplate for Sale

[View all 13 suitable items for Toyota Premio](#)Check out the specialist workshop for Toyota cars: [Alliance Auto Pte Ltd](#)

Tags: Toyota Premio, toyota premio, 2009 Toyota Premio, 2009 toyota premio, Toyota, Premio, premio, Used Toyota

Recommended for you

1-6 of 14

CAT A	\$32,000	▲
CAT B	\$39,700	▼
CAT E	\$40,889	▲

Increase for Cat A and E
while Cat B falls



Approval granted to tap
e-scooter grant



Volkswagen ID. VIZZION
makes world debut



Toyota launches fully
redesigned Premio and
Allion



3 friends, over 700km of
roads and an A4

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Audi, Kia, Hyundai, Volkswagen, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, luxury cars, sports cars, SUV, MPV, hatchback or stationwagons. You can also buy from a car auction and look up car loans, financial services, low mileage cars, car brands, car insurance, carpark rates, car audio, car grooming, car rental, vehicle insurance, car insurance quotation, car blog, car accessories, car workshop & car sticker. Visit our partners for job openings, Singapore jobs, real estate properties for sale, facebook marketing, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.



New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Google Home.

Hands-free help around the house.



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Renewal Coe Toyota Altis 1.6A



2.68% P.A, \$0 Down, \$0 Admin,
Mthly from \$468, 2 Years
Warranty engine, gearbox
GV Credit StarAd



Think One Automobile

**NEW & USED
COMMERCIAL VEHICLES**



Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

5 vehicles

Search

premio

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

premio

Any

Any

Any

Any

Any

Any

Available



☐ Toyota Premio 1.5A F (COE till
08/2024)

\$30,500

\$6,490 /yr

07-Aug-2009

1,496 cc

140,000 km

Sedan

Available

The Only Mid-Sized Car With Luxury Feels. Bank And In House Full Loan Available! Well Kept And Maintained By Previous Owner, New Paintwork With Clean And Neat Interior! View To Believe, Contact Our Name Sales Person Now For Viewing. Price Is Negotiable.

PREMIUM AD

Ka-Hup Vehicles Trading

★ Posted: 23-Nov-2019

Tags: 2009 Toyota Premio, 2009 toyota premio, Toyota Premio, toyota premio, Toyota, Premio, premio,
Used Toyota



☐ Toyota Premio 1.5A F (New
10-yr COE)

\$46,888

\$4,680 /yr

26-Aug-2009

1,496 cc

98,965 km

Sedan

Available

Various Finance Plans To Cater To All Individuals Needs. Extended Warranty Available, Please Contact Our Knowledgeable Salesman For A Viewing Or Test Drive Today. All Trade In Welcome.

Creative Auto

★ Posted: 30-Oct-2019

Tags: 2009 Toyota Premio, 2009 toyota premio, Toyota Premio, toyota premio, Toyota, Premio, premio,
Used Toyota



☐ Toyota Premio 1.5A F (New
10-yr COE)

\$48,800

\$4,880 /yr

02-Oct-2009

1,496 cc

99,862 km

Sedan

Available

Max Loan Amount Available As Advertised! Meticulously Well Maintained Unit In Beautiful Pearl White! Low Mileage Done With No Repairs Needed! Guaranteed Accident Free! Buy With Confidence & Assurance! Our Company Provide Various Loan Scheme With Low Driveaway...

Creative Auto

★ Posted: 02-Nov-2019

Tags: 2009 Toyota Premio, 2009 toyota premio, Toyota Premio, toyota premio, Toyota, Premio, premio,
Used Toyota



☐ Toyota Premio 1.5A F (New 5-
yr COE)

\$34,800

\$6,950 /yr

16-Nov-2009

1,496 cc

101,728 km

Sedan

Available

Optional 1 Year Warranty! No Price Gimmicks! No Such Things As \$3k Booking Fees! Fuel Economical. Hot Favourite 1.5L Sedan For Small Families. Call Our Friendly Sales Consultant For Viewing And Test Drive.

PREMIUM AD

★ Posted: 23-Nov-2019

Tags: 2009 Toyota Premio, 2009 toyota premio, Toyota Premio, toyota premio, Toyota, Premio, premio,
Used Toyota



Toyota launches fully redesigned Premio and Allion

TOYOTA MOTOR CORPORATION (TMC) announced that the nationwide launch in Japan of the completely redesigned Premio through "Toyopet" dealers, and completely redesigned Allion through "Toyota" dealers

Read this article



☐ Toyota Premio 1.5A F (New 5-
yr COE)

\$34,888

\$6,970 /yr

21-Jan-2010

1,496 cc

101,000 km

Sedan

Available

Very Rare White Premio! Low Mileage! Free 1 Servicing Upon Purchase! Up To 2 Years Warranty Engine And Gearbox! 100% Loan Approval! Bank And In House Loan Available! No Gimmicks! Trade-In Welcome! Best Value For Money! Well Maintained, Excellent Condit...

JDM Cars

★ Posted: 22-Nov-2019

Tags: 2010 Toyota Premio, 2010 toyota premio, Toyota Premio, toyota premio, Toyota, Premio, premio,
Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

SHORTLISTED HISTORY

Compare

View Expired ads

20 results/page

PRE-REPAIR INSPECTION REQUEST – SMN787K vs SLX6562L (OI) on D.O.A.: 21/11/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni
Sent: 11/25/2019 11:38:59 AM
Attachments: 23112019091324.pdf 22112019155206.pdf

Hi,

Please refer to the enclosed request from **Dynamic Autowork**.
Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rui (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yinnul.Hor@aig.com | www.aig.sg

11:49am @ 25/11/2019
p: Michelle
v: Nat In

From: dynamicautowork@gmail.com [mailto:dynamicautowork@gmail.com]
Sent: Monday, November 25, 2019 11:19 AM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLX6562L AND SMN787K ON 21/11/2019

Dear All,

Thanks for reply.

Please arrange LKK AUTO CONSULTANTS PTE LTD to survey the above vehicle

Michelle

From: Hor, Yinnul
Sent: Mon, 25 Nov 2019 02:01:05 +0000
To: dynamicautowork@gmail.com
Cc: Fong, Andy-SY, Fan, Winnie-LW, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLX6562L AND SMN787K ON 21/11/2019

Without Prejudice

Your Reference : SMN787K
Our Reference : SLX6562L

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services

EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

FNOL Adjuster I

Singapore FNOL | Claims Operations – Auto

Tel: 8001208556 | Ext: 1002208

Yinrul.Hor@aig.com | www.aig.sg

From: Dynamic Autowork [<mailto:dynamicautowork@gmail.com>]

Sent: Saturday, November 23, 2019 9:23 AM

To: Hor, Yinrul; Lim, Sheng Yang; Abu Kassim, Noor Mariesa

Subject: [EXTERNAL] Re: SMN787K (Pre-inspection) / Your vehicle : SLX6562L

This message is from an external sender; be cautious with links and attachments.

Dear All,

Attach GIA report for your record

On Fri, Nov 22, 2019 at 3:57 PM Dynamic Autowork <dynamicautowork@gmail.com> wrote:

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

Hope we can do Direct Settle and please provide the surveyor firm or surveyor name list to conduct the joint pre-repair survey as a single joint expert

**** PLEASE ADVISE LIABILITY****

**** GIA REPORT WILL EMAIL TO YOUR ONCE RECEIVE FROM MY CLIENT ****

--

Thank You.

Yours Sincerely,

Michelle
HP : 9856 4815

8 Kaki Bukit Avenue 4
#08-09Premier @ Kaki Bukit
Singapore (415875)
Tel : 6341 6789
Fax : 6341 6778

--

Thank You.

Yours Sincerely,

Michelle

HP : 9856 4815

8 Kaki Bukit Avenue 4
#08-09Premier @ Kaki Bukit
Singapore (415875)
Tel : 6341 6789
Fax : 6341 6778

View Received Message

This mail is associated with :

***SMN787K (7022655634SG)**
[SLX6562L]

TP
CAI ZHONGLING
Nov 21 2019 6:00PM
[HO TUCK CHUEN]
Dynamic Autowork Pte. Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on **03/03/2020 11:36 AM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$16629.45) - SMN787K - Claim Handler: Syed-Yusoff, Saliha

Approved:16629.45:pls proceed with settlement @ \$16,629.45 [COR-\$15,622 LOR-\$1000 LTA-\$7.45] **subject to final repair bill & ATA

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Nov 2019 Edit Reg		25 Nov 2019 00:00 Edit Adj Rpt	S\$14,600.00 Edit Estimates	S\$14,600.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	HO TUCK CHUEN, ID: S1610557J		
Main Claimant:	CAI ZHONGLING, ID: S8835729I		
Vehicle Reg. No.:	SMN787K	Date of Loss:	21/11/2019 18:00 - :59 [122 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7022655634SG	Policy/Cover Note No.:	1900246734 (Comprehensive) Coverage: 14/11/2019 - 13/11/2021
Vehicle Reg. No. (Insured):	SLX6562L	Policy No. (Claimant):	5111759799
		Excess:	
Repairer:	Dynamic Autowork Pte. Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha, Syed-Yusoff@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 04/12/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (03/03/2020): Alert - Adj Mandate Approved (S\$16629.45) - SMN787K - Claim Handler: Syed-Yusoff...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMN787K (7022655634SG)**
[SLX6562L]

TP

CAI ZHONGLING

Nov 21 2019 6:00PM

[HO TUCK CHUEN]

Dynamic Autowork Pte. Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser ▼					
Video															1 per page ▼			☒					
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail			Print					
1	28/11/19 15:17	OI VIDEO 1													Load MP4								
2	28/11/19 15:17	OI VIDEO 2													Load MP4								
Letters/Correspondences																		1 per page ▼			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print					
1	(Draft)	Third Party Express Settlement – Payment Breakdown													Edit								
Photos/Images															3 per page ▼			☒					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print					
1	29/01/20 09:52	General View													Load JPG			☒					
2	29/01/20 09:52	General View													Load JPG			☒					
3	29/01/20 09:52	General View													Load JPG			☒					
4	29/01/20 09:52	General View													Load JPG			☒					
5	29/01/20 09:52	General View													Load JPG			☒					
6	29/01/20 09:52	General View													Load JPG			☒					
7	29/01/20 09:52	General View													Load JPG			☒					
8	29/01/20 09:52	General View													Load JPG			☒					
9	29/01/20 09:52	General View													Load JPG			☒					
10	29/01/20 09:52	General View													Load JPG			☒					
11	29/01/20 09:52	General View													Load JPG			☒					
12	29/01/20 09:52	General View													Load JPG			☒					
13	29/01/20 09:52	General View													Load JPG			☒					
14	29/01/20 09:52	General View													Load JPG			☒					
15	29/01/20 09:52	General View													Load JPG			☒					
16	29/01/20 09:52	General View													Load JPG			☒					
17	29/01/20 09:52	General View													Load JPG			☒					
18	29/01/20 09:52	General View													Load JPG			☒					
19	29/01/20 09:52	General View													Load JPG			☒					
20	29/01/20 09:52	General View													Load JPG			☒					
21	29/01/20 09:52	General View													Load JPG			☒					
22	29/01/20 09:52	General View													Load JPG			☒					
23	29/01/20 09:52	General View													Load JPG			☒					
24	29/01/20 09:53	General View													Load JPG			☒					
25	29/01/20 09:53	General View													Load JPG			☒					
26	29/01/20 09:53	General View													Load JPG			☒					
27	29/01/20 09:53	General View													Load JPG			☒					
28	29/01/20 09:53	General View													Load JPG			☒					

Video			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
29	29/01/20 09:53	General View	 Load JPG	✓
30	29/01/20 09:53	General View	 Load JPG	✓
31	29/01/20 09:53	General View	 Load JPG	✓
32	29/01/20 09:53	General View	 Load JPG	✓
33	29/01/20 09:53	General View	 Load JPG	✓
34	29/01/20 09:53	General View	 Load JPG	✓
35	29/01/20 09:53	General View	 Load JPG	✓
36	29/01/20 09:53	General View	 Load JPG	✓
37	29/01/20 09:53	General View	 Load JPG	✓
38	29/01/20 09:53	General View	 Load JPG	✓
39	29/01/20 09:53	General View	 Load JPG	✓
40	29/01/20 09:53	General View	 Load JPG	✓
41	29/01/20 09:53	General View	 Load JPG	✓
42	29/01/20 09:53	General View	 Load JPG	✓
43	29/01/20 09:53	General View	 Load JPG	✓
44	29/01/20 09:53	General View	 Load JPG	✓
45	29/01/20 09:53	General View	 Load JPG	✓
46	29/01/20 09:53	General View	 Load JPG	✓
47	29/01/20 09:53	General View	 Load JPG	✓
48	29/01/20 09:53	General View	 Load JPG	✓
49	29/01/20 09:53	General View	 Load JPG	✓
50	29/01/20 09:53	General View	 Load JPG	✓
51	29/01/20 09:53	General View	 Load JPG	✓
52	29/01/20 09:53	General View	 Load JPG	✓
53	29/01/20 09:53	General View	 Load JPG	✓
54	29/01/20 09:53	General View	 Load JPG	✓
55	29/01/20 09:53	General View	 Load JPG	✓
56	29/01/20 09:53	General View	 Load JPG	✓
57	29/01/20 09:53	General View	 Load JPG	✓
58	29/01/20 09:53	General View	 Load JPG	✓
59	29/01/20 09:53	General View	 Load JPG	✓
60	29/01/20 09:53	General View	 Load JPG	✓
61	29/01/20 09:53	General View	 Load JPG	✓
62	29/01/20 09:53	General View	 Load JPG	✓
63	29/01/20 09:53	General View	 Load JPG	✓
64	29/01/20 09:53	General View	 Load JPG	✓
65	29/01/20 09:53	General View	 Load JPG	✓
66	29/01/20 09:53	General View	 Load JPG	✓
67	29/01/20 09:53	General View	 Load JPG	✓
68	29/01/20 09:53	General View	 Load JPG	✓
69	29/01/20 09:53	General View	 Load JPG	✓
70	29/01/20 09:53	General View	 Load JPG	✓
71	29/01/20 09:53	General View	 Load JPG	✓
72	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
73	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
74	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
75	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
76	29/01/20 09:53	Reinspection Photo	Load JPG	✓

Video			1 per page ▾	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
77	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
78	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
79	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
80	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
81	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
82	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
83	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
84	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
85	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
86	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
87	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
88	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
89	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
90	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
91	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
92	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
93	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
94	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
95	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
96	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
97	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
98	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
99	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
100	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
101	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
102	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
103	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
104	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
105	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
106	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
107	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
108	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
109	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
110	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
111	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
112	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
113	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
114	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
115	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
116	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
117	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
118	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
119	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
120	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
121	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
122	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
123	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
124	29/01/20 09:53	Reinspection Photo	Load JPG	☒

Video			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte, Ltd. (SG)	Thumbnail	Print
125	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
126	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
127	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
128	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
129	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
130	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
131	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
132	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
133	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
134	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
135	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
136	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
137	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
138	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
139	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
140	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
141	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
142	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
143	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
144	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
145	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
146	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
147	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
148	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
149	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
150	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
151	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
152	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
153	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
154	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
155	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
156	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
157	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
158	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
159	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
160	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
161	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
162	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
163	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
164	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
165	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
166	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
167	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
168	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
169	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
170	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
171	29/01/20 09:53	Reinspection Photo	 Load JPG	✓
172	29/01/20 09:53	Reinspection Photo	 Load JPG	✓

Video			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
173	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
174	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
175	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
176	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
177	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
178	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
179	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
180	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
181	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
182	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
183	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
184	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
185	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
186	29/01/20 09:53	Reinspection Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/11/19 18:32	ACKNOWLEDGEMENT EMAIL TO AIG DD 25.11.19	 Load PDF	
2	25/11/19 18:32	EMAIL FROM AIG DD 25.11.19	 Load PDF	
3	25/11/19 18:32	TP GIA REPORT	 Load PDF	
4	25/11/19 18:32	NOTIFICATION FROM WORKSHOP	 Load PDF	
5	05/02/20 14:55	TP ESTIMATE - MARKED (FINAL)	 Load PDF	
6	17/02/20 13:30	LETTER TO OI	 Load PDF	
7	17/02/20 17:38	LOD	 Load PDF	
8	17/02/20 17:38	RENTAL RECEIPT	 Load PDF	
9	17/02/20 17:38	LTA SEARCH FEE	 Load PDF	
10	19/03/20 17:36	Authorisation to Act	 Load PDF	
11	19/03/20 17:36	Release Voucher	 Load PDF	
12	19/03/20 17:36	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/11/19 16:55	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLX6562L (Insd veh)	Model:	TOYOTA PREMIO 1.5 F (A)
	SMN787K (TP veh)		
Date of Accident:	21/11/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	33,727.90
Final Repair Cost	:	\$	16,600.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	10 days
LTA / GIA Search Fee	:	\$	_____
Others:	:	\$	_____
	:	\$	_____
Final Settlement Sum (GLOBAL SUM)	:	\$	16,600.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 0 (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Dynamic Autowork Pte. Ltd	: \$	16,600.00
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

19 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020841/ADA3S2
Date: 19/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900246734
Claimant Vehicle No: SMN787K Insured Vehicle No: SLX6562L
Date of Loss: 21/11/2019 Nature of Claim: TP Claim No: 7022655634SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMN787K
Make & Model: TOYOTA PREMIO, 1.5 F (A) Engine No: 1NZD284885
Reg. Date: 27/08/2009 (Man. Year: 2008) Chassis No: NZT2603037476
Colour: Silver Odometer: 116837 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,231.40	12,883.32	9,348.08	42.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,290.00	5,410.00	3,880.00	41.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,521.40	18,293.32	13,228.08	41.97
Approved Total (Overridden) (S\$)		14,600.00		
(S\$)	31,521.40	14,600.00	16,921.40	53.68
+ GST 7.00/7.00% (S\$)	2,206.50	1,022.00	1,184.50	53.68
Nett Amount (S\$)	33,727.90	15,622.00	18,105.90	53.68
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		16,629.45		
Global Sum Settlement (S\$)		16,600.00		

INSPECTION

Date of Assignment: 25/11/2019
Date Inspected: 26/11/2019 Inspected At: Dynamic Autowork Pte. Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875
Estimated Period of Repair: 16.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	791.10 FL	*791.10 FL
2	1		*FRONT BUMPER LOWER GRILLE	Cracked	113.40 FL	*113.40 FL
3	1		*FRONT BUMPER LOWER COVER GARNISH	Not Necessary	125.10 FL	*- FL
4	2		*FRONT BUMPER SIDE RETAINER	Necessary	120.60 FL	*120.60 FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	211.60 FL	*211.60 FL
6	1		*FRONT BUMPER SPONGE	Cracked	183.50 FL	*183.50 FL
7	1		*FRONT RADIATOR GRILLE WITH LOGO	Cut	317.70 FL	*317.70 FL
8	2		*HEADLAMP	Cracked	1,582.20 FL	*1,582.20 FL
9	1		*FRONT FENDER LH	Repair	531.10 FL	*- FL
10	2		*FRONT FENDER INNER COWLING	Not Necessary	302.20 FL	*- FL
11	1		*BONNET	Buckled	624.40 FL	*624.40 FL
12	1		*BONNET MOULDING	Cut	167.10 FL	*167.10 FL
13	2		*BONNET HINGE	Not Necessary	136.20 FL	*- FL
14	2		*BONNET STOPPER	Not Necessary	36.00 FL	*- FL
15	1		*BONNET LOCK	Not Necessary	79.40 FL	*- FL
16	1		*BONNET LOCK BRACE PANEL	Bent	98.10 FL	*98.10 FL
17	1		*BONNET INSULATOR	Not Necessary	312.40 FL	*- FL
18	1		*FRONT SUPPORT PANEL	Buckled	744.60 FL	*744.60 FL
19	1		*AIR CONDENSER	Dented	731.40 FL	*731.40 FL
20	1		*RADIATOR	Bent	794.10 FL	*794.10 FL
21	1		*RADIATOR CENTER TOP BRACKET	Cracked	139.40 FL	*139.40 FL
22	2		*RADIATOR TOP BRACKET	Not Necessary	36.00 FL	*- FL
23	4		*RADIATOR MOUNTING	Not Necessary	113.60 FL	*- FL
24	1		*TEMPERATURE SENSOR	Not Necessary	198.00 FL	*- FL
25	1		*BOOT LID	Distorted	801.30 FL	*801.30 FL
26	1		*BOOT LID MOULDING	Cut	238.10 FL	*238.10 FL
27	2		*BOOT LID NUMBER PLATE LAMP	Not Necessary	332.60 FL	*- FL
28	1		*BOOT LID LOGO	Necessary	65.00 FL	*65.00 FL
29	1		*BOOT LID EMBLEM PREMIO	Necessary	63.30 FL	*63.30 FL
30	1		*BOOT LID EMBLEM F	Necessary	55.90 FL	*55.90 FL
31	1		*BOOT LID DETECTOR	Cracked	194.10 FL	*194.10 FL
32	2		*BOOT LID LAMP	Cracked	620.40 FL	*620.40 FL
33	4		*BOOT LID STOPPER	Not Necessary	60.00 FL	*- FL
34	1		*BOOT LID TOP LOCK	Damaged	313.40 FL	*313.40 FL
35	1		*BOOT LID LOWER LOCK	Not Necessary	24.60 FL	*- FL
36	1		*BOOT LID SWITCH BUTTON	Not Necessary	131.60 FL	*- FL
37	2		*BOOTLID HINGE	Bent	271.00 FL	*271.00 FL
38	2		*BOOTLID HINGE GARNISH	Deformed	220.60 FL	*220.60 FL
39	1		*BOOTLID INSULATOR	Not Necessary	221.10 FL	*- FL
40	1		*BOOT LID WEATHERSTRIP	Cut	198.30 FL	*198.30 FL
41	1		*REAR FENDER	N/s Buckled	2,470.20 FL	*1,235.10 FL
42	2		*REAR FENDER INNER COWLING	Not Necessary	197.40 FL	*- FL
43	2		*REAR FENDER INNER TRIM	Torn	842.20 FL	*659.00 FL
44	1		*REAR FENDER AIR VENT	Not Necessary	58.30 FL	*- FL
45	1		*REAR WINDSCREEN MOULDING	Necessary	128.10 FL	*128.10 FL
46	2		*REAR DOOR INNER LOCK	Not Necessary	657.40 FL	*- FL
47	2		*REAR DOOR WEATHERSTRIP	Not Necessary	227.20 FL	*- FL
48	2		*REAR DOOR INNER TRIM	Not Necessary	1,210.20 FL	*- FL
49	1		*REAR BUMPER	Distorted	769.80 FL	*769.80 FL
50	2		*REAR BUMPER SIDE RETAINER	Necessary	179.20 FL	*179.20 FL
51	2		*REAR BUMPER BRACKET	Dented	110.20 FL	*110.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	2		*TAIL LAMP	Cracked	642.80 FL	*642.80 FL
53	2		*TAIL LAMP LOWER BRACKET	Not Necessary	78.60 FL	*- FL
54	2		*TAIL LAMP PANEL	Buckled	452.20 FL	*452.20 FL
55	1		*REAR END PANEL	Distorted	411.10 FL	*411.10 FL
56	1		*REAR END PANEL TOP GARNISH	Deformed	143.10 FL	*143.10 FL
57	1		*REAR FLOOR PANEL	Reapiir	853.40 FL	*- FL
58	1		*REAR FLOOR PANEL TOP BAORD	Deformed	138.60 FL	*138.60 FL
59	2		*REAR FLOOR PANEL SIDE TOP BOARD	Deformed	226.20 FL	*226.20 FL
60	1		*REAR CHASSIS MEMBER RH	Repair	221.10 FL	*- FL
61	1		*REAR TOOLS TRAY	Cut	192.30 FL	*192.30 FL
62	1		*SPARE TYRE BOLT	Bent	46.70 FL	*46.70 FL
63	1		*CENTER EXHAUST	Not Necessary	1,483.50 FL	*- FL
64	1		*CENTER EXHAUST INSULATOR	Not Necessary	189.10 FL	*- FL
65	1		*SET CENTER EXHAUST GASKET	Not Necessary	60.10 FL	*- FL
66	1		*REAR EXHAUST BOX	Bent	796.10 FL	*796.10 FL
67	1		*REAR EXHAUST INSULATOR	Not Necessary	121.40 FL	*- FL
68	3		*REAR EXHAUST BOX MOUNTING	Not Necessary	88.20 FL	*- FL
69	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*50.00 FS
70	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
71	1		*BONNET SEALANT	Not Necessary	150.00 FS	*- FS
72	1		*SET BONNET MOULDING CLIP	Necessary	50.00 FS	*20.00 FS
73	1		*SET BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
74	1		*FRONT FENDER SEALANT LH	Not Necessary	120.00 FS	*- FS
75	1		*SET FRONT FENDER INNER COWLING	Not Necessary	50.00 FS	*- FS
76	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	120.00 FS	*- FS
77	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
78	1		*REAR NUMBER PLATE	Deformed	50.00 FS	*50.00 FS
79	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
80	1		*BOOT LID SEALANT	Not Necessary	120.00 FS	*- FS
81	1		*SET BOOT LID MOULDING CLIP	Necessary	50.00 FS	*20.00 FS
82	1		*SET BOOTLID HINGE GARNISH CLIP	Not Necessary	50.00 FS	*- FS
83	1		*SET BOOTLID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
84	1		*SET TAIL LAMP CLIP	Necessary	80.00 FS	*20.00 FS
85	1		*TAIL LAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
86	2		*REAR FENDER SEALANT	Not Necessary	160.00 FS	*- FS
87	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	30.00 FS	*- FS
88	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	50.00 FS	*50.00 FS
89	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
90	1		*REAR WINDSCREEN INNER SHIELD	Necessary	60.00 FS	*40.00 FS
91	1		*SET REAR DOOR INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
92	1		*REAR END PANEL INSULATOR SEAL	Necessary	150.00 FS	*60.00 FS
93	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	80.00 FS	*10.00 FS
94	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
95	4		*REAR REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
96	1		*REVERSE CAMERA	Damaged	550.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,555.20	16,831.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	6,323.80	3,947.78
Total Parts (\$\$)	22,231.40	12,883.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS.	New	1,200.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA.	New	1,200.00	800.00
3	REFOCUS HEADLAMP BEAM.	New	80.00	0.00
4	REMOVE AND REFIX AIRCON CONDENSER AND REFILL AIRCON GAS.	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.	New	80.00	60.00
6	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN.	New	2,800.00	1,600.00
7	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS.	New	2,000.00	1,400.00
8	TUFF COAT.	New	250.00	120.00
9	WIRING CHECK.	New	180.00	30.00
10	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.	New	250.00	100.00
11	TRANSFER BOOTLID MECHANISM.	New	80.00	60.00
12	CONDUCT WATER LEAKAGE TEST.	New	80.00	0.00
13	REAR CHASSIS ALIGNMENT	New	250.00	0.00
14	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	New	80.00	50.00
15	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.	New	80.00	50.00
16	REMOVE AND REFIX REAR EXHAUST PIPE.	New	180.00	80.00
17	REMOVE AND REFIX REAR WINDSCREEN.	New	120.00	120.00
18	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT.	New	80.00	80.00
19	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	180.00	0.00
Gross Labour Cost (\$\$)			9,290.00	5,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >