

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262

Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimate :

Date : 23.11.2019
Vehicle Num : SKU 7627E
Make/Model : MAZDA 3
Chassis/Engine no :
Accident Date : 21.11.2019
Claim No :
Reference :
Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Rear boot lid / BT	\$ 1,352.20 1004
1 pc	Rear boot lock / BT	\$ 465.20 185
1 pc	Rear boot lock catch X	\$ 70.20
2 pc	Rear boot hinges @ 168.00 X GAN	\$ 336.00
1 pc	Rear boot insulator X	\$ 365.50
1 pc	Rear boot rubber X LWR	\$ 315.20 107.70
2 pc	Rear boot reflector lamp @ 543.00 X BR	\$ 1,086.00 932
1 pc	Rear boot emblem (Mazda 3)	\$ 65.00 54
1 pc	Rear boot emblem logo / MBZ	\$ 72.00
1 pc	Rear boot emblem (Skyactive)	\$ 65.00
2 pc	Taillamp panel @388 X repair	\$ 776.00
2 pc	Rear tail lamp @ 985.00 X CRA	\$ 1,970.00 1830
1 pc	Rear end panel X PH	\$ 825.00 425
1 pc	Rear end panel top garnish X RE	\$ 315.50 99
1 pc	Rear spare tyre panel X repair	\$ 1,325.00
1 pc	Rear spare tyre panel top cover board X CRA	\$ 465.20 249
2 pc	Rear bumper side retainer @ 35.00 X RE	\$ 70.00
1 pc	Rear bumper reinforcement X BT	\$ 652.20 537.30
2 pc	Rear bumper reflector @ 50.00 X PH	\$ 100.00
2 pc	Rear number plate lamp @ 85.00 X NN	\$ 170.00
1 pc	Rear exhaust silencer X repair	\$ 1,800.00
2 pc	Rear exhaust chrome pipe 125.00 X NN	\$ 250.00
2 pc	Rear fender @1250.00 X repair	\$ 2,500.00
2 pc	Rear fender inner garnish @ 598.40 X NN	\$ 1,196.80
2 pc	Rear bumper tow cover@75.20 IPC / M's	\$ 150.40 16.20
4 pc	Reversing sensor @ 274.00 / DM (SN)	\$ 1,096.00 200
4 pc	Reversing sensor holder @ 22.00 X NN	\$ 88.00
1 pc	Rear bumper / RE	\$ 1,210.00 1042
List Item Total :		\$ 19,152.40
Discount 20 % :		\$ 3,830.48
		\$ 15,321.92

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate :

Date : 23.11.2019
 Vehicle Num : SKU 7627E
 Make/Model : MAZDA 3
 Chassis/Engine no :
 Accident Date : 21.11.2019
 Claim No :
 Reference :
 Policy No :

Qty	Particular	Amount S\$
<u>Special Nett Item :</u>		
1 set	Rear boot board clip <i>X NN</i>	\$ 50.00
1 set	Rear end panel garnish clip <i>✓</i>	\$ 40.00 <i>20</i>
1 pc	Rear number plate <i>✓ SUR</i>	\$ 45.00 <i>40</i>
	Special Nett Total	\$ 135.00

Labour Charge :

To check wiring	\$ 150.00 <i>30</i>
Apply anti rust chemical	\$ 200.00 <i>80</i>
Remove and refix petrol tank	\$ 120.00 <i>X NN</i>
Remove and refix rear cushion seat, trimming etc	\$ 150.00 <i>60</i>
Remove and refix reversing sensor	\$ 150.00 <i>60</i>
Remove and refix exhaust pipe	\$ 150.00 <i>X NN</i>
Labour charge for knock dents, cut & welding parts on front & rear damage portion	\$ 1,800.00 <i>750</i>
To spray painting and etc	\$ 1,600.00 <i>1000</i>
Labour Charge Total :	\$ 4,320.00

E & O . E Total Amount : \$ 19,776.92

Guo Qiang - 82880282

Insurance repair.

After repair photos.

KIM CHWEE AUTO PTE LTD

21/11/19.

6 Days.