

23/03/2019

ASS. REC. BY:

REF: CS/MSG 19020853/ Hvf3

Special Instruction: ✓

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Christina Wong

of MSG

Date/Time: 25.11.19 17.18p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBIV 4809K

Insured: GBA 377J

CS.lim@baan51w
handles
rm59

at Workshop m/s Baan 51w Singapore

Tel: 91177624

of 370 Ua Rd 3

9112 1132 Mr Teo 82011626

Policy No: 28865523

Claim No: 612158

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A 28.10.2019

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement

Date/Time: 26.11.19 9.33a.m

Person Contacted: Bwn

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	FBIV 4809K - CS/SPF 19020853/ Hvf3 D.O.A - 02/10/2019
	GBA 377J - CS/AWA 19017406/ ASD15112 D.O.A - 28.10/2019
28/11/19	Send preli revised via merimen
23/20	@451pm Mr Teo said vehicle pending for spare parts
27/4/20	Submit preli report

7/1/21 Final fig \$3374.30 confirmed by email (Red 1182.03,25%)

ASS. REC. BY: *H-ANN*

REF: MS1G

ASSIGNMENT

From: _____ Date: *26-11-2019*

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: *FBN 4809K*at Workshop m/s *Boon Siew*of *370 ubi Rd 3*

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *FBN 4809K*Yr Regn: *7/10/2018*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Honda**ADV 750*

C.C.

*745*Colour: *Red*

A/C:

Insured / Std / NI / NA

Sp. Reading: *18957*

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: *JH2AC 95AJJK 109220*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

F:

120/70/R17

R:

160/60/R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

5 BS

mm

R/Bal:

5 BS

mm

L/Bal:

mm

L/Bal:

mm

D.O.A:

29.10.2019

D.O.I:

26/11/19

Survey held at

*Boon Siew*Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☒ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

** FBN 4809K**Le. Agent Av. Boon Siew**MV - 23000**PV - 3890**NV - 17100*** Second Damage Assessment**insurance premium 82011626*

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2) *27/11-tylist*

7/11/21-Typist

Report Format: Merimen

Lump Sum / P.P. \$3374.30

Days Of Repair: *2 1/2* 3

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Meal and (\$

Survey Fee:

Transportation:

S + RS: \$

Photos:

Notes:

TOTAL

Second Party Accident
 Refer to the Damage
 D.O.A: 28/10/17

QUOTATION

M/S: MSIG INSURANCE (SINGAPORE)

4 SHENTON WAY

#23-01

SGX CENTRE 2 SINGAPORE 068807

NO:

WQT0902846

DATE:

20 Nov 2019

A/C CODE:

902

TERMS:

60

YOUR REF:

FBN4809K

SALESMAN:

PAGE:1

Item No	Description	Quantity	Unit Price	%	Amount
			<u>SS</u>		<u>SS</u>
1	ACC99 D.O.A./POLICY NO.:28/10/19 TOW/DRIVE IN: SURVEYOR/DATE IN: AUTHORISED BY/EXCESS: 3RD PARTY VEHICLE NO.: 3RD PARTY REF.:	1 HR			0.00
2	070799 *TO REMOVE ALL DAMAGED PARTS, NECESSARY ATTACHMENT, REPLACE AND REALIGN AFFECTED PORTION TO ALIGNMENT.	4 HR 2.5	280.00		1,120.00 700
3	C06042 *USING HONDA MOTORCYCLE COMMUNICATION SYSTEM (MSC) TO ERASE/RESET MEMORY. NETT.	1 PCS	120.00		120.00 60
4	MISC99 FRONT NUMBER PLATE ✓ CRM	1 HR	25.00		25.00
5	88220-MGS-D30 MIRROR COMP L,BAC ✓ CRM MGS	1 PC	102.70		102.70
6	53196-MKH-D00 HOLDER COMP, L KNUCKLE ✓ CRM XADV	1 PC	18.70		18.70
7	77250-MKH-D00ZD COWL, L REAR*R381C* ✓ SCR XADV	1 PC	196.80		196.80
8	64372-MKH-D00ZC COWL ASSY *R381C* ✓ SCR XADV	1 PC	710.80		710.80
9	50610-MKH-D00 STAIR FLOOR ✓ CRM MKH	1 PC	172.60		172.60
10	64420-MKH-D00 SKIRT COMP RIGHT FLOOR ✓ CRM XADV 750	1 PC	98.90		98.90
11	50711-MKH-D00ZC ARM, R PILLION*NH460M* ✓ CRM XADV	1 PC	93.30		93.30
12	64500-MKH-D00 PANEL ASSY,R STEP MKH	1 PC	130.50		130.50

QUOTATION

M/S : MSIG INSURANCE (SINGAPORE)

NO:

WQT0902846

DATE:

20 Nov 2019

PAGE:2

Item No	Description	Quantity	Unit Price	%	Amount
			SS		SS
13	64505-MKH-D00 PLATE, RIGHT ADV ? XADV750	1 PC	88.80		88.80
14	33650-MKH-D01 WINKER ASSY,L RR X (suv) MKH	1 PC	105.60		105.60
15	64371-MKH-D00 COVER, L WINKER X (suv) XADV	1 PC	6.30		6.30
16	64100-MKH-D00ZA SET ILLUSTRATE*TYPE1* ADV750 (fnt) ✓ (scr)	1 PC	528.20		528.20
17	64360-MKH-D00ZA COWL,L FR*NHA86M* X (suv) MKH	1 PC	430.83		430.83

Total SS 3,949.03

Add GST @ 7% 276.43

Grand Total SS 4,225.46

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND TWO HUNDRED TWENTY FIVE AND CENTS FORTY SIX ONLY

MSIG INSURANCE (SINGAPORE)

For Boon Siew Singapore Pte Ltd

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE

*P/p repair without preparation
resurvey before paint
Hock ANW
8531813
Hock ANW @ Heli Auto - car
26/11/19
3.35pm
2.5 day*

28/11/19

Let the Insurer/Insurance notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to quotation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance company

Acknowledged by Repairer

Signature:

Date: